

# AUTOTEAM ENGINEERING PTE LTD

7 Gambas Crescent #04-07 Singapore 757087

Tel: (65) 6253 0233 Email: sales@autoteam.com.sg

Co. Reg. No. 201205841K

bizSAFE<sub>3</sub>



Quote To

**SBS Transit Ltd**

Seletar Workshop

3 Yio Chu Kang Crescent

Singapore 786010

Attn: Yong Guang

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



## QUOTATION

Quotation No. Q20121643

Date 11 Dec 2020

Terms Net 30

S/No	Description	Qty	Unit Price	Amount
<b><u>Repair Accident Bus - SBS 6875D</u></b>				
1.	Supply 3 workers for 2 days work	1	S\$700.00	S\$700.00 ✓
-	Replace Right Side Headlamp Cover			
-	Repair Right Side Panel No. 1			
-	Repair Right Side Battery Door			
-	Repair 1pc X Front Bumper Bracket			
-	Spray Painting Right Side Headlamp Cover			



Remark(s) All Material To Be Supplied by SBST

Total S\$700.00

This is computer generated. No signature is required.

Repair day 2 days.

Sun Pin (LKK)

DOI: 16/12/2020.

Receive: 22/03/2021.  
Estimate