

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

HOW YEW CHYE
BLK 435C FERNVALE ROAD #13-232
SINGAPORE 793435

Contact : 96815101

TP Chin

Xiao Chen

ESTIMATE

Repair Code : CLM15130

Date in : 15/12/2020

Vehicle Num. : SLM5166L

Model : HONDA VEZEL HYBRID 1.5X AUTO

Chassis/Eng# : RU31220446/LEB5920461

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>Del'd</i>	1	762.70	✓ 762.70
REAR BUMPER LOWER COVER <i>Del'd.</i>	1	250.00	✓ 250.00
REAR BUMPER REFLECTOR L/R <i>could</i>	2	141.10	✓ 282.20
REAR BUMPER SIDE L/R <i>New</i>	2	195.00	+ 390.00
REAR BUMPER SIDE RETAINER L/R <i>New</i>	2	23.00	✓ 46.00
REAR END PANEL <i>Repair</i>	1	415.60	+ 415.60
REAR END PANEL INNER TOP GARNISH <i>Del'd</i>	1	98.00	✓ 98.00
REAR EXHAUST CHROME TAIL PIPE <i>New</i>	1	135.00	+ 135.00
REAR EXHAUST PIPE <i>New</i>	1	517.70	+ 517.70
REAR EXHAUST RUBBER MOUNTING <i>New</i>	2	16.50	+ 33.00
REAR EXHAUST SILENCER BOX <i>New</i>	1	517.70	+ 517.70
REAR EXHAUST SILENCER BOX GASKET <i>New</i>	1	48.30	+ 48.30
REAR FENDER ARCH GARNISH L/R <i>New</i>	2	195.00	+ 390.00
REAR FLOOR PANEL COMPARTMENT TRAY GARNISH <i>could</i>	1	485.30	326 485.30
REAR FLOOR PANEL INNER TOP BOARD COVER <i>Del'd</i>	1	430.30	306 430.30
REAR TAILGATE <i>Dented.</i>	1	953.30	✓ 953.30
REAR TAILGATE 'HYBRID' EMBLEM <i>New</i>	1	75.80	✓ 75.80
REAR TAILGATE 'VEZEL' EMBLEM	1	56.20	✓ 56.20

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

HOW YEW CHYE
BLK 435C FERNVALE ROAD #13-232
SINGAPORE 793435

Contact : 96815101

ESTIMATE

Repair Code : CLM15130

Date in : 15/12/2020

Vehicle Num. : SLM5166L

Model : HONDA VEZEL HYBRID 1.5X AUTO

Chassis/Eng# : RU31220446/LEB5920461

REAR TAILGATE INNER PULL GARNISH <i>new</i>	1	27.50	+	27.50
REAR TAILGATE INNER TRIM GARNISH <i>could</i>	1	153.40	✓	153.40
REAR TAILGATE MECHANISM LOCK <i>Damaged</i>	1	180.00	✓	180.00
REAR TAILGATE OUTER GARNISH <i>could</i>	1	220.00	✓	220.00
REAR TAILGATE OUTER GARNISH 'H' LOGO EMBLEM <i>new</i>	1	25.00	✓	25.00
REAR TAILGATE REFLECTOR BACK RUBBER GASKET L/R <i>m</i>	2	38.50	✓	77.00
REAR TAILGATE REFLECTOR L/R <i>could</i>	2	413.20	✓	826.40
REAR TAILGATE WEATHER STRIP <i>ut</i>	1	96.80	✓	96.80
REAR TAILGATE WINDSCREEN INNER SEAL <i>new</i>	2	50.00	80 ✓	100.00
REAR TAILGATE WINDSCREEN MOULDING <i>m</i>	2	50.00	80 ✓	100.00
REAR TAILLAMP L/R <i>LH ut, RH could</i>	2	474.60	✓	949.20
Subtotal before discount				8,642.40
Percentage discount 20%				1,728.48
Sub-total 1				6,913.92
REAR BUMPER CHROME PLATE <i>Best</i>	1	280.00	200 ✓	280.00
REAR BUMPER CLIPS - SET <i>new</i>	1	50.00	30 ✓	50.00
REAR BUMPER REVERSE SENSOR <i>Damaged</i>	1	250.00	200 ✓	250.00
REAR FENDER ARCH GARNISH CLIPS L/R - SET <i>new m</i>	2	30.00	✓	60.00

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

HOW YEW CHYE

BLK 435C FERNVALE ROAD #13-232

SINGAPORE 793435

Contact : 96815101

ESTIMATE

Repair Code : CLM15130

Date in : 15/12/2020

Vehicle Num. : SLM5166L

Model : HONDA VEZEL HYBRID 1.5X AUTO

Chassis/Eng# : RU3T220446/LEB5920461

REAR NUMBER PLATE HOLDER <i>new</i>	1	50.00	<i>x</i>	50.00
REAR TAILGATE INNER TRIM GARNISH CLIPS - SET <i>new</i>	1	50.00	<i>30</i>	50.00
REAR TAILGATE REVERSE CAMERA <i>Damaged</i>	1	800.00	<i>380</i>	800.00
REAR TAILGATE WINDSCREEN SEALANT <i>new</i>	1	60.00	<i>✓</i>	60.00
REAR TAILLAMP CLIPS L/R - SET <i>new</i>	2	20.00	<i>✓</i>	40.00
Subtotal before discount				1,640.00
Percentage discount 0%				0.00
Sub-total 2				1,640.00
Parts-total				8,553.92

LABOUR

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.

To remove, reinstall tailgate windscreen

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

To remove, reinstall tailgate mechanism and check for function

Labour Total	2,630.00
Parts & Labour Total	11,183.92

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

*** This is a computer-generated document which requires no signature.***

page 3

total: 7075.20

w/s: 5.6k ✓

Adrian Lij

h/s 18/12/20

05 Days.