



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2103850

36 ROBINSON ROAD  
#16-01 CITY HOUSE  
SINGAPORE 068877

INV Date 02/06/2021  
Reference CC4/FCI20014007/Uea3q2  
Code FCI2

### PROFESSIONAL SERVICE FEE

Vehicle No. FU 2345K  
Insured Veh. SHD 8803G  
Claim No. D20005135MFSH  
Policy No. D-20094921MFSH  
Accident Date 07/12/2020  
Inspection Date 16/12/2020

| Description                    | Total         |
|--------------------------------|---------------|
| Third Party Express Settlement | 500.00        |
| <b>Subtotal</b>                | <b>500.00</b> |
| <b>GST (7%)</b>                | <b>35.00</b>  |
| <b>Grand Total</b>             | <b>535.00</b> |

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                      |                                                                                     |                 |                             |  |
|----------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-----------------|-----------------------------|--|
| MS FIRST CAPITAL INSURANCE LTD<br>36 ROBINSON ROAD<br>#16-01 CITY HOUSESINGAPORE 068877                                                |                                                                                     |                 | Ref: CC4/FCI20014007/Uea3q2 |  |
|                                                                                                                                        |                                                                                     |                 | Date: 02/06/2021            |  |
|                                                                                                                                        |                                                                                     |                 | Code: FCI2                  |  |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                      |                                                                                     |                 |                             |  |
| Insured Veh.                                                                                                                           | SHD 8803G                                                                           | Veh. Inspected  | FU 2345K                    |  |
| Policy No.                                                                                                                             | D-20094921MFSH                                                                      | Coverage (\$)   | 0.00                        |  |
| Claim No.                                                                                                                              | D20005135MFSH                                                                       | Excess (\$)     | 0.00                        |  |
| Assign From                                                                                                                            | ERIC WOO                                                                            | Assign Date     | 16/12/2020                  |  |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                          |                                                                                     |                 |                             |  |
| Make & Model                                                                                                                           | YAMAHA CZD300A                                                                      | c.c             | 292                         |  |
| Engine No.                                                                                                                             | HIDDEN                                                                              | Year of Reg.    | 2020                        |  |
| Chassis No.                                                                                                                            | MH3SH0849LK012599                                                                   | Colour          | GREY                        |  |
| Odometer                                                                                                                               | 6075 KM                                                                             | Steering        | AFFECTED                    |  |
| Brakes                                                                                                                                 | IN ORDER                                                                            | Modification    | SPORTS RIM                  |  |
| General                                                                                                                                | FAIR                                                                                |                 |                             |  |
| <b>3. Conditions of Tyres</b>                                                                                                          |                                                                                     |                 |                             |  |
|                                                                                                                                        | Size                                                                                | Make            | Balance                     |  |
| R/H Front Tyre                                                                                                                         | 120/70 -15                                                                          | DUNLOP          | 8 mm                        |  |
| L/H Front Tyre                                                                                                                         |                                                                                     |                 | mm                          |  |
| R/H Rear Tyre                                                                                                                          | 140-70-14                                                                           | DUNLOP          | 8 mm                        |  |
| L/H Rear Tyre                                                                                                                          |                                                                                     |                 | mm                          |  |
| <b>4. Description of Damages</b>                                                                                                       |                                                                                     |                 |                             |  |
| THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND N/S BODY.<br><br>DAMAGES SEE DETAILS.                                           |                                                                                     |                 |                             |  |
| <b>5. General Information</b>                                                                                                          |                                                                                     |                 |                             |  |
| Accident Date                                                                                                                          | 07/12/2020                                                                          | Inspection Date | 16/12/2020                  |  |
| Survey held at                                                                                                                         | EROFIA MOTOR TRADING PTE LTD<br>1 KAKI BUKIT AVENUE 6<br>#02-62<br>SINGAPORE 417883 |                 |                             |  |
| <b>5a. Remarks</b>                                                                                                                     |                                                                                     |                 |                             |  |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                     |                 |                             |  |
| <b>5b. Estimate Days of Repair</b>                                                                                                     |                                                                                     |                 |                             |  |
| ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                    |                                                                                     |                 | 6 Working Days              |  |



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FU 2345K

| Qty | Description of Parts               | Condition      | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|------------------------------------|----------------|---------------------------|-------------------|
|     | <b><u>REPLACEMENT OF PARTS</u></b> |                |                           |                   |
| 1   | FRONT FORK ASSY                    | BENT / TWISTED | 980.00                    | 950.00            |
| 1   | FORK UNDER BRACKET COVER           | NO SUCH PARTS  | 190.00                    | -                 |
| 1   | FRONT SPORT RIM                    | BENT           | 550.00                    | 450.00            |
| 1   | FRONT BRAKE DISC                   | BENT           | 180.00                    | 180.00            |
| 1   | FRONT RIM SHAFT                    | CUT            | 52.00                     | 30.00             |
| 1   | WINDSHIELD                         | NOT NECESSARY  | 248.00                    | -                 |
| 1   | HEADLAMP                           | CRACKED        | 550.00                    | 520.00            |
| 1   | HEADLAMP COVER (MATT BLACK)        | CRACKED        | 18.00                     | 18.00             |
| 1   | SIDE MIRROR (O/S)                  | BROKEN         | 180.00                    | 125.00            |
| 1   | HANDLE BAR                         | BENT           | 135.00                    | 135.00            |
| 1   | SET HANDLE BAR BALANCER            | MISSING        | 80.00                     | 40.00             |
| 1   | SET HAND GRIP                      | TORN           | 60.00                     | 60.00             |
| 2   | BRAKE LEVER                        | N/S SCRATCHED  | 104.00                    | 48.00             |
| 1   | FRONT COWLING INNER PANEL          | CRACKED        | 150.00                    | 125.00            |
| 1   | FRONT INNER PANEL                  | CRACKED        | 160.00                    | 120.00            |
| 2   | FRONT FENDER SIDE COVER            | CRACKED        | 320.00                    | 185.00            |
| 1   | FRONT FENDER                       | CRACKED        | 180.00                    | 180.00            |
| 2   | FRONT SIGNALS                      | CRACKED        | 150.00                    | 120.00            |
| 1   | LAMP STAY                          | BENT           | 225.00                    | 225.00            |
| 1   | CENTRE COVER LOWER                 | CRACKED        | 80.00                     | 80.00             |
| 1   | LOWER BELLY PANEL                  | CRACKED        | 250.00                    | 215.00            |
| 1   | LOWER COWLING CENTRE GRILLE        | CUT            | 95.00                     | 95.00             |
| 1   | RADIATOR                           | PUNCTURE       | 485.00                    | 485.00            |
| 1   | RADIATOR SPARE TANK                | NOT NECESSARY  | 155.00                    | -                 |
| 2   | FOOTSTEP PANELS                    | N/S DISTORTED  | 310.00                    | 155.00            |
| 2   | REAR HANDLES                       | N/S CUT        | 170.00                    | 85.00             |
| 1   | MAIN STAND                         | CUT            | 145.00                    | 125.00            |
| 1   | SIDE STAND                         | CUT            | 95.00                     | 95.00             |
| 1   | SET FAIRING COVER                  | CRACKED        | 1,150.00                  | 800.00            |
| 1   | ENGINE COVER                       | CUT            | 350.00                    | 350.00            |
| 1   | AIRFILTERBOX COVER                 | CUT            | 150.00                    | 150.00            |

Report Ref No. CC4/FCI20014007/Uea3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty                                                                             | Description of Parts                          | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|---------------------------------------------------------------------------------|-----------------------------------------------|---------------|---------------------------|-------------------|
| 1                                                                               | FRONT BRAKE CALIPER                           | SERVICEABLE   | 325.00                    | -                 |
| 1                                                                               | CRASH BAR                                     | BENT          | 380.00                    | 320.00            |
|                                                                                 | LESS 10% DISCOUNT                             |               | -865.20                   | -646.60           |
|                                                                                 |                                               |               | 7,786.80                  | 5,819.40          |
|                                                                                 | <b><u>SPECIAL NETT ITEMS</u></b>              |               |                           |                   |
| 2                                                                               | FORK OILS (SN)                                | NOT NECESSARY | 30.00                     | -                 |
| 2                                                                               | FORK OIL SEALS (SN)                           | NOT NECESSARY | 56.00                     | -                 |
| 1                                                                               | SET STEERING CONE (SN)                        | NECESSARY     | 120.00                    | 80.00             |
| 1                                                                               | SET NUMBER PLATE (SN)                         | NOT NECESSARY | 28.00                     | -                 |
| 1                                                                               | COOLANT (SN)                                  | NOT NECESSARY | 18.00                     | -                 |
| 1                                                                               | REAR BOX (SN)                                 | CUT           | 580.00                    | 500.00            |
| 1                                                                               | 'X MAX' EMBLEM (SN)                           | NECESSARY     | 60.00                     | 60.00             |
|                                                                                 |                                               |               | 892.00                    | 640.00            |
|                                                                                 | <b><u>LABOUR</u></b>                          |               |                           |                   |
|                                                                                 | TO PROVIDE TOWING SERVICE (LOD) .             |               | 120.00                    | 120.00            |
|                                                                                 | TO CHECK WIRING AND RESET HEADLAMP FOCUSING . | NOT NECESSARY | 80.00                     | -                 |
|                                                                                 | TO PROVIDE LABOUR .                           |               | 480.00                    | 350.00            |
|                                                                                 | TO RESPRAY PAINTING .                         | NOT NECESSARY | 800.00                    | -                 |
|                                                                                 | TO REPAIR BODY FRAME .                        | NOT NECESSARY | 450.00                    | -                 |
|                                                                                 |                                               |               | 1,930.00                  | 470.00            |
| <b>GRAND TOTAL</b>                                                              |                                               |               | <b>10,608.80</b>          | <b>6,929.40</b>   |
| <b>RECOMMENDED COST OF LUMP SUM REPAIRS<br/>(TO ITS PRE-ACCIDENT CONDITION)</b> |                                               |               |                           | <b>5,500.00</b>   |

Report Ref No. CC4/FCI20014007/Uea3q2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. FU 2345K

INSPECTION





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. FU 2345K

RE-INSPECTION





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. FU 2345K

### RE-INSPECTION





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

