

C L Auto Pte Ltd

48 TOH GUAN ROAD EAST #02-125 ENTERPRISE HUB SINGAPORE 608586
TEL: 6795 6125 FAX: 6795 0920 Email: vincent@clauto.com.sg
RCB NO:198800292M

M/S : INSTRUMAC INSTRUMENTATION

51 BUKIT BATOK CRESENT

#06-01 UNITY CENTRE

SINGAPORE 658077

TEL: +65 6742 4840

FAX: +65 6741 3991

ATTN: MR. MICHAEL W.P. LIM

Estimate No: EST1900520

Date: 01 Dec 2020

Policy No:

Veh Reg No: GBD1879E

Make/Model: NISSAN NV200 1.5L MT
ABS AIRBAG 2WD 6DR
EURO 5

Your Ref No: GBD1879E

Chassis No: VSKYBAM20Z0085086

Claim Type: Third Party

Engine No: K9KC400D053665

Accident Date:

Reg. Date: 21/07/2014

Payment Term: COD

Estimate Repair Cost to Vehicle No :GBD1879E

Item No	Description	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
	CHASIS NO. - VSKYBAM20Z0085086			
	Net Price:			
1	PART REAR LH TAIL LAMP ASSY <i>Xnn</i>	1 PC	297.00 <i>X</i>	624.80
2	PART REAR LH TAIL LAMP SEAL <i>Xnn</i>	1 PC	432.00 <i>X</i>	10%
3	PART REAR LH FENDER ASSY <i>repair</i>	1 PC	1,854.30 <i>X R</i>	
4	PART REAR BUMPER <i>scr</i>	1 PC	624.80	562.32
5	PART REAR BUMPER BEAM <i>Xnn</i>	1 PC	120.00 <i>X</i>	
6	PART REAR BUMPER RETAINER <i>Xnn</i>	1 PC	58.00 <i>X</i>	
7	PART REAR LOWER PANEL <i>Xnn</i>	1 PC	217.12 <i>X</i>	
			3,603.22	
		Less 10%	360.32	3,242.90
	Special Net:			
8	PART REAR BUMPER RETAINER CLIP <i>ae</i>	1 SET	50.00 <i>30</i>	30
			50.00	50.00
	Labour Charges:			
9	LABOUR TO UNDERCOATING REAR LH FENDER ASSY & BUMPER	1 PCS	280.00 <i>40</i>	
10	LABOUR TO CUT & WELDING REAR LH FENDER, LOWER PANEL, TAIL LAMP PANEL, REAR BUMPER BEAM & REAR TAIL LAMP ASSY AND BACK LH DOOR	1 JOB	1,400.00 <i>250+150</i>	440
			1,680.00	1,680.00
	Total			S\$ 4,972.90

LKK Total Consultants have notified the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For C L Auto Pte Ltd

AUTHORISED SIGNATURE

C L Auto Pte Ltd

48 TOH GUAN ROAD EAST #02-125 ENTERPRISE HUB SINGAPORE 608586
TEL: 6795 6125 FAX: 6795 0920 Email: vincent@clauto.com.sg
RCB NO:198800292M

M/S : INSTRUMAC INSTRUMENTATION
51 BUKIT BATOK CRESENT
#06-01 UNITY CENTRE
SINGAPORE 658077

TEL: +65 6742 4840 FAX: +65 6741 3991
ATTN: MR. MICHAEL W.P. LIM

Estimate No: EST1900535

Date: 22 Dec 2020

Policy No:

Veh Reg No: GBD1879E

Make/Model: NISSAN NV200 1.5L MT
ABS AIRBAG 2WD 6DR
EURO 5

Your Ref No: GBD1879E

Claim Type: Third Party

Accident Date: 25/11/2020

Chassis No: VSKYBAM20Z0085086

Engine No: K9KC400D053665

Reg. Date: 21/07/2014

Term: COD

Supplementary Estimate Repair Cost to Vehicle No : GBD1879E

Pages:1/1

Item No	Description	U/Price	Quantity	Cost S\$	Amount S\$
<u>Labour Charges</u>					
1	LABOUR				
	TO PUTTY & RESPRAY PAINT REAR		1 JOB	800.00	400
	FENDER & TAIL LAMP & LOWER				
	PANEL & POLISH				
2	LABOUR				
	REAR LH FENDER COMPANY LOGO		1 SET	240.00	300
3	LABOUR				
	REAR RH FENDER COMPANY		1 SET	240.00	
	TELEPHONE NUMBER & EMAIL				
					1,280.00

Total Amount Payable

S\$ 1,280.00

TOTAL: SINGAPORE DOLLAR ONE THOUSAND TWO HUNDRED EIGHTY ONLY

562.32

30.00

400.00

700.00

1692.32

20%

1353.85

45-1,350

For C L Auto Pte Ltd

AUTHORISED SIGNATURE

have to uk off

+6011-11