



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2102629
INV Date 15/04/2021
Reference CC4/LPC20014014/Qga3q2
Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SJD 5022P
Insured Veh. GBD 6067Z
Claim No. 20/20/20/VC00/024012
Policy No. Z/20/VC00/105778
Accident Date 14/12/2020
Inspection Date 21/12/2020

Description	Total
Survey Inspection	250.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	250.00
GST (7%)	17.50
Grand Total	267.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

300 BEACH ROAD

#17-04/07 THE CONCOURSESINGAPORE 199555

Ref: CC4/LPC20014014/Qga3q2

Date: 15/04/2021

Code: LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBD 6067Z	Veh. Inspected	SJD 5022P
Policy No.	Z/20/VC00/105778	Coverage (\$)	0.00
Claim No.	20/20/20/VC00/024012	Excess (\$)	0.00
Assign From	ONG LI LI	Assign Date	16/12/2020

2. Vehicle Particulars & Condition

Make & Model	MITSUBISHI LANCER 1.5	c.c	1499
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	JMYSRCY2A8U004588	Colour	SILVER
Odometer	285376 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/50Z R17	KAPSEN	6 mm
L/H Front Tyre	225/50Z R17	KAPSEN	6 mm
R/H Rear Tyre	225/50Z R17	KAPSEN	6 mm
L/H Rear Tyre	225/50Z R17	KAPSEN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	14/12/2020	Inspection Date	21/12/2020
Survey held at	TWIN WHEELS AUTO TRADING ENTERPRISE 38 WOODLANDS INDUSTRIAL PARK E1 # 03-14 SINGAPORE 757700		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJD 5022P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	CRUMPLED	809.00	809.00
1	FRONT BUMPER RETAINER -RH	BROKEN	16.00	16.00
1	FRONT HEADLAMP -RH	CRUMPLED	671.00	671.00
1	FRONT FENDER -RH	CRUMPLED	496.00	496.00
1	FRONT FENDER COWLING -RH	SERVICEABLE	105.00	-
1	FRONT FENDER GARNISH -RH	NECESSARY	98.00	98.00
1	FRONT WHEEL BEARING -RH	JAMMED	137.00	137.00
1	FRONT LOWER ARM -RH	SERVICEABLE	292.00	-
1	FRONT WHEEL KNUCKLE -RH	SERVICEABLE	308.00	-
1	FRONT WIPER TANK -RH	CRUMPLED	74.00	74.00
1	FRONT SPORT RIM -RH	CUT	380.00	350.00
	LESS 20% DISCOUNT		-677.20	-530.20
			2,708.80	2,120.80
LABOUR				
	LABOUR TO SPRAY PAINT .		650.00	400.00
	LABOUR TO PANEL BEATING .		500.00	500.00
	LABOUR TO FOCUS HEADLAMP ,WIRING CHECK .		50.00	30.00
	LABOUR TO APPLY RUST-PROOFING ON REPAIRED AND REPLACED PARTS.		80.00	30.00
	COMPUTERISED WHEEL ALIGNMENT .		120.00	60.00
			1,400.00	1,020.00
GRAND TOTAL			4,108.80	3,140.80
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,500.00

Report Ref No. CC4/LPC20014014/Qga3q2

OI SUN PIN

Asst. Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJD 5022P

INSPECTION









LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJD 5022P

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

