

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC4/III20014018/GEA3Q2

Date:

25/08/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No: D18MFL0001926_02

Claimant Vehicle No : SGN6418H**Insured Vehicle No :** XD7678T

Date of Loss: 09/12/2020

Nature of Claim: TP

Claim No: MFL2020D0002689

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SGN6418H**

Make & Model: TOYOTA COROLLA ALTIS, 1.6 CVT (A)

Engine No: 1ZRX571489

Reg. Date: 11/11/2016 (Man. Year: 2016)

Chassis No: MR053REH104550466

Colour: Silver

Odometer: 128901 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/45Z R17	Rear Tyre Size:	215/45Z R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,766.77	912.07	854.70	48.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,770.00	1,170.00	600.00	33.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,536.77	2,082.07	1,454.70	41.13
Approved Total (Overridden) (S\$)		1,650.00		

(S\$)	3,536.77	1,650.00	1,886.77	53.35
+ GST 7.00/7.00% (S\$)	247.57	115.50	132.07	53.35
Nett Amount (S\$)	3,784.34	1,765.50	2,018.84	53.35
+ Car Rental (5.0 x S\$100.00/day) (S\$)		500.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,272.95		
Global Sum Settlement (S\$)		2,270.00		

INSPECTION

Date of Assignment: 16/12/2020

Date Inspected: 17/12/2020

Estimated Period of Repair: 5.0 days

Inspected At:

KAI MOTOR TRADING (HQ)
 BLK 3007 UBI ROAD 1, #01-440
 Singapore 408701

Adjuster: XING GUO QIANG**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 May 2021)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGN6418H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR FENDER RH	Buckled	1,102.10 FL	*981.10 FL
2	1		*REAR BUMPER	Repair	515.30 FL	*- FL
3	8		*REAR BUMPER CLIPS	Necessary	50.00 FL	*50.00 FL
4	2		*REAR BUMPER SIDE RETAINER RH	Deformed (1 PCS ONLY)	270.20 FL	*65.00 FL
5	1		*REAR WINDSCREEN GLASS MOULDING	Necessary	120.00 FL	*120.00 FL
6	1		*REAR DOOR INNER RUBBER RH	Not Necessary	298.10 FL	*- FL
					Sub Total (\$\$)	2,355.70
					- List Item Discount on L Items 25.00/25.00% (\$\$)	588.93
					Total Parts (\$\$)	1,766.77
						912.07

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE & REPLACE DAMAGE PARTS ,PANEL BEAT WHERE NECESSARY	New	800.00	550.00
2	TO PUTTY ,APPLY PRIMER & SPRAY PAINT ON THE AFFECTED PORTION	New	850.00	500.00
3	TO REMOVE AND REFIT WINDSCREEN	New	120.00	120.00
Gross Labour Cost (\$\$)			1,770.00	1,170.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >