



凱摩哆服務

KAI MOTOR TRADING

BLK 3007 UBI ROAD 1 #01-440, SINGAPORE 408701.
TEL: 6747 4006 FAX: 6743 7591 EMAIL: kaimotor@gmail.com
BUS. REG. NO: 44223100L GST NO: M90371531Y

專業服務：汽車意外保險賠償，拖車，汽車修理及維修服務，打嗎呷，噴漆。
Specialist in: Accidents Insurance Claim, Towing Service, Motor Vehicle Repairing, Panel Beating, Spray Painting.

Date : 14/12/2020

Attn: The Motor Claims Department
Your Insured veh no :SJS 3733 E
India International Insurance Pte Ltd
64 Cecil Street
#04--02 IOB Building
Singapore 049711

Dear Sir / Madam

WITHOUT PREJUDICE

(By Email Only)

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimate Cost of repair To Toyota Corolla ~~SJS 3733 E~~ **SJS 3733 E** on 11/02/2020 @ 084000

To Supply :-

1pc	Rear fender RH / <i>Blue</i>	\$ 1,102.10
1pc	Rear bumper ?	\$ 515.30
8pcs	Rear bumper clips / <i>MC</i>	\$ 50.00
2pcs	Rear bumper side retainer RH ?	\$ 270.20
1pc	Rear windscreen glass moulding / <i>MC</i>	\$ 120.00
1pc	Rear door inner rubber RH <i>X MC</i>	\$ 298.10
		\$ 2,355.70
		25% \$ 588.93
		\$ 1,766.78

To dismantl & replace damage parts, panel beat where necessary \$ 800.00 *550*

To putty, apply primer & spray paint on the affected portion. \$ 850.00 *500*

To remove and refit windscreen. \$ 120.00 ✓
\$ 3,499.28

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

5 Days.
Unspray repair
After repair photos.
Good Qial for 880282
17/12/2020