



# QUOTATION

**KAH MOTOR CO. SDN. BHD.**  
(A Member of the Oriental Holdings Berhad)

GST Reg No.: M200050223  
Company Ref. No.: S60FC1380G

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

**Customer** : MS FIRST CAPITAL INSURANCE LIMITED  
36 ROBINSON ROAD  
#16-01 CITY HOUSE  
SINGAPORE 068877

**Registration No** : SME1313K

**Chassis No** : JHMGK5850JX208455

**Model** : JAZZ 1.5VTIR CVT 18YM (EURO 6)

**Owner's Name** : NG LAY PHENG

**Ins Policy No.** :

**Date of Accident** : 14/12/2020

**Document No.** : SQT20004105

**Date** : 15. Dec 2020

**Customer No.** : WZF002

**Svc Advisor** : ANIKKA LAI SWEE KAM

**Engine No** : L15B33114346

**Date | Time** : 15. Dec 2020 4:04:23 PM

**Surveyor Name** :

**Survey Date** :

**Authentication** : LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

**Acknowledged by Repairer**

Signature:

Date:

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: ) OWNER: NG LAY PHENG OWNER INSURER: AVIVA ACC DATE: 14/12/2020 SURVEYED BY: DATE: REF NO: TP INSURER: FCL TP VEH: SHC7255A						
68100-T5B-Z50ZZ	TAILGATE COMP / <i>buc</i>	1	749.60	25	562.20	39.35	601.55
74440-T5A-003	WEATHERSTRIPTAILGATE X <i>NN</i>	1	92.30	25	69.22	4.85	74.07
74800-T5S-K61	LOCK ASSY, TAILGATE X <i>NN</i>	1	86.20	25	64.65	4.53	69.18
74820-T5C-J01	STAY ASSYR. TAILGATE OPEN X <i>NN</i>	1	96.40	25	72.30	5.06	77.36
74870-T5C-J01	STAY ASSYL. TAILGATE OPEN X <i>NN</i>	1	96.40	25	72.30	5.06	77.36
75722-T5L-T01	EMBLEMRR. / <i>bc</i>	1	11.90	25	8.92	0.62	9.54
04715-T5B-J50ZZ	FACE, RR. BUMPER / <i>Dis</i>	1	515.50	25	386.62	27.06	413.68
71593-T5A-J50	SPACER, R. RR. BUMPER SIDE <del>X</del> <i>NN</i>	1	17.30	25	12.97	0.91	13.88
71598-T5A-J50	SPACER, L. RR. BUMPER SIDE / <i>cut</i>	1	17.30	25	12.97	0.91	13.88
71510-T5B-J50ZA	DIFFUSER ASSY, RR. PR / <i>Dis</i>	1	212.10	25	159.07	11.13	170.20
71502-T5A-J60	COVER, R. RR. BUMPER X <i>NN</i>	1	21.20	25	15.90	1.11	17.01
71507-T5A-J60	COVER, L. RR. BUMPER / <i>cut</i>	1	21.20	25	15.90	1.11	17.01
74890-T5B-911	GARNISH ASSY, RR. LICENSE X <i>NN</i>	1	219.10	25	164.32	11.50	175.82
75701-T5A-000	EMBLEMH X <i>NN</i>	1	10.70	25	8.02	0.56	8.58
90301-ST0-003	NUTPUSH 3MM X <i>NN</i>	2	2.10	25	3.15	0.22	3.37
66100-TAR-T10ZZ	PANEL COMPRR. / <i>buc</i>	1	328.60	25	246.45	17.25	263.70
65540-T5A-N00ZZ	STIFFENER COMP, R. RR. X <i>NN</i>	1	89.20	25	66.90	4.68	71.58
63720-T5A-900ZZ	GUTTER COMP, L. RR. PILLAR LOWER / <i>buc</i>	1	91.00	25	68.25	4.78	73.03
63910-T5A-000ZZ	LID COMPFUEL FILLER X <i>NN</i>	1	43.70	25	32.77	2.29	35.06

Printed on 15/12/2020 5:04:53 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



# QUOTATION

**KAH MOTOR CO. SDN. BHD.**  
 (A Member of the Oriental Holdings Berhad)  
 Service and Body Repair

GST Reg No.: M200050223  
 Company Ref. No.: S60FC1380G

Tel: +65 6841 3838 Website: www.honda.com.sg  
 For 24-hours Roadside Assistance, Call 98203838

<b>Customer</b> : MS FIRST CAPITAL INSURANCE LIMITED	<b>Document No.</b> : SQT20004105	<b>Page</b> 2
36 ROBINSON ROAD	<b>Date</b> : 15. Dec 2020	
#16-01 CITY HOUSE	<b>Customer No.</b> : WZF002	
SINGAPORE 068877	<b>Svc Advisor</b> : ANIKKA LAI SWEE KAM	
<b>Registration No</b> : SME1313K	<b>Engine No</b> : L15B33114346	
<b>Chassis No</b> : JHMGK5850JX208455	<b>Date   Time</b> : 15. Dec 2020 4:04:23 PM	
<b>Model</b> : JAZZ 1.5VTIR CVT 18YM (EURO 6)	<b>Surveyor Name</b> :	
<b>Owner's Name</b> : NG LAY PHENG	<b>Survey Date</b> :	
<b>Ins Policy No.</b> :	<b>Authorisation Date</b> :	
<b>Date of Accident</b> : 14/12/2020		

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
84521-T5A-901ZA	LID ASSYSPARE TIRE X <i>nn</i>	1	194.70	25	146.02	10.22	156.24
84550-TAS-U00	BOX ASSY,CARGO FLOOR X <i>nec</i>	1	113.50	25	85.12	5.96	91.08
04646-TAS-330ZZ	PANEL SET,L.RR.OUTSIDE <i>ac</i>	1	585.30	25	438.97	30.73	469.70
64700-T5B-325ZZ	PANEL COMP,L.RR. X <i>NN</i>	1	533.50	25	400.12	28.01	428.13
84640-T5A-003ZA	LINING ASSY,RR.PANEL <i>BR</i>	1	60.80	25	45.60	3.19	48.79
65662-T5A-300ZZ	FRAME BL.RR. X <i>NN</i>	1	50.10	25	37.57	2.63	40.20
65619-T5A-300ZZ	FLANGE,RR.FRAME END X <i>NN</i>	1	11.30	25	8.47	0.59	9.06
74592-T5B-003	FENDER,L.RR.INNER X <i>NN</i>	1	81.00	25	60.75	4.25	65.00
84651-TAR-Z03ZA	LINING ASSYL.TRUNK X <i>NN</i>	1	173.40	25	130.05	9.10	139.15
33550-T5A-J02	TAILLIGHT ASSYL. <i>CRA</i>	1	244.60	25	183.45	12.84	196.29
34155-T5A-J01	LIGHT ASSYL.LID X <i>NN</i>	1	89.20	25	66.90	4.68	71.58
YH-185/55R16-AE50	YOKOHAMA TYRE <i>ct.</i> <i>(20%)</i>	1	135.00	10%	135.00	9.45	144.45
52611-T5A-J12	DAMPER UNITRR. X <i>NN</i>	1	222.90	25	167.17	11.70	178.87
42100-T5A-J75	BEAM ASSYRR.AXLE <i>BT</i>	1	934.70	25	701.02	49.07	750.09
73211-T5A-J01	GLASS SETRR.WINDSHIELD X <i>nn</i>	1	625.60	25	469.20	32.84	502.04
73127-TY0-000	RUBBER CWINDSHIELD DAMPER	1	11.70	25	8.77	0.61	9.38
73214-T5A-013	RUBBERWINDSHIELD DAMPER	2	7.10	25	10.65	0.75	11.40
73226-SZW-000	DAMPERSTD 5X5	1	8.70	25	6.52	0.46	6.98
BO-WS-SEALANT	WINDSCREEN SEALANT (N) <i>ac</i>	1	60.00		60.00	4.20	64.20
73525-SYY-000	RUBBERRR QTR W/SHIELD	2	9.90	25	14.85	1.04	15.89
91501-T5A-003	CLIPQUARTER WINDSHIELD A	1	3.70	25	2.77	0.19	2.96
91502-T5A-003	CLIPQUARTER WINDSHIELD B	1	3.70	25	2.77	0.19	2.96
91503-T5A-003	CLIPQUARTER WINDSHIELD C	1	2.50	25	1.87	0.13	2.00
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1	60.00		60.00	4.20	64.20
<b>Sum Item</b>					<b>5286.49</b>	<b>370.01</b>	<b>5,656.50</b>
BOSUN	SUNDRIES	1	100.00		100.00	7.00	107.00
BG51R	REPLACE RR. L QTR GLASS.(N)	1	300.00		300.00	21.00	321.00
BG02R	REPLACE RR. WINDSCREEN.(N)	1	650.00		650.00	45.50	695.50

Printed on 15/12/2020 5:04:53 PM  
 This is a computer generated invoice. No signature is required.  
 Part prices are subjected to change without notice.  
 The above estimated cost of repair do not include any unforeseen damages.  
 GST Amount is calculated from individual line(s).  
 An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.  
 However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.





# SERVICE PRE-INVOICE

**KAH MOTOR CO. SDN. BHD.**  
(A Member of the Oriental Holdings Berhad)

GST Reg No.: M200050223  
Company Ref. No.: S60FC1380G

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022  
255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

<b>Customer:</b>	CU0102259 / MS FIRST CAPITAL	<b>Document No:</b>	SVO20066429
<b>Chassis No:</b>	JHMGK5850JX208455	<b>Printed By:</b>	ANIKKALAI
<b>License No:</b>	SME1313K	<b>Order Date:</b>	17. December 2020
<b>Mileage:</b>	43508	<b>Order Time:</b>	6:14:04 PM
<b>Engine No:</b>	L15B33114346	<b>Service Advisor:</b>	ANIKKA LAI SWEE KAM

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount Includ GST
	TP DIRECT SETTLEMENT (J/NO: OWNER: NG LAY PHENG OWNER INSURER: AVIVA ACC DATE: 14/12/2020 SURVEYED BY: DATE: REF NO: TP INSURER: FCL TP VEH: SHC7255A						
					4096.3		
					-25%: 3072.22		
					f 228		
					Total = 3300.22		
68100-T5B-Z50ZZ	TAILGATE COMP	1	749.60	25	562.20	39.35	601.55
75722-T5L-T01	EMBLEMRR.	1	11.90	25	8.92	0.62	9.54
04715-T5B-J50ZZ	FACE,RR.BUMPER	1	515.50	25	386.62	27.06	413.68
71598-T5A-J50	SPACER,L.RR.BUMPER SIDE	1	17.30	25	12.97	0.91	13.88
71510-T5B-J50ZA	DIFFUSER ASSY,RR.PR	1	212.10	25	159.07	11.13	170.20
71507-T5A-J60	COVER,L.RR.BUMPER	1	21.20	25	15.90	1.11	17.01
66100-TAR-T10ZZ	PANEL COMPRR.	1	328.60	25	246.45	17.25	263.70
63720-T5A-900ZZ	GUTTER COMP,L.RR.PILLAR LOWER	1	91.00	25	68.25	4.78	73.03
84550-TAS-U00	BOX ASSY,CARGO FLOOR	1	113.50	25	85.12	5.96	91.08
04646-TAS-330ZZ	PANEL SET,L.RR.OUTSIDE	1	585.30	25	438.97	30.73	469.70
84640-T5A-003ZA	LINING ASSY,RR.PANEL	1	60.80	25	45.60	3.19	48.79
33550-T5A-J02	TAILLIGHT ASSYL.	1	244.60	25	183.45	12.84	196.29
YH-185/55R16-AE51	YOKOHAMA TYRE (CN)	1	135.00	108	135.00	9.45	144.45
42100-T5A-J75	BEAM ASSYRR.AXLE (CA)	1	934.70	25	701.02	49.07	750.09
73127-TY0-000	RUBBER CWINDSHIELD DAMPER	1	11.70	25	8.77	0.61	9.38
73214-T5A-013	RUBBERWINDSHIELD DAMPER	2	7.10	25	10.65	0.75	11.40
73226-SZW-000	DAMPERSTD 5X5	1	8.70	25	6.52	0.46	6.98
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1	60.00	25	60.00	4.20	64.20
73525-SYY-000	RUBBERRR QTR W/SHIELD	2	9.90	25	14.85	1.04	15.89
91501-T5A-003	CLIPQUARTER WINDSHIELD A	1	3.70	25	2.77	0.19	2.96
91502-T5A-003	CLIPQUARTER WINDSHIELD B	1	3.70	25	2.77	0.19	2.96
91503-T5A-003	CLIPQUARTER WINDSHIELD C	1	2.50	25	1.87	0.13	2.00
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1	60.00	25	60.00	4.20	64.20
65590-T5A-310ZZ	STIFFENER COMP,L.RR. (CA) ✓	1	91.00	25	68.25	4.78	73.03
74591-T5B-N00	COVER,L.RR.FENDER (CA) ✓	1	43.70	25	32.77	2.29	35.06
75450-SAA-013	OUTLETRR AIR (CA) ✓ CRA	1	25.90	25	19.42	1.36	20.78
90120-T2A-000	BOLTLOCK STRIKER (CA) ✓ MBC	1	2.30	25	1.72	0.12	1.84
	<b>SUM PARTS:</b>				<b>3,339.90</b>	<b>233.77</b>	<b>3,573.67</b>
BOSUN	SUNDRIES	1	30.00	25	30.00	2.10	32.10
BG51R	REPLACE RR. L QTR GLASS.(N)	1	300.00	25	300.00	21.00	321.00
BG02R	REPLACE RR. WINDSCREEN.(N)	1	650.00	25	650.00	45.50	695.50
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)	1	120.00	25	120.00	8.40	128.40
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	120.00	25	120.00	8.40	128.40



# SERVICE PRE-INVOICE

**KAH MOTOR CO. SDN. BHD.**  
(A Member of the Oriental Holdings Berhad)

GST Reg No.: M200050223  
Company Ref. No.: S60FC1380G

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022  
255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

<b>Customer:</b>	CU0102259 / MS FIRST CAPITAL	<b>Document No:</b>	SVO20066429
<b>Chassis No:</b>	JHMGK5850JX208455	<b>Printed By:</b>	ANIKKALAI
<b>License No:</b>	SME1313K	<b>Order Date:</b>	17. December 2020
<b>Mileage:</b>	43508	<b>Order Time:</b>	6:14:04 PM
<b>Engine No:</b>	L15B33114346	<b>Service Advisor:</b>	ANIKKA LAI SWEE KAM

<b>BMI03D</b>	REMOVE & INSTALL REAR COMPARTMENT LININGS GARNISHES.(N)	1	650.00 /	650.00	45.50	695.50
<b>BKTG02R</b>	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & ALIGN TAILGATE.(N)	1	350.00 /	350.00	24.50	374.50
<b>BC012R</b>	RESET VEHICLE SMART ENTRY SYSTEM	1	325.00 /	325.00	22.75	347.75
<b>BC011R</b>	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	325.00 /	325.00	22.75	347.75
<b>BMF00D</b>	RREMOVE & INSTALL FUEL TANK FUEL PIPES.(N)	1	325.00 /	325.00	22.75	347.75
<b>BOJSE</b>	BODY JOINT SEALANT TAILGATE	1	80.00 /	80.00	5.60	85.60
<b>BOJSE</b>	BODY JOINT SEALANT END PANEL	1	80.00 /	80.00	5.60	85.60
<b>BOJSE</b>	BODY JOINT SEALANT FENDER	1	80.00 /	80.00	5.60	85.60
<b>BKFE21R</b>	0671 CUT & RENEW RR L FENDER. STRAIGHTEN INNER PANEL INCLUDING FITTING ON ATTACHMENT ITEMS.	1	4,225.00 /	4,225.00	295.75	4,520.75
<b>BP07R</b>	1847 SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(7P)	1	2,600.00 /	2,600.00	182.00	2,782.00
<b>BO-TOW</b>	TOWING SERVICES (MBBS)	1	100.00 /	100.00	7.00	107.00
<b>BG51R</b>	REPLACE RR. L QTR GLASS.(N)	1	250.00 X	250.00	17.50	267.50
<b>BMU02R</b>	REMOVE & REPLACE RR AXLE. (N)	1	650.00 /	650.00	45.50	695.50
			<b>SUM LABOUR:</b>	<b>11,260.00</b>	<b>788.20</b>	<b>12,048.20</b>
<b>BO-WHEEL ALIGN X4</b>	WHEEL ALIGNMENT X4	1	180.00 /	180.00	12.60	192.60
			<b>SUM EXT SERVICE:</b>	<b>180.00</b>	<b>12.60</b>	<b>192.60</b>
				<b>TOTAL SGD</b>	<b>14,779.90</b>	<b>1,034.57</b>
				<b>TOTAL SGD</b>	<b>14,779.90</b>	<b>1,034.57</b>
				<b>Total Payable (SGD)</b>		<b>15,814.47</b>

GST Amount is calculated from individual line(s)

1190  
14490.22  
11 Days