



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877
Registration No : SME1313K
Chassis No : JHMGK5850JX208455
Model : JAZZ 1.5VTIR CVT 18YM (EURO 6)
Owner's Name : NG LAY PHENG
Ins Policy No. :
Date of Accident : 14/12/2020

Document No. : SQT20004105
Date : 15. Dec 2020
Customer No. : WZF002
Svc Advisor : ANIKKA LAI SWEE KAM
Engine No : L15B33114346
Date | Time : 15. Dec 2020 4:04:23 PM
Surveyor Name :
Survey Date :
Authentication :
LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: NG LAY PHENG OWNER INSURER: AVIVA ACC DATE: 14/12/2020 SURVEYED BY: DATE: REF NO: TP INSURER: FCL TP VEH: SHC7255A						
68100-T5B-Z50ZZ	TAILGATE COMP / Bue	1	749.60	25	562.20	39.35	601.55
74440-T5A-003	WEATHERSTRIPTAILGATE X NN	1	92.30	25	69.22	4.85	74.07
74800-T5S-K61	LOCK ASSY, TAILGATE ?	1	86.20	25	64.65	4.53	69.18
74820-T5C-J01	STAY ASSY, R. TAILGATE OPEN X SNN	1	96.40	25	72.30	5.06	77.36
74870-T5C-J01	STAY ASSY, L. TAILGATE OPEN X	1	96.40	25	72.30	5.06	77.36
75722-T5L-T01	EMBLEMRR. / Bue	1	11.90	25	8.92	0.62	9.54
04715-T5B-J50ZZ	FACE, RR. BUMPER / Dis	1	515.50	25	386.62	27.06	413.68
71593-T5A-J50	SPACER, R. RR. BUMPER SIDE X NN	1	17.30	25	12.97	0.91	13.88
71598-T5A-J50	SPACER, L. RR. BUMPER SIDE / Cut	1	17.30	25	12.97	0.91	13.88
71510-T5B-J50ZA	DIFFUSER ASSY, RR. PR / Dis	1	212.10	25	159.07	11.13	170.20
71502-T5A-J60	COVER, R. RR. BUMPER X NN	1	21.20	25	15.90	1.11	17.01
71507-T5A-J60	COVER, L. RR. BUMPER / Cut	1	21.20	25	15.90	1.11	17.01
74890-T5B-911	GARNISH ASSY, RR. LICENSE X NN	1	219.10	25	164.32	11.50	175.82
75701-T5A-000	EMBLEMH X SNN	1	10.70	25	8.02	0.56	8.58
90301-ST0-003	NUTPUSH 3MM X SNN	2	2.10	25	3.15	0.22	3.37
66100-TAR-T10ZZ	PANEL COMPRR. / Bue	1	328.60	25	246.45	17.25	263.70
65540-T5A-N00ZZ	STIFFENER COMP, R. RR. /	1	89.20	25	66.90	4.68	71.58
63720-T5A-900ZZ	GUTTER COMP, L. RR. PILLAR LOWER / Bue.	1	91.00	25	68.25	4.78	73.03
63910-T5A-000ZZ	LID COMPFUEL FILLER X NN.	1	43.70	25	32.77	2.29	35.06

Printed on 15/12/2020 5:04:53 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877
Registration No : SME1313K
Chassis No : JHMGK5850JX208455
Model : JAZZ 1.5VTIR CVT 18YM (EURO 6)
Owner's Name : NG LAY PHENG
Ins Policy No. :
Date of Accident : 14/12/2020

Document No. : SQT20004105
Date : 15. Dec 2020
Customer No. : WZF002
Svc Advisor : ANIKKA LAI SWEE KAM
Engine No : L15B33114346
Date | Time : 15. Dec 2020 4:04:23 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
84521-T5A-901ZA	LID ASSYSPARE TIRE X	1	194.70	25	146.02	10.22	156.24
84550-TAS-U00	BOX ASSY,CARGO FLOOR X	1	113.50	25	85.12	5.96	91.08
04646-TAS-330ZZ	PANEL SET,L.RR.OUTSIDE -	1	585.30	25	438.97	30.73	469.70
64700-T5B-325ZZ	PANEL COMP,L.RR. ?	1	533.50	25	400.12	28.01	428.13
84640-T5A-003ZA	LINING ASSY,RR.PANEL -	1	60.80	25	45.60	3.19	48.79
65662-T5A-300ZZ	FRAME BL.RR. ?	1	50.10	25	37.57	2.63	40.20
65619-T5A-300ZZ	FLANGE,RR.FRAME END ?	1	11.30	25	8.47	0.59	9.06
74592-T5B-003	FENDER,L.RR.INNER ?	1	81.00	25	60.75	4.25	65.00
84651-TAR-Z03ZA	LINING ASSYL.TRUNK ?	1	173.40	25	130.05	9.10	139.15
33550-T5A-J02	TAILLIGHT ASSYL. CRA.	1	244.60	25	183.45	12.84	196.29
34155-T5A-J01	LIGHT ASSYL.LID ?	1	89.20	25	66.90	4.68	71.58
YH-185/55R16-AE50	YOKOHAMA TYRE -	1	135.00	10%	135.00	9.45	144.45
52611-T5A-J12	DAMPER UNITRR. ?	1	222.90	25	167.17	11.70	178.87
42100-T5A-J75	BEAM ASSYRR.AXLE ?	1	934.70	25	701.02	49.07	750.09
73211-T5A-J01	GLASS SETRR.WINDSHIELD X	1	625.60	25	469.20	32.84	502.04
73127-TY0-000	RUBBER CWINDSHIELD DAMPER	1	11.70	25	8.77	0.61	9.38
73214-T5A-013	RUBBERWINDSHIELD DAMPER	2	7.10	25	10.65	0.75	11.40
73226-SZW-000	DAMPERSTD 5X5	1	8.70	25	6.52	0.46	6.98
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1	60.00		60.00	4.20	64.20
73525-SYY-000	RUBBERRR QTR W/SHIELD	2	9.90	25	14.85	1.04	15.89
91501-T5A-003	CLIPQUARTER WINDSHIELD A	1	3.70	25	2.77	0.19	2.96
91502-T5A-003	CLIPQUARTER WINDSHIELD B	1	3.70	25	2.77	0.19	2.96
91503-T5A-003	CLIPQUARTER WINDSHIELD C	1	2.50	25	1.87	0.13	2.00
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1	60.00		60.00	4.20	64.20
Sum Item					5286.49	370.01	5,656.50
BOSUN	SUNDRIES	1	100.00		100.00	7.00	107.00
BG51R	REPLACE RR. L QTR GLASS.(N)	1	300.00		300.00	21.00	321.00
BG02R	REPLACE RR. WINDSCREEN.(N)	1	650.00		650.00	45.50	695.50

Printed on 15/12/2020 5:04:53 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : MS FIRST CAPITAL INSURANCE LIMITED
 36 ROBINSON ROAD
 #16-01 CITY HOUSE
 SINGAPORE 068877

Registration No : SME1313K

Chassis No : JHMGK5850JX208455

Model : JAZZ 1.5VTIR CVT 18YM (EURO 6)

Owner's Name : NG LAY PHENG

Ins Policy No. :

Date of Accident : 14/12/2020

Document No. : SQT20004105

Date : 15. Dec 2020

Customer No. : WZF002

Svc Advisor : ANIKKA LAI SWEE KAM

Engine No : L15B33114346

Date | Time : 15. Dec 2020 4:04:23 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 3

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Incl GST
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	150.00	120	150.00	10.50	160.50
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	150.00	120	150.00	10.50	160.50
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	800.00	650	800.00	56.00	856.00
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	450.00	350	450.00	31.50	481.50
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	450.00	325	450.00	31.50	481.50
BC011R	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	450.00	325	450.00	31.50	481.50
BMF00D	RREMOVE & INSTALL FUEL TANK FUEL PIPES.(N)	1	650.00	325	650.00	45.50	695.50
BOJSE	BODY JOINT SEALANT TAILGATE	1	100.00	80	100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT END PANEL	1	100.00	80	100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT FENDER	1	100.00	80	100.00	7.00	107.00
BKFE21R	CUT & RENEW RR L FENDER. STRAIGHTEN INNER PANEL	1	4500.00	4225	4500.00	315.00	4815.00
BP07R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (7P)	1	3500.00	2600	3500.00	245.00	3745.00
BO-TOW	TOWING SERVICES (MBBS)	1	100.00	/	100.00	7.00	107.00
BG51R	REPLACE RR. L QTR GLASS.(N) X NN	1.6	100.00		160.00	11.20	171.20
Sum Labor					12710.00	889.70	13,599.70
BO-WHEEL ALIGN X4	WHEEL ALIGNMENT X4	1	180.00	/	180.00	12.60	192.60
Sum Ext. Service					180.00	12.60	192.60

Survey By

Date & Time

Excess

Status

Signature

Total Amount 18,176.49 1,272.31 19,448.80

Total (Inclusive of GST) 19,448.80

10 Days.

Printed on 15/12/2020 5:04:53 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.