



60 Woodlands Industrial Park E4 Singapore 757705 Tel: 65 6362 3422 Fax: 65 6368 7420

SMRT Vehicle Repair Estimate

Group : Buses / Taxis / Commercial	
Reg. No. : SLE233B	Ref. N :
Make / Model : HONDA JAZZ	Reg. Date :
Chassic No JHMGK58500X203105	Mileag : 9496
Name of Driver : GOH SHU FONG	Rental/Replacement Vehic: Yes / No
Date/Time of Accident : 14/12/2020 19:20	The damages on the vehicle are as
Surveyer is Required ? YES / NO	indicated in the following diagram :
If Yes, VICOM / LKK / AIS / Others MSIG :	
Vehicle is Towed Back ? YES / NO Date / Time :	
Accident reporting date: 15/12/2020	
Type of Accident : Skid / Head-Rear / Head-On / Side Swipe / Others	
Special Instruction to ARC, if any :	
	_
*Note: Air freight waiting time not included in number of repair days.	
Signed : Date	
	· · · · · · · · · · · · · · · · · · ·
Accident Repair Job Card No : Date Pre	eparec :
	Compl :
Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges : \$ 250.00	
Total Spray Painting Charges: \$ 350.00	
· · · · · · · · · · · · · · · · · · ·	
Total Material Charges :	
Total Material Charges : Other Charges : \$ 200.00	
Other Charges : \$ 200.00	
Other Charges \$ 200.00 TOTAL \$ 800.00	
Other Charges	
Other Charges \$ 200.00 TOTAL \$ 800.00	any::
Other Charges	
Other Charges \$ 200.00 TOTAL \$ 800.00 Lump Sum Repair, if a No. of Repair Days [3] days	[] days
Other Charges : \$ 200.00 TOTAL : \$ 800.00 Lump Sum Repair, if a series of the series	[] days
Other Charges \$ 200.00 TOTAL \$ 800.00 Lump Sum Repair, if a No. of Repair Days [3] days	[] days

Part 1 - Labour Works

Job Scope	Quotation from ARC	
To Panel Beat Rear Boot Two Portions	\$ 250.	00.
Total Labour	\$ 250.	00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC		
To respray affected areas	\$	350.00	
Total Spray Painting & Panel Beating	\$	350.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Page (3)

Job Scope	Quotation from ARC	
To Check on Effected Area Wiring System	\$ 80.00	20
To Test And Refit Reverse Sensor Sy:	\$ 120.00	30
Total Other Costs	\$ 200.00	

Repair dy - 2dy,

P/P
before pains phoe
Sur Pin (Usli) 21/12/2020. TPurtha prejudu

LKK Auto Consultants hence notify

the Repairer of the following:

- · To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: