

Sum / I.B.I: (\$

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5111U

15 DEC 2020

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

PART

- 1 MIRROR ASSY, OUTER REAR VIEW, LH
- 1 PANEL SUB-ASSY, FRONT DOOR, LH
- 1 REGULATOR SUB-ASSY, FRONT DOOR WINDOW, LH
- 1 MOTOR ASSY, POWER WINDOW REGULATOR, LH
- 1 HINGE ASSY, FRONT DOOR, LOWER LH
- 1 HINGE ASSY, FRONT DOOR, UPPER LH
- 1 TAPE, BLACK OUT, NO.1 FRT LH
- 1 TAPE, BLACK OUT, NO.2 FRT LH
- 1 TAPE, BLACK OUT, NO.3 FRT LH
- 1 MOULDING ASSY, BODY ROCKER PANEL, LH
- 1 WEATHERSTRIP, FRONT DOOR FIX WINDOW, LH

LIST

\$	<i>Br</i> 1,339.30	<i>✓</i>
\$	<i>Br</i> 1,300.70	<i>✓</i>
\$	<i>Br</i> 238.30	<i>✓</i>
\$	<i>Br</i> 926.00	<i>✓</i>
\$	<i>Br</i> 110.60	<i>X</i>
\$	<i>Br</i> 97.50	<i>X</i>
\$	<i>Br</i> 13.30	<i>✓</i>
\$	<i>Br</i> 43.50	<i>✓</i>
\$	<i>Br</i> 26.30	<i>✓</i>
\$	<i>Br</i> 594.80	<i>X</i>
\$	<i>Br</i> 76.40	<i>X</i>

TOTAL \$ 4,766.70**25% \$ 1,191.68****\$ 3,575.03****Special Nett**

- 1SET DOOR STICKER TRANSCAB
- 1SET REAR BUMPER CLIP
- 1 REAR BUMPER PROTECTOR
- 1SET REAR BUMPER RETAINER CLIP
- 1 END PANEL TRIM CLIP

\$	<i>Br</i> 100.00	<i>60.00</i>
\$	<i>Br</i> 95.00	<i>X</i>
\$	<i>Br</i> 180.00	<i>X</i>
\$	<i>Br</i> 85.00	<i>X</i>
\$	<i>Br</i> 65.00	<i>X</i>

TOTAL \$ 525.00**TOTAL PARTS \$ 4,100.03****LABOUR**

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ *Br* 380.00 *X*Faster
memory
speedPrecision
touchpadFas
wi• Intel® Celeron® processor N4020
• Intel® UHD Graphics

AAD2012-

Not Authored
Primary By point
83505.55