

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD739L**AAD2012-***Not Authored
C/Ry &*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

16 DEC 2020**SHD739L**

VF1ABL15AUC283200

RENAULT

LATITUDE

11/12/2020

EQ

15/12/2017

PART		LIST	
1	1 BUMPER COVER REAR	\$	Bu 561.70 ✓
2	1 BUMPER LOWER REAR	\$	Net 411.90 ✓
3	1 BUMPER REFLECTOR RH	\$	CM 16.60 ✓
4	1 BUMPER BRACKET CTR REAR	\$	Sm 98.10 X
5	1 BUMPER BRACKET SIDE RH REAR	\$	Dir 82.10 ✓
6	1 BUMPER RETAINER RH REAR	\$	Dir 59.80 ✓
7	1 BUMPER BRACKET SIDE LH REAR	\$	Sm 80.80 X
8	1 BUMPER RETAINER LH REAR	\$	Sm 54.20 X
9	1 ABSORBER REAR	\$	Sm 217.30 X
10	1 BUMPER BEAM REAR	\$	7 547.80 7
11	1 BUMPER BEAM BRACKET LH REAR	\$	N 114.50 X
12	1 BUMPER BEAM BRACKET RH REAR	\$	N 114.50 X
13	1 OUTER PANEL REAR (End Panel)	\$	N 745.80 X
14	1 OUTER PANEL REAR (End Panel)TRIM	\$	Sm 404.56 X
15	1 FENDER PANEL REAR RH	\$	Bu 1,933.20 ✓
16	1 WHEELARCH REAR RH	\$	Sm 275.40 X
17	1 TAILLAMP RH	\$	CM 401.40 ✓
18	1 EXHAUST CAP REAR	\$	Sm 125.40 X
19	1 BUMPER COVER FRT	\$	Bu 747.20 ✓
20	1 BUMPER BRACKET KIT FRT LH	\$	Sm 101.40 X
21	1 BUMPER RETAINER FRT LH	\$	Sm 101.40 X
22	1 BUMPER BRACKET KIT FRT RH	\$	Sm 101.40 X
23	1 BUMPER RETAINER FRT RH	\$	Sm 101.40 X
24	1 RADIATOR GRILLE	\$	7 969.90 7
25	1 RADIATOR GRILLE BADGE 'RENAULT'	\$	7 225.36 7
26	1 RADIATOR GRILLE FRAME	\$	CM 686.00 ✓
27	1 FRAME FULL SUPPORT PANEL	\$	7 592.70 7
		\$	9,871.82

Trans-cab Auto Services Pte Ltd

AAD2012-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD739L

10%	\$	987.18
	\$	<u>8,884.64</u>

Special Nett

1 1SET PARKING AID	\$	700.00	400.00
2 1SET FENDER CLIP	\$	65.00	X
3 1SET FENDER LINER CLIP	\$	60.00	X
4 1SET REAR BUMPER CLIP	\$	66.00	✓
5 1SET BUMPER BRACKET CTR CLIP	\$	33.00	X
6 1SET BUMPER BRACKET SIDE CLIP RH RR	\$	10.00	X
7 1SET BUMPER RETAINER RH CLIP RR	\$	20.00	X
8 1SET BUMPER BRACKET SIDE CLIP LH RR	\$	10.00	X
9 1SET BUMPER RETAINER CLIP LH RR	\$	20.00	X
10 1SET BUMPER LOWER REAR CLIP	\$	66.00	✓
11 1 EXHAUST MOUNTING REAR	\$	17.82	X
12 1 BUMPER CLIP FRT	\$	85.00	66.00
13 1 BUMPER RETAINER CLIP FRT	\$	70.00	X
14 1 BUMPER GRILLE LOWER CLIP	\$	70.00	X
15 1 LICENSE PLATE WITH HOLDER FRT	\$	120.00	45.00
16 2 WINDSCREEN SEALANT	\$	150.00	40.00
17 1 WINDSCREEN MOULDING	\$	200.00	X
18 1 WINDSCREEN INNER SPONGE SEAL	\$	130.00	30.00
TOTAL	\$	1,412.82	
TOTAL PARTS	\$	<u>10,297.46</u>	

LABOUR

To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.	\$	300.00	120.00
Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	880.00
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00	900.00
To Rust-Proofing Of The Affected Areas.	\$	170.00	30.00

Trans-cab Auto Services Pte Ltd

AAD2012-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD739L

To reinstall rear bumper parking sensor.	\$	170.00	601
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	nn 170.00	X
To repair and realign rear exhaust pipe.	\$	4 170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	L 170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00	X
To check steering geometry and computer wheel alignment	\$	220.00	X
To Check Electrical Lighting Concerned.	\$	170.00	901

TOTAL \$ 7,580.00**Over All Total \$ 26,762.09**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

(LUMP SUM)**Repair Days****10 DAYS****7 days**