

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No.: 6287 6666 Fax No.: 6257 1330

CO./GST Reg. No. 201019626G

SHD739L**AAD2012-***Not Authoised**648p 8**1-B1*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

16 DEC 2020**SHD739L****VF1ABL15AUC283200****RENAULT****LATITUDE****11/12/2020****EQ****15/12/2017**

PART		LIST	
1	1 BUMPER COVER REAR	\$	<i>Bu</i> 561.70 ✓
2	1 BUMPER LOWER REAR	\$	<i>bu</i> 411.90 ✓
3	1 BUMPER REFLECTOR RH	\$	<i>CM</i> 16.60 ✓
4	1 BUMPER BRACKET CTR REAR	\$	<i>bu</i> 98.10 X
5	1 BUMPER BRACKET SIDE RH REAR	\$	<i>bu</i> 82.10 ✓
6	1 BUMPER RETAINER RH REAR	\$	<i>bu</i> 59.80 ✓
7	1 BUMPER BRACKET SIDE LH REAR	\$	<i>bu</i> 80.80 X
8	1 BUMPER RETAINER LH REAR	\$	<i>bu</i> 54.20 X
9	1 ABSORBER REAR	\$	<i>bu</i> 217.30 X
10	1 BUMPER BEAM REAR	\$	<i>R</i> 547.80 X
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>R</i> 114.50 X
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>R</i> 114.50 X
13	1 OUTER PANEL REAR (End Panel)	\$	<i>R</i> 745.80 X
14	1 OUTER PANEL REAR (End Panel)TRIM	\$	<i>bu</i> 404.56 X
15	1 FENDER PANEL REAR RH	\$	<i>Bu</i> 1,933.20 ✓
16	1 WHEELARCH REAR RH	\$	<i>bu</i> 275.40 X
17	1 TAILLAMP RH	\$	<i>CM</i> 401.40 ✓
18	1 EXHAUST CAP REAR	\$	<i>bu</i> 125.40 X
19	1 BUMPER COVER FRT	\$	<i>Bu</i> 747.20 ✓
20	1 BUMPER BRACKET KIT FRT LH	\$	<i>bu</i> 101.40 X
21	1 BUMPER RETAINER FRT LH	\$	<i>bu</i> 101.40 X
22	1 BUMPER BRACKET KIT FRT RH	\$	<i>bu</i> 101.40 X
23	1 BUMPER RETAINER FRT RH	\$	<i>bu</i> 101.40 X
24	1 RADIATOR GRILLE	\$	<i>mgent</i> 969.90 ✓
25	1 RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>bu</i> 225.36 ✓
26	1 RADIATOR GRILLE FRAME	\$	<i>CM</i> 686.00 ✓
27	1 FRAME FULL SUPPORT PANEL	\$	<i>JUC</i> 592.70 X
		\$	9,871.82

Trans-cab Auto Services Pte Ltd

AAD2012-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD739L

10%	\$	987.18
	\$	<u>8,884.64</u>

Special Nett

1 1SET PARKING AID	\$	<i>nd</i> 700.00 <i>400.00</i>
2 1SET FENDER CLIP	\$	<i>na</i> 65.00 <i>X</i>
3 1SET FENDER LINER CLIP	\$	<i>na</i> 60.00 <i>X</i>
4 1SET REAR BUMPER CLIP	\$	<i>na</i> 66.00 <i>✓</i>
5 1SET BUMPER BRACKET CTR CLIP	\$	<i>na</i> 33.00 <i>X</i>
6 1SET BUMPER BRACKET SIDE CLIP RH RR	\$	<i>na</i> 10.00 <i>X</i>
7 1SET BUMPER RETAINER RH CLIP RR	\$	<i>na</i> 20.00 <i>X</i>
8 1SET BUMPER BRACKET SIDE CLIP LH RR	\$	<i>na</i> 10.00 <i>X</i>
9 1SET BUMPER RETAINER CLIP LH RR	\$	<i>na</i> 20.00 <i>X</i>
10 1SET BUMPER LOWER REAR CLIP	\$	<i>na</i> 66.00 <i>✓</i>
11 1 EXHAUST MOUNTING REAR	\$	<i>na</i> 17.82 <i>X</i>
12 1 BUMPER CLIP FRT	\$	<i>na</i> 85.00 <i>66.00</i>
13 1 BUMPER RETAINER CLIP FRT	\$	<i>na</i> 70.00 <i>X</i>
14 1 BUMPER GRILLE LOWER CLIP	\$	<i>na</i> 70.00 <i>X</i>
15 1 LICENSE PLATE WITH HOLDER FRT	\$	<i>na</i> 120.00 <i>45.00</i>
16 2 WINDSCREEN SEALANT	\$	<i>na</i> 150.00 <i>40.00</i>
17 1 WINDSCREEN MOULDING	\$	<i>na</i> 200.00 <i>X</i>
18 1 WINDSCREEN INNER SPONGE SEAL	\$	<i>na</i> 130.00 <i>30.00</i>
TOTAL	\$	1,412.82
TOTAL PARTS	\$	<u>10,297.46</u>

LABOUR

To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.	\$	300.00 <i>120.00</i>
Putty And Spray Painting Of The Affected Portion.	\$	3,000.00 <i>880.00</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00 <i>900.00</i>
To Rust-Proofing Of The Affected Areas.	\$	170.00 <i>30.00</i>

Trans-cab Auto Services Pte Ltd

AAD2012-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD739L

To reinstall rear bumper parking sensor.	\$	170.00	601
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	nn 170.00	X
To repair and realign rear exhaust pipe.	\$	4 170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	4 170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00	X
To check steering geometry and computer wheel alignment	\$	220.00	X
To Check Electrical Lighting Concerned.	\$	170.00	901

TOTAL \$ 7,580.00**Over All Total \$ 26,762.09****28,416.11**

(LUMP SUM)
Repair Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

10 DAYS**7 days**