

08/11/13) wef

ASS REC BY: Marcus

REF:

CS/CT/20014025/4+f3

ASSIGNMENT

From:

Date:

Veh No:

SLD9654R

Yr Regn:

1/7 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLD9654R

Make:

Toyota Sienta

c.c

1496

Colour

Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

64078

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

NSP/707010971

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/60R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

h. fly

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

10/12/20

D.O.I.

17/12/20

Survey held at


Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

\$49k.

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

5

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

1987

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time

Action / Instruction

LTA 33923

29/12/20 2/3 \$4600 Confirmed with chris. (Red: 11907.58 : 72%)

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

5

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

) \$ + RS \$ SI

) Photos

) Others

)

TOTAL

Report Format :

Lump Sum / I.B.I. (\$))

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	199F
Vehicle Details	
Vehicle No.:	SLD9654R
Vehicle to be Exported:	No
Intended Deregistration Date:	17 Dec 2020
Vehicle Make:	TOYOTA
Vehicle Model:	SIENTA 1.5G CVT ABS D/AIRBAG 2WD 5DR
Primary Colour:	Silver
Manufacturing Year:	2015
Engine No.:	2NR8545182
Chassis No.:	NSP1707010971
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$20,375.00
Original Registration Date:	01 Jul 2016
First Registration Date:	01 Jul 2016
Transfer Count:	0
Actual ARF Paid:	\$10,525.00 5262
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Jun 2026
PARF Rebate Amount:	\$7,893.00
Intended COE Rebate Details	
COE Expiry Date:	30 Jun 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$47,020.00
COE Rebate Amount:	\$26,030.00
Total Rebate Amount:	\$33,923.00

The information contained herein is correct as at 17 Dec 2020

OK

U/S \$4600

2.4kg/10.1kg After Not Affected
Rep.

17/12/20
U/S \$4600

5 days



1st Auto Pro Pte Ltd

We Believe In Service

8 KAKI BUKIT AVENUE 4 PREMIER @ KAKI BUKIT #01-49 & #01-51/52 SINGAPORE 415875

Tel : 9188 3197 / 8614 6767 | Email: christina@1ap.com.sg

ESTIMATION QUOTE

CHINA TAIPING INSURANCE (SG) PTE LTD

3 ANSON ROAD #15-00

SPRINGLEAF TOWER

SINGAPORE 79909

ATTN: MOTOR CLAIMS DEPARTMENT

VEHICLE NO : SLD9654R

MAKE MODEL : TOYOTA SIENTA

REFERENCE : 1AP-202012-27

DOA : 10-Dec-20

CLAIM TYPE : TP CLAIM

PAGE 1 OF 2

LIST ITEMS	QTY	LIST PRICE (\$)	REMARKS
*REAR BUMPER	1	\$ 1,380.50	645.10 ✓
*REAR BUMPER CENTRE GARNISH	1	\$ 498.60	245.10 ✓
*REAR BUMPER LOWER BRACKET LH / RH	2	\$ 231.60	X
*REAR BUMPER SIDE RETAINER LH / RH	2	\$ 520.00	X
*REAR BUMPER REFLECTOR LH / RH	2	\$ 560.00	X
*REAR END PANEL	1	\$ 922.80	522.10 ✓
*REAR END PANEL INNER GARNISH	1	\$ 312.60	165.80 ✓
*REAR PANEL LOCK CATCH LOWER	1	\$ 152.20	X
*REAR BOOT	1	\$ 2,065.00	1281.20 ✓
*REAR BOOT HINGE LH / RH	2	\$ 436.00	X
*REAR BOOT COVER RUBBER MOULDING	1	\$ 180.00	145.80 ✓
*REAR BOOT LOCK UPPER	1	\$ 335.60	✓
*REAR BOOT OUTER GARNISH CENTRE	1	\$ 289.60	X
*REAR BOOT LAMP LH / RH	2	\$ 1,045.80	X
*REAR BOOT INNER TRIM	1	\$ 481.00	241.10 ✓
*REAR BOOT LOGO	1	\$ 180.00	58.10 ✓
*REAR BOOT INNER TRIM BOARD O/S	1	\$ 486.20	✓
*REAR BOOT STOPPER	1	\$ 194.40	X
*REAR TAIL LAMP LH / RH	2	\$ 1,451.80	X
*REAR TAIL LAMP SIDE PANEL LH / RH	2	\$ 678.40	X
*REAR FENDER INNER SHIELD LH / RH	2	\$ 539.00	X
*SPARE WHEEL CARRIER	1	\$ 560.00	X
*REAR EXHAUST SILENCER	1	\$ 925.00	X
*REAR EXHAUST MOUNTING	1	\$ 184.00	X

\$ 14,610.10

LESS 25% \$ 3,652.53

SUBTOTAL \$ 10,957.58

BALANCE C/F \$ 10,957.58

SPECIAL NETT ITEMS	QTY	LIST PRICE (\$)	REMARKS
--------------------	-----	-----------------	---------

BALANCE B/F \$ 10,957.58

REAR NUMBER PLATE WITH GARNISH	1	\$ 100.00	40
REAR BUMPER CLIPS	1	\$ 50.00	✓
REVERSE CAMERA	1 SET	\$ 300.00	✓

Reer

ESTIMATION QUOTE

CHINA TAIPING INSURANCE (SG) PTE LTD
3 ANSON ROAD #15-00
SPRINGLEAF TOWER
SINGAPORE 79909
ATTN: MOTOR CLAIMS DEPARTMENT

VEHICLE NO : SLD9654R
MAKE MODEL : TOYOTA SIENTA
REFERENCE : 1AP-202012-27
DOA : 10-Dec-20
CLAIM TYPE : TP CLAIM

PAGE 2 OF 2

SPECIAL NETT ITEMS	QTY	LIST PRICE (\$)	REMARKS
REAR BUMPER SENSOR <i>shurd</i>	1 SET	\$ 200.00	✓
REAR WINDSCREEN MOULDING <i>seelent ner</i>	1	\$ 100.00	40

SUBTOTAL \$ 750.00

BALANCE C/F \$ 11,707.58

LABOUR	S/NO	LIST PRICE (\$)	REMARKS
--------	------	-----------------	---------

BALANCE B/F \$ 11,707.58

TO REMOVE, REFIT AND TRANSFER REAR BOOT COMPONENT	1	\$ 250.00	60
TO REMOVE AND REFIT ELECTRICAL WIRING, REPLACE DAMAGED LAMPS AND TEST FOR PROPER FUNCTIONING - REAR	2	\$ 250.00	20
TO REMOVE AND REFIT INNER TRIMS AND GARNISHES TO FACILITATE THE REPAIR	3	\$ 250.00	80
TO REMOVE AND REFIT REAR BUMPER SENSOR	4	\$ 100.00	50
TO REMOVE AND REFIT, STRAIGHTEN AND RE-ADJUST EXHAUST PIPE AND REPLACE REAR EXHAUST SILENCER AND MOUNTING	5	\$ 350.00	4X
TO APPLY UNDERCOATING ON REPLACED AND REPAIRED PANELS FOR RUST PROTECTION	6	\$ 100.00	60
TO PROVIDE SPRAY PAINTING ON THE REPLACED AND REPAIRED PARTS	7	\$ 2,000.00	1000
TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS. TO RE-ADJUST TO ORIGINAL POSITION USING POWER TOOLS	8	\$ 1,500.00	800

SUBTOTAL \$ 4,800.00

GRAND TOTAL \$ 16,507.58

KK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P- 4126.10
252
P- 3094.57
S.N- 630.00
L- 2070
5794.57