

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG20014031/KQD3E2

Date: 11/03/2021

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29141713MKF
Claimant Vehicle No :	SMG9915K	Insured Vehicle No :	SLH1903D
Date of Loss:	15/12/2020	Nature of Claim:	TP
		Claim No:	632079

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMG9915K	Engine No:	3A92UHL9375
Make & Model:	MITSUBISHI ATTRAGE, 1.2 CVT (A)	Chassis No:	MMBSTA13AKH000651
Reg. Date:	08/01/2019 (Man. Year: 2018)	Odometer:	39431 km
Colour:	Metallic Red		
Engine Capacity:	1193 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/55 R15	Rear Tyre Size:	185/55 R15
Front Left Side:	Sumitomo 8 mm	Rear Left Side:	Sumitomo 8 mm
Front Right Side:	Sumitomo 8 mm	Rear Right Side:	Sumitomo 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,217.60	3,867.20	1,350.40	25.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,010.00	2,240.00	770.00	25.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,227.60	6,107.20	2,120.40	25.77
+ GST 7.00/7.00% (S\$)	575.93	427.50	148.43	25.77
Nett Amount (S\$)	8,803.53	6,534.70	2,268.83	25.77

INSPECTION

Date of Assignment:	17/12/2020	
Date Inspected:	17/12/2020	Inspected At: Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A Singapore 768761
Estimated Period of Repair:	9.0 days	

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 11 Mar 2021)	
Parts:	N/A	mitsubishi attrage 1.2 cvt (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMG9915K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	748.00 FL	*748.00 FL
2	1		*REAR BUMPER RH SIDE RETAINER	Distorted	29.00 FL	*29.00 FL
3	1		*REAR BUMPER RH SIDE MUD GUARD	Serviceable	49.00 FL	*- FL
4	5		*REAR BUMPER CLIPS	Necessary	20.00 FL	*20.00 FL
5	1		*BOOTLID	Bent	791.00 FL	*791.00 FL
6	1		*REAR BOOTLID INNER LOCK	Dented	206.00 FL	*206.00 FL
7	1		*REAR BOOTLID INNER RUBBER	Distorted / Dented	157.00 FL	*157.00 FL
8	1		*REAR BOOTLID LOGO	Necessary	69.00 FL	*69.00 FL
9	1		*REAR BOOTLID EMBLEM (ATTRAGE)	Necessary	45.00 FL	*11.00 FL
10	2		*TAILLAMPS	N/S Cut O/S Mtg Cracked	670.00 FL	*670.00 FL
11	1		*RH PANEL	Repair	67.00 FL	*- FL
12	1		*RH PANEL CLIP	Necessary	6.00 FL	*6.00 FL
13	1		*REAR END PANEL	Repair	425.00 FL	*- FL
14	1		*REAR END PANEL INNER TOP GARNISH	Dented	72.00 FL	*66.00 FL
15	2		*REAR END PANEL INNER TOP GARNISH CLIPS	Necessary	10.00 FL	*10.00 FL
16	1		*REAR SPARE TYRE PANEL TOP BOARD	Cracked	195.00 FL	*195.00 FL
17	1		*REAR RH FENDER	Repair	755.00 FL	*- FL
18	1		*REAR BUMPER LOWER SKIRT	Cracked	980.00 F	*980.00 FN
19	1		*SET REVERSE SENSORS	Shorted	200.00 FS	*200.00 FS
20	1		*REAR BOOTLID EMBLEM (MIVEC)	Necessary	35.00 FS	*35.00 FS
21	1		*REAR END PANEL SEALANT	Necessary	40.00 FS	*30.00 FS
22	1		*REAR WINDSCREEN GLASS GUM	Not Necessary	40.00 FS	*- FS
23	1		*C&C LOGO	Necessary	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (\$\$)	5,649.00	4,263.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	431.40	297.80
- Nett Item Discount on N Items 0.00/10.00% (\$\$)	0.00	98.00

Total Parts (\$\$) 5,217.60 3,867.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING	New	50.00	50.00
2	REMOVE & REFIX REAR BUMPER, LOWER SKIRT & ATTACHMENT, BOOTLID, SPOILER & ATTACHMENTS, TAILLAMPS, CUT, WELD & RENEW REAR END PANEL, RH TAILLAMP PANEL, REAR RH FENDER, KNOCK & REPAIR REAR SPARE TYRE PANEL & REALIGN THE SAME	New	1,300.00	980.00
3	PUTTY & RESPRAY REAR BUMPER, LOWER SKIRT, BOOTLID & SPOILER, REAR FENDERS, REAR END PANEL, REAR SPARE TYRE PANEL & ALL AFFECTED AREAS	New	1,300.00	1,000.00
4	REMOVE & REFIX REVERSE CAMERA, RESET & POSITION	New	50.00	50.00
5	RUSTPROOFING	New	90.00	60.00
6	REMOVE AND REFIX REAR WINDSCREEN GLASS	New	100.00	0.00
7	REMOVE & REFIX SEAT, CARPET, TOP ROOF LINING, GARNISH, ETC	New	120.00	100.00
Gross Labour Cost (S\$)			3,010.00	2,240.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >