

MBM WHEELPOWER PTE. LTD.

YOUR REF.: SMW1939K

OUR REF.: SDA6337L

TO: CHINA TAIPING INSURANCE

CC: MOTOR CLAIMS DEPARTMENT

FAX:

ESTIMATE FOR VEHICLE NO.: SDA6337L



DATE: 16/12/2020
FROM: Lee Shirley
FAX: 64525333
CONTACT: 86865188
MAKE & MODEL: BMW 740Li AT SR LED DSC NAV HUD
CHASSIS NO.: WBAYE42050DD87288
ENGINE NO.: 10778424N55B30A
YEAR MADE: 2013
ACCIDENT DATE: 15 December 2020

NO.	DESCRIPTION	PART NO.	QTY.	LIST PRICE
1	BONNET X		1	\$ 3,200.00 X
2	BONNET FRONT SEAL X		1	\$ 97.00 X
3	BONNET WEATHERSTRIP X		1	\$ 50.00 X
4	BONNET BMW LOGO X		1	\$ 130.00 X
5	FRONT BUMPER ✓ 1500.00		1	\$ 1,980.00 ✓
6	FRONT BUMPER TOWING COVER ✓ 35.00		1	\$ 65.00 ✓
7	FRONT BUMPER LOWER SPOILER ?		1	\$ 100.00 ?
8	FRONT BUMPER LICENSE PLATE ✓		1	\$ 110.00 ✓
9	FRONT BUMPER RUBBER STRIP LH ?		1	\$ 145.00 ?
10	FRONT BUMPER RUBBER STRIP RH ?		1	\$ 145.00 ?
11	FRONT BUMPER SENSOR ✓ 260		1	\$ 460.00 ✓
12	FRONT BUMPER CLIP ✓		10	\$ 100.00 ✓
13	FRONT BUMPER SPONGE ?		1	\$ 130.00 ?
14	FRONT BUMPER REINFORCEMENT ?		1	\$ 900.00 ?
15	FRONT BUMPER LOWER CENTER GRILLE ✓		1	\$ 90.00 ✓
16	FRONT BUMPER SIDE GRILLE LH X		1	\$ 90.00 X
17	FRONT BUMPER SIDE GRILLE RH ✓		1	\$ 90.00 ✓
18	FRONT GRILLE LH ✓ 165		1	\$ 200.00 ✓
19	FRONT GRILLE RH ✓ 165		1	\$ 200.00 ✓
20	FOG LAMP LH X		1	\$ 300.00 X
21	FOG LAMP RH ?		1	\$ 300.00 ?
22	HEADLAMP LH X		1	\$ 6,500.00 X
23	HEADLAMP RH P.A. 5250.00		1	\$ 6,500.00 ✓
24	FRONT FENDER LH X		1	\$ 1,220.00 X
25	FRONT FENDER INNER SHIELD LH X		1	\$ 200.00 X
26	FRONT FENDER RH X		1	\$ 1,220.00 X
27	FRONT FENDER INNER SHIELD RH X		1	\$ 200.00 X

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

MBM WHEELPOWER PTE. LTD.
160 SIN MING DRIVE, #06-02
SIN MING AUTOCITY
t 6282 8888 f 6452 5333
COMPANY REG. NO.: 200204110W

28

FRONT FENDER INNER SHIELD CLIP X

20	\$	<i>nn</i> 200.00 X
TOTAL:	\$	24,922.00
LESS 10%:	\$	(2,492.20)
PARTS TOTAL:	\$	22,429.80

SPECIAL NETT

FRONT NUMBER PLATE & HOLDER

BODY SEALANT ON BONNET

1	\$	<i>nn</i> 45.00
1	\$	<i>nn</i> 50.00 X

LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS, INCLUDING TO KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS

TO REMOVE, REFIT & UPHOLSTERY TO FACILITATE REPAIRS

TO CHECK & RECONNECT ALL NECESSARY WIRING

TO REMOVE & REFIT ALL SENSOR

TO RESET ENGINE WARNING LIGHT (ABS, SRS, ECU MEMORY & ETC)

TO SPRAY PAINT ON THE AFFECTED AREAS

	\$	<i>500</i> 1,800.00
	\$	<i>nn</i> 100.00 X
	\$	<i>30</i> 150.00
	\$	<i>60</i> 100.00
	\$	<i>100</i> 150.00
	\$	<i>500</i> 1,600.00
TOTAL:	\$	26,479.80
7% GST:	\$	1,853.59
GRAND TOTAL:	\$	28,333.39