



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2102696
INV Date 16/04/2021
Reference CC6/LPC20014040/Kpa3q2
Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SMJ 3029S
Insured Veh. YM 9180P
Claim No. 20/20/20/VC00/023590
Policy No. Z/20/VC00/107440
Accident Date 26/08/2020
Inspection Date 14/12/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

300 BEACH ROAD

#17-04/07 THE CONCOURSESINGAPORE 199555

Ref: CC6/LPC20014040/Kpa3q2

Date: 16/04/2021

Code: LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YM 9180P	Veh. Inspected	SMJ 3029S
Policy No.	Z/20/VC00/107440	Coverage (\$)	0.00
Claim No.	20/20/20/VC00/023590	Excess (\$)	0.00
Assign From		Assign Date	14/12/2020

2. Vehicle Particulars & Condition

Make & Model	HONDA SHUTTLE (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	GP72003063	Colour	METALLIC GREY
Odometer	191170 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/55 R15	BRIDGESTONE	8 mm
L/H Front Tyre	195/55 R15	BRIDGESTONE	8 mm
R/H Rear Tyre	195/55 R15	BRIDGESTONE	8 mm
L/H Rear Tyre	195/55 R15	BRIDGESTONE	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S DOOR HANDLE.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	26/08/2020	Inspection Date	14/12/2020
Survey held at	MBM WHEELPOWER PTE LTD 176 SIN MING DRIVE #01-15 SIN MING AUTOCARE SINGAPORE 575721		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **1 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMJ 3029S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	LH FRONT DOOR GLASS	SERVICEABLE	1,000.00	-
1	LH FRONT DOOR GLASS MOULDING	SERVICEABLE	150.00	-
1	LH FRONT DOOR	TO REPAIR SEE LABOUR	1,000.00	-
1	LH FRONT DOOR SEAL FRONT	NOT NECESSARY	60.00	-
1	LH FRONT DOOR SEAL LOWER	NOT NECESSARY	60.00	-
1	LH FRONT DOOR WEATHERSTRIP	SERVICEABLE	100.00	-
1	LH FRONT DOOR HANDLE	TO REPAIR SEE LABOUR	600.00	-
1	LH FRONT DOOR UPPER HINGE	TO REPAIR SEE LABOUR	80.00	-
1	LH FRONT DOOR LOWER HINGE	TO REPAIR SEE LABOUR	80.00	-
	LESS 20% DISCOUNT		-626.00	-
			2,504.00	-
<u>SPECIAL NETT ITEMS</u>				
1	BODY SEALANT (SN)	NOT NECESSARY	80.00	-
			80.00	-
<u>LABOUR</u>				
	TO REMOVE,REFIT & REPAIR AFFECTED DAMAGED PARTS.	NOT NECESSARY	600.00	-
	TO CHECK & RECONNECT ALL NECESSARY WIRING.	NOT NECESSARY	50.00	-
	TO DISMANTLE & TRANSFER DOOR FITTINGS & MECHANISM TO NEW DOOR/FACILIAATE REPAIR.	NOT NECESSARY	100.00	-
	TO RESET ENGINE WARNING LIGHT (ABS.SRS.ECU MEMORY & ETC).	NOT NECESSARY	200.00	-
	TO SPRAY PAINT ON THE AFFECTED AREAS.		600.00	60.00
			1,550.00	60.00
GRAND TOTAL			4,134.00	60.00



RECOMMENDED COST OF REPAIRS			60.00
------------------------------------	--	--	--------------

Report Ref No. CC6/LPC20014040/Kpa3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMJ 3029S

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

