


MBM WHEELPOWER PTE. LTD.



YOUR REF.: YM9180P

OUR REF.: SMJ3029S

TO: Lonpac Insurance Bhd

CC: MOTOR CLAIMS DEPARTMENT

FAX:

*Not Authorized
Remy Abu Palm
1 day*

DATE: 29/9/2020
 FROM: Lee Shirley
 FAX: 6452 5333
 CONTACT: 8686 5188
 MAKE & MODEL: HONDA SHUTTLE 1.5 (A)
 CHASSIS NO.: GP72003063
 ENGINE NO.: LEB7104040
 YEAR MADE: 2019
 ACCIDENT DATE: 26 August 2020

FINALISE FOR VEHICLE NO.: SMJ3029S

NO.	DESCRIPTION	PART NO.	QTY.	LIST PRICE
1	LH FRONT DOOR GLASS		1	\$ 1,000.00 X
2	LH FRONT DOOR GLASS MOULDING		1	\$ 150.00 X
3	LH FRONT DOOR		1	\$ 1,000.00 X
4	LH FRONT DOOR SEAL FRONT		1	\$ 60.00 X
5	LH FRONT DOOR SEAL LOWER		1	\$ 60.00 X
6	LH FRONT DOOR WEATHERSTRIP		1	\$ 100.00 X
7	LH FRONT DOOR HANDLE		1	\$ 600.00 X
8	LH FRONT DOOR UPPER HINGE		1	\$ 80.00 X
9	LH FRONT DOOR LOWER HINGE		1	\$ 80.00 X
TOTAL:				\$ 3,130.00
LESS 20%:				\$ (626.00)
PARTS TOTAL:				\$ 2,504.00

SPECIAL NETT
BODY SEALANT

1 \$ 80.00 X

LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS \$ 600.00 X
 TO CHECK & RECONNECT ALL NECESSARY WIRING \$ 50.00 X
 TO DISMANTLE & TRANSFER DOOR FITTINGS & MECHANISM TO NEW DOOR / FACILITATE REPAIR \$ 100.00 X
 TO RESET ENGINE WARNING LIGHT (ABS, SRS, ECU MEMORY & ETC) \$ 200.00 X
 TO SPRAY PAINT ON THE AFFECTED AREAS \$ 600.00

TOTAL: \$ 4,134.00
 7% GST: \$ 289.38
GRAND TOTAL: \$ 4,423.38

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

MBM WHEELPOWER PTE. LTD.
 160 SIN MING DRIVE, #06-02
 SIN MING AUTOCITY
 T 6262 8888 F 6452 5333
 COMPANY REG. NO.: 200204110W