

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0974/2020/NS
DATE : 14-Dec-20
WIP : 62420

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MS LAU PUAY CHENG
ADDRESS : 54 SELETAR HILLS DRIVE
SINGAPORE 807069
TELEPHONE : HP +65 96201169
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO :
VEHICLE NO : **SBQ 100 G**
MODEL CODE : AUDI Q7 2.0 TFSI QU
MODEL YEAR : 16/8/2019
ENGINE NO : CYR 074740
CHASSIS NO : WAUZZZ4M1KD003299
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 11-Dec-20
PLACE OF ACCIDENT : CARPARK IN FRONT OH HSBC BANK

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SBQ 100 G

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE.	S/N \$ 360.00	
2	TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,350.00	
3	TO RESPRAY REAR BUMPER.	\$ 1,350.00	
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	
TOTAL LABOUR CHARGES		: \$ 3,252.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SBQ 100 G

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
1 REAR UPPER BUMPER		\$ 1,215.00	
2 REAR LOWER BUMPER		\$ 1,681.00	
3 REAR BUMPER FIXING PARTS		\$ 205.00	
4 REAR BUMPER SPOILER		\$ 1,247.00	
5 REAR BUMPER SPOILER TRIM		\$ 105.00	
6 REAR BUMPER CARRIER		\$ 1,341.00	
7 REAR BUMPER CARRIER SEAL - LH/RH	2	\$ 28.00	
8 REAR BUMPER HOLDING STRAP		\$ 180.00	
9 REAR BUMPER GUIDE SECTION - CENTRE		\$ 140.00	
10 REAR PARKING AID SENSOR - INNER/OUTER	2	\$ 484.00	
11 REAR PARKING AID SEAL RING	4	\$ 14.00	
12 TAIL LIGHT - RH		\$ 355.00	
13 REAR WHEEL COVER - LH/RH	2	\$ 388.00	
14 EXHAUST TAIL PIPE TRIM - RH		\$ 325.00	
15 SUNDRIES		\$ 200.00	
TOTAL SPARE PARTS	:	\$ 7,908.00	
TOTAL LABOUR CHARGES	:	\$ 3,252.00	
GRAND TOTAL	:	\$ 11,160.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT