

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SMW7224A**LAD2012-002***Not Authorized
Reservy B4 pain*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

15 DEC 2020**SMW7224A**

JTDKB3FU703092009

TOYOTA

PRIUS GEN 4

12/12/2020

TOKIO

03/12/2020

PART	LIST	
1 COVER, REAR BUMPER	\$ CMT 485.60	✓
1 REINFORCEMENT SUB-ASSY, REAR BUMPER	\$ R 332.70	✓
1 COVER, REAR BUMPER, LOWER	\$ D 22.00	✓
1 GUARD, REAR BUMPER, CENTER	\$ R 374.50	✓
1 REFLECTOR ASSY, REFLEX, RH	\$ CMT 39.00	✓
1 RETAINER, REAR BUMPER SIDE, LH	\$ S 132.60	X
1 FILLER, REAR BUMPER EXTENSION, LH	\$ S 123.70	X
1 RETAINER, REAR BUMPER SIDE, RH	\$ B 132.60	✓
1 SEAL, REAR BUMPER SIDE, LH	\$ S 118.30	} X
1 SEAL, REAR BUMPER SIDE, RH	\$ S 118.30	
1 PANEL SUB-ASSY, QUARTER, RH	\$ R 871.50	
1 PANEL SUB-ASSY, BODY LOWER BACK	\$ R 651.00	
1 LENS & BODY, REAR COMBINATION LAMP, RH	\$ S 339.60	
1 LENS & BODY, REAR COMBINATION LAMP, NO.2 RH	\$ S 261.00	
1 COVER, FLOOR UNDER, NO.1 (LH)	\$ S 175.10	
1 COVER, FLOOR UNDER, NO.2 (RH)	\$ S 241.90	
1 COVER, REAR FLOOR (CTR)	\$ S 229.90	
TOTAL	\$ 3,401.80	
25%	\$ 850.45	
	\$ 2,551.35	

Special Nett

1SET PARKING AID	\$ S 700.00	X
1SET REAR BUMPER CLIP	\$ R 95.00	6050
1 REAR BUMPER PROTECTOR	\$ WSP 180.00	X
1SET REAR BUMPER RETAINER CLIP	\$ R 85.00	X
1 END PANEL TRIM CLIP	\$ R 65.00	X
TOTAL	\$ 1,125.00	

Trans-cab Auto Services Pte Ltd

LAD2012-002

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SMW7224A

TOTAL PARTS \$ 3,676.35**LABOUR**

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ 380.00 601

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 2,200.00 4001

To transfer of rear end panel fittings, attachment and perform water seepage test.

\$ 380.00 X

To transfer of Tailgate fittings, attachments and perform water seepage test.

\$ 180.00 X

To remove and refit electrical wiring, battery and other necessary items to facilitate bodywork repair.

\$ 480.00 X

To transfer of Fender fittings, attachments and perform water seepage test.

\$ 480.00 X

To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.

\$ 380.00 X

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.

\$ 380.00 X

To check steering geometry and computer wheel alignment

\$ 220.00 X

To Rust-Proofing and apply undercoat Of The Affected Areas.

\$ 250.00 X

Towing Fees

\$ 150.00 X

Putty And Spray Painting Of The Affected Portion.

\$ 2,200.00 4401