

C

Fast
mem

Fax : 64816131

Not Notated
C1 Rmp @ 28 days
Recovery After Paint
C1 Rmp @ 30,500 ft

28 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

SIGNMENT

Veh No:

Type:

200140451Kg
SUS 2737C

Yr Reg

2737 C

balance b/f \$12,003.20

C Rear buzzer
 SC Rear fender e 931.00
 CS Rear fender air duct
 CS Rear fender inner panel
 CS Rear fender inner trim board
 CS Rear fender arch protector
 CS Rear fender inner shield
 CS Rear fender inner top garnish
 C Rear o/s fender triangle garnish
 C Rear boot top cover
 C Roof lining
 CS Roof air bag sensor
 C Air bag control unit
 CS Rear door assy e 935.10
 CS Rear door inner lock
 CS Rear door rubber
 C Rear o/s door inner trim board
 C Rear o/s door glass regulator motor
 CS Rear door pillar weatherstrip
 C Rear o/s rocker panel
 C Rear o/s rocker panel garnish
 CS Rear door step garnish
 C Rear spare tyre panel
 C Rear spare tyre tool sponge
 C Rear spare tyre top cover board
 C Rear exhaust silencer
 C Rear axle assy
 CS Rear shock absorber
 CS Rear shock absorber mounting
 CS Rear hub assy
 CS Rear ABS pump
 CS Rear ABS wire sensor
 C Hybrid battery
 C Hybrid battery chrome cover
 C Hybrid battery fan discharge motor
 C Hybrid battery air discharge hose
 C Hybrid battery control unit
 C Hybrid battery tray
 C Fuel tank
 C Fuel tank tube
 C Fuel tank lock
 C Fuel tank outer door cover
 C Fuel pump assy
 S Rear exhaust silencer
 S Rear exhaust silencer hook
 S Rear exhaust silencer heat shield
 S Front o/s shock absorber
 S Front o/s shock absorber mounting

	Sm	\$185.20	X
Ry	\$1,185.90	\$2,371.80	✓
Od/Onit	\$155.10	\$310.20	✓
Al/Ry	\$655.10	\$1,310.20	✓
	\$425.10	\$850.20	✓
nit/cm	\$175.20	\$350.40	✓
	\$105.60	\$211.20	✓
	\$115.20	\$230.40	✓
		\$95.70	✓
	dis	\$355.60	✓
	Return	\$839.60	✓
		\$197.70	✓
Am	\$1,250.70	\$2,501.40	✓
ols Ry		\$935.10	✓
	\$255.60	\$511.20	X
ols cm	\$175.10	\$350.20	✓
	ng/cm	\$620.20	✓
	nit	\$378.20	✓
	\$165.10	\$330.20	✓
	Ry	\$655.50	✓
	cm	\$487.60	✓
	\$75.10	\$150.20	X
	Ry	\$1,255.80	✓
	cm	\$275.60	✓
	nit	\$385.60	✓
	Replaced	\$975.10	X
	Ry	\$1,490.70	✓
	\$385.10	\$770.20	✓
	\$155.10	\$310.20	✓
ols Ry	\$305.30	\$610.60	✓
	\$255.10	\$510.20	X
	\$195.70	\$391.40	X
l-r	Red	\$14,955.00	3500asw
	Red	\$325.70	✓
	Sm	\$750.70	X
	Sm	\$485.10	X
	Sm	\$1,985.20	X
	Sm	\$256.90	X
	Red	\$985.70	✓
	Sm	\$225.10	X
	R	\$187.20	X
	R	\$185.70	X
	Sm	\$633.80	X
	Ry	\$975.60	✓
	\$85.10	\$170.20	✓
	Ry	\$165.20	✓
	Sm	\$550.75	X
	Sm	\$165.20	X
balance c/c		\$56,802.75	

0014045/Kg

IGNMENT

Veh No:

SLS 2737C

Type: M.Cat / M.Cycle / Bus / Van /

Yr Reon:

CO

Aspire 3

DDR4

Faster

Precis touch

SLS 2737 C

balance b/f \$56,802.75

1 pc Front o/s shock absorber linkage
1 pc Front o/s kunckle arm
1 pc Front o/s kunckle bearing
1 pc Front o/s hub assy
1 pc Front o/s ABS sensor
1 pc Front o/s lower arm
1 pc Front o/s driver shaft

Sh \$85.70 X
Ry \$405.70 X
na \$195.20 X
In \$485.70 X
In \$187.20 X
Dis \$425.60 X
R \$955.30 X
\$59,543.15
Less 20 % \$11,908.63
\$47,634.52

S Nett

4 pcs Roof air bag
2 pcs Front & rear o/s tyre rim
3 pcs Tyres
1 pc Rear tail-gate glass sealant
1 pc Rear reverse camera
1 pc Rear reverse sensor
1 pc Sundry expesnes
1 pc Rear no plate
1 pc Rear CCTV

Roof \$955.50 \$3,822.00 ✓
Rear o/s \$450.00 \$900.00 ✓
In \$200.00 \$600.00 80% net
na \$55.00 40%
na \$300.00 ✓
na \$200.00 ✓
na \$60.00 X
na \$40.00 X
na \$450.00 X
\$6,427.00

Labour Charges

Remove/renew the above parts including knocking, welding & cutting.

2400
\$2,800.00

To putty and spray paint

\$2,000.00 1800

Check & reconnect wiring.

\$480.00 1800

To respray anti-rust proofing treatment

\$240.00 2100

Remove/refit rear windscreen to facilitate repair

\$120.00 ✓

Remove/refit rear tail-gate mechanism to new door.

\$150.00 600

Remove/renew rear exhaust silencer.

\$120.00 800

Remove/refit rear boot upholstery to facilitate repair.

\$150.00 1000

Remove/renew rear and rear undercarriages.

\$650.00 2200

Check and realign wheel alignment.

\$80.00 600

Diagnostic check on rear ABS and to reset same.

na \$200.00 X

Remove/renew hybrid battery and to reset factory specification

\$800.00 3600

balance c/f \$61,851.52

20014045/Kg

ASSIGNMENT

Veh No: S2S 2737C
Type: MCB / M.Cycle / R...

C

Aspire 3

DDR4

Faster

SLS 2737-C

balance b/f \$61,851.52

Labour Charges

Remove/repair rear cushion seat frame and leather

\$1,000.00 350

Trolling towing

(Bill) \$150.00 120

Remove/renew roof lining, air bag and to reset same

\$800.00 280

Remove/renew fuel pump and tank etc.

\$320.00 60

Total

\$64,121.52