

ASS. REC. BY:

REF:

C71/20014045/Kg d3

Kenneth

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No. DMHCSNA00004132000

Claims No. SNM20D204697/C02

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

B68k

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

28

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SUS 2737C

Yr Regn:

09, 17

Type: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Vezel

c.c.

1496

Colour:

M. Grey

A/C:

Insured / Std / NI / NA

Sp. Reading:

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

RU3 1253362

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

215/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

12/11/20

D.O.I.

17/12/2020

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S &amp; Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1

Motor Plot

22/12/20 @ 12.09pm revised to Pauline Tham by email.

Kenneth confirmed LS \$30500, 28 days (Red \$33621.52, 52%)

Date/Time, File Pass to?

☐

: Prell. Report

1) 15/06 Typist

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

28

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

S - RS, SI

Fees

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

TOTAL

Report Format: MER-TP

Lump Sum / B.B. (\$ 30500

# Lian Her Motors

Blk 503B #01-405 Ang Mo Kio Industrial Pk 2 Singapore 569641  
Tel : 64817221

Fax : 64816131

China Taiping Insurance ( Singapore ) Pte Ltd  
3 Anson Road #15-00  
Springleaf Tower  
Singapore 079909

*Not Notified*  
*6/10/17*  
*Repair After Paint*

*28 days*

Vehicle No : SLS 2737 C  
Make/Model : Honda Vezel 1.5 X Hybrid  
Year : 2017

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

## Estimate Cost Of Repair

1 pc	Rear tail-gate assy	<i>By Shorten</i>	\$1,350.60	✓
1 pc	Rear tail-gate glass		\$1,256.30	✓
2 pcs	Rear tail-gate side garnish	\$107.10 <i>mit</i>	\$214.20	✓
1 pc	Rear tail-gate glass centre garnish	<i>mit</i>	\$155.60	✓
1 pc	Rear tail-gate glass moulding	<i>mit</i>	\$105.20	✓
1 pc	Rear tail-gate top spoiler	<i>mit</i>	\$475.10	✓
1 pc	Rear third brake light	<i>mit</i>	\$205.10	✓
1 pc	Rear tail-gate outer garnish	<i>CMT</i>	\$385.60	✓
2 pcs	Rear tail-gate hinge	\$65.10	\$130.20	✓
2 pcs	Rear tail-gate damper	<i>Al/mt</i> \$105.10	\$210.20	✓
1 pc	Rear wiper motor	<i>in</i>	\$425.10	X
1 pc	Rear wiper arm	<i>in</i>	\$155.60	X
1 pc	Rear tail-gate emblem "H"	<i>in</i>	\$45.10	✓
1 pc	Rear tail-gate emblem : Vezel "	<i>in</i>	\$50.20	✓
1 pc	Rear tail-gate outer garnish	<i>CMT</i>	\$385.60	✓
1 pc	Rear tail-gate inner lock	<i>in</i>	\$285.60	✓
1 pc	Rear tail-gate inner trim board	<i>CMT</i>	\$455.90	✓
2 pcs	Rear tail-gate lamp assy	\$425.30 <i>CMT</i>	\$850.60	✓
2 pcs	Rear no plate lamp	\$65.10	\$130.20	✓
2 pcs	Rear tail-lamp assy	<i>Ar</i> \$855.90	\$1,711.80	✓
1 pc	Rear boor rubber	<i>in</i>	\$225.80	<i>502m</i>
1 pc	Rear end panel	<i>By</i>	\$455.10	✓
1 pc	Rear end panel inner garnish	<i>in</i>	\$185.90	✓
1 pc	Rear bumper	<i>mt</i>	\$955.60	✓
2 pcs	Rear side bumper	<i>Al/mt</i> <i>clmt</i>	\$335.60	✓
2 pcs	Rear bumper side retainer		\$38.20 <i>CMT</i>	✓
2 pcs	Rear bumper reflector		\$137.10 <i>mit</i>	✓
1 pc	Rear bumper lower cover	<i>mt/CM</i>	\$175.20	✓

balance c/f \$12,003.20

LIK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



		balance b/f	\$12,003.20	
1 pc	Rear buzzer			
2 psc	Rear fender		\$185.20	X
2 pcs	Rear fender air duct	B <sub>1</sub> \$1,185.90	\$2,371.80	✓
2 pcs	Rear fender inner panel	0d/0m17 \$155.10	\$310.20	✓
2 pcs	Rear fender inner trim board	21/1R <sub>1</sub> \$655.10	\$1,310.20	4
2 pcs	Rear fender arch protector	\$425.10	\$850.20	✓
2 pcs	Rear fender inner shield	117/1001 \$175.20	\$350.40	✓
2 pcs	Rear fender inner top garnish	\$105.60	\$211.20	✓
1 pc	Rear o/s fender triangle garnish	\$115.20	\$230.40	✓
1 pc	Rear boot top cover		\$95.70	✓
1 pc	Roof lining		\$355.60	✓
4 pcs	Roof air bag sensor	Return \$197.70	\$839.60	✓
1 pc	Air bag control unit		\$790.80	✓
2 pcs	Rear door assy	M <sub>1</sub> \$1,250.70	\$2,501.40	✓
2 pcs	Rear door inner lock	015 R <sub>1</sub>	\$935.10	4
2 pcs	Rear door rubber	\$255.60	\$511.20	X
1 pc	Rear o/s door inner trim board	015 CVT \$175.10	\$350.20	4
1 pc	Rear o/s door glass regulator motor		\$620.20	?
2 pcs	Rear door pillar weatherstrip		\$378.20	?
1 pc	Rear o/s rocker panel	\$165.10	\$330.20	?
1 pc	Rear o/s rocker panel garnish		\$655.50	✓
2 pcs	Rear door step garnish		\$487.60	✓
1 pc	Rear spare tyre panel	\$75.10	\$150.20	X
1 pc	Rear spare tyre tool sponge		\$1,255.80	?
1 pc	Rear spare tyre top cover board		\$275.60	?
1 pc	Rear exhaust silencer		\$385.60	✓
1 pc	Rear axle assy		\$975.10	?
2 pcs	Rear shock absorber		\$1,490.70	✓
2 pcs	Rear shock absorber mounting	\$385.10	\$770.20	✓
2 pcs	Rear hub assy	\$155.10	\$310.20	✓
2 pcs	Rear ABS pump	015 R <sub>1</sub> \$305.30	\$610.60	4
2 pcs	Rear ABS wire sensor	\$255.10	\$510.20	?
1 pc	Hybrid battery	\$195.70	\$391.40	?
1 pc	Hybrid battery chrome cover		\$14,955.00	?
1 pc	Hybrid battery fan discharge motor		\$325.70	?
1 pc	Hybrid battery air discharge hose		\$750.70	?
1 pc	Hybrid battery control unit		\$485.10	?
1 pc	Hybrid battery tray		\$1,985.20	?
1 pc	Fuel tank		\$256.90	?
1 pc	Fuel tank tube		\$985.70	?
1 pc	Fuel tank lock		\$225.10	?
1 pc	Fuel tank outer door cover		\$187.20	?
1 pc	Fuel pump assy		\$185.70	X
1 pc	Rear exhaust silencer		\$633.80	?
2 pcs	Rear exhaust silencer hook	\$85.10	\$975.60	?
1 pc	Rear exhaust silencer heat shield		\$170.20	?
1 pc	Front o/s shock absorber		\$165.20	?
1 pc	Front o/s shock absorber mounting		\$550.75	?
			\$165.20	?
		balance c/c	\$56,802.75	

SLS 2737 C

		balance b/f	\$56,802.75
1 pc	Front o/s shock absorber linkage		\$85.70 ?
1 pc	Front o/s kunckle arm		\$405.70 ?
1 pc	Front o/s kunckle bearing		\$195.20 ?
1 pc	Front o/s hub assy		\$485.70 ?
1 pc	Front o/s ABS sensor	in	\$187.20 X
1 pc	Front o/s lower arm		\$425.60 ?
1 pc	Front o/s driver shaft	R	\$955.30 X
			\$59,543.15
		Less 20 %	\$11,908.63
			\$47,634.52

S Nett

4 pcs	Roof air bag	Part	\$955.50	\$3,822.00 ✓
2 pcs	Front & rear o/s tyre rim	Acc o/s R	\$450.00	\$900.00 ✓
3 pcs	Tyres	L R L	\$200.00	\$600.00 80/salt
1 pc	Rear tail-gate glass sealant			\$55.00 ✓
1 pc	Rear reverse camera			\$300.00 ✓
1 pc	Rear reverse sensor			\$200.00 ✓
1 pc	Sundry expesnes			\$60.00 ?
1 pc	Rear no plate			\$40.00 X
1 pc	Rear CCTV			\$450.00 ?
				\$6,427.00

Labour Charges

Remove/renew the above parts including knocking, welding & cutting.	2400	\$2,800.00
To putty and spray paint	1800	\$2,000.00
Check & reconnect wiring.	400	\$480.00
To respray anti-rust proofing treatment	2100	\$240.00
Remove/refit rear windscreen to facilitate repair	✓	\$120.00
Remove/refit rear tail-gate mechanism to new door.	600	\$150.00
Remove/renew rear exhaust silencer.	800	\$120.00
Remove/refit rear boot upholstery to facilitate repair.	1000	\$150.00
Remove/renew rear and rear undercarriages.	2200	\$650.00
Check and realign wheel alignment.	600	\$80.00
Diagnostic check on rear ABS and to reset same.	✓	\$200.00 X
Remove/renew hybrid battery and to reset factory specification	✓	\$800.00
		balance c/f
		\$61,851.52



SLS 2737-C

balance b/f \$61,851.52

Labour Charges

Remove/repair rear cushion seat frame and leather	\$1,000.00	1501
Trolling towing	(Bill) \$150.00	7
Remove/renew roof lining, air bag and to reset same	\$800.00	2201
Remove/renew fuel pump and tank etc.	\$320.00	601
Total	<u>64 121.52</u>	

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission ..... 13/11/2020 14:17 (SGT)  
Date of Accident ..... 12/11/2020 02:30 (SGT)  
Exact Location of Accident ..... Upper Serangoon Rd, Singapore  
Additional Location Information .....  
Country/State of Loss ..... Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number ..... SLS2737C

#### INSURED/POLICYHOLDER

Is company? ..... Yes  
Name Of Registered Owner ..... H L CAR RENTAL PTE LTD  
Company Reg No ..... 2XXXXX543E  
Email Address ..... carrental.lh@gmail.com  
Mobile Phone No ..... (Phone) +65-97687073  
Alternative Phone No ..... (Office) +65-64817221

#### VEHICLE PARTICULARS

Manufacturer ..... Honda  
Model ..... Vezel  
Variant .....  
Exact purpose for which vehicle was being used at time of accident ..... Private hire  
Are you claiming under your own insurance policy for repair to your vehicle? ..... No - Claiming third party  
Vehicle Category ..... Private car

#### INSURANCE COMPANY

Name of Insurance Company ..... China Taiping Insurance  
Type of Coverage ..... Comprehensive  
Fleet Policy ..... Yes  
Policy Number ..... DMHCSNA00002722000  
Cover Note Number .....

#### DRIVER

Name of Driver ..... YE JUNYOU  
NRIC No ..... SXXXX678E  
Date Of Birth ..... 05/11/1985  
Occupation ..... Outdoor



Date Of Driving Pass ..... 02/03/2006  
 Driving experience ..... 14 YEARS AND 8 MONTHS  
 Gender ..... Male  
 Mobile Number .....  
 Alt. Phone Number ..... (Phone) +65-81105721  
 Email Address ..... -  
 Address ..... shouye101@gmail.com  
 Address complement ..... BLK689E WOODLANDS DRIVE 75 #03-130  
 Postcode ..... -  
 Is the driver the policyholder? ..... 735689  
 If No, Relationship of the Driver with the Insured ..... No  
 Does Driver Own Other Vehicles? ..... Paid Driver  
 Vehicle Registration Number of Other Vehicle Owned by Driver ..... No  
 Insurance Company of Other Vehicle Owned by Driver ..... -

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident ..... Collision - Head to Rear  
 Weather Conditions ..... Clear  
 Road Surface ..... Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident? ..... No  
 Number of vehicles involved in the accident ..... 2  
 Was anybody injured in the Accident? ..... Yes  
 Was any injured conveyed to hospital by ambulance? ..... No  
 Was any other material or property damaged? ..... Yes  
 Number of Passengers (Including Driver) ..... 3  
 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? ..... No

#### PASSENGER 1

Name ..... UNKNOWN  
 Gender ..... Female

#### PASSENGER 2

Name ..... UNKNOWN  
 Gender ..... Female

#### DETAILS OF POLICE ACTION

Was the accident reported to the police? ..... Yes  
 Police Station Name ..... Ang Mo Kio South Neighbourhood Police Centre  
 Was notice of intended Prosecution given? ..... No  
 If yes, against whom? ..... -

#### CIRCUMSTANCES OF ACCIDENT

Please refer to police report

#### ATTACHMENT(S)

Are accident photos available for attachment? ..... Yes  
 Was there any video captured by Car Camera? ..... Yes  
 Was there any audio recorded? ..... No

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number ..... SME8937P  
 Vehicle Manufacturer ..... -  
 Vehicle Model ..... -



# SKETCH PLAN

## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Please refer to police report.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

H.I. CAR RENTAL PTE LTD

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

GIARMC SketchPlanForm\_V3

2





# SINGAPORE POLICE FORCE



T202011162073

1 of 3

Report No. T202011162073

Police Station Of Origin:  
Ang Mo Kio South N.P.C  
21 Ang Mo Kio Avenue 3 SINGAPORE  
559829  
Tel No: 1800-4519999

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 18/11/2020 05:23		Vide Report No.: E/20201112/0020		Station Diary No.: 78
Name of Informant: YE JUNYOU		Address: APT BLK 689E WOODLANDS DRIVE 75 #03-130 SINGAPORE 735689		
ID Type / ID No.: NRIC NO / S8538578E		Contact No.: Home/Office: Mobile: 81105721		
Nationality: SINGAPORE CITIZEN		Email:		
Sex: Male	Age: 35	Date of Birth: 05/11/1985	Type of Informant: Driver	
Race: Chinese		Language: Chinese	Institution / School Name:	
Occupation: PRIVATE HIRE DRIVER		Driving Licence Information: Class: 3		Date of Expiry:

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 12/11/2020 02:20	Type of Location:
Location: UPPER SERANGOON ROAD				
Weather: Clear	Road Surface: Dry	Road Speed Limit:		
Traffic Flow: One Way	Traffic Control: Not Controlled	Traffic Volume: Light		
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: Yes	


SLS2737C	Car	HONDA	Silver	Seriously Damaged	2
SME8937P	Car	VOLKSWAGO N	Silver	Slightly Damaged	0

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA





# SINGAPORE POLICE FORCE



T/20201116/2073

Police Station Of Origin:  
Ang Mo Kio South N.P.C  
81 Ang Mo Kio Avenue 3 SINGAPORE  
689929  
Tel No: 1800-4619999

Report No. T/20201116/2073

## CONTINUATION OF REPORT

Name	YE JUNYOU	ID No.	S8536678E
Related Vehicle	SLS2737C (Car)	Contact No.	81105721
Hospital/Clinic	MOUNT ALVERNIA HOSPITAL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	16/11/2020	Date Discharge	NIL
No. of Days granted Medical Leave	03	Degree of Injury	Slight
Name	Unknown Passenger	ID No.	NIL
Related Vehicle	SLS2737C (Car)	Contact No.	82821690
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

### Brief Details.

On 12/11/2020 at about 0220hrs, I was driving my vehicle SLS2737C along Upper Serangoon Road before Braddell Road on the most left lane with two female passengers. Suddenly, I felt a strong impact at the rear. I lost control of my vehicle and went up the divider. I made a check and a vehicle SME8937P have collided into my vehicle. My vehicle was badly damaged and was towed away.

Subsequently, Police and ambulance came. I was given a case card and the other vehicle driver was sent to the hospital by ambulance.

On 16/11/2020 at about 1300hrs, I went to Mount Alvernia Hospital to see doctor as I was still feeling chest pain. I was given 3 days of MC from 16/11/2020 to 18/11/2020. MC number is M20000051948.