

V8 MOTOR WERKZ PTE. LTD.

Registration No. 201622378N

Not Authorized
11 Sep @ 1100h
Resurvey After Paint
2 days

Estimate for SGR5247U(Honda Stream)

1 *REAR BUMPER	665.40	Bu	\$788.90	—
2 *REAR BUMPER LOWER BRACKET L/R		in	\$110.00	X
2 *REAR BUMPER SIDE RETAINER L/R		also in	\$125.00	LT
1 *REAR BUMPER TOW HOOK COVER		in	\$13.50	X
1 *REAR LH TAILLAMP	385.20	CM	\$820.00	—
1 *REAR TAILGATE H LOGO EMBLEM		in	\$21.90	X
1 *REAR END PANEL		R	\$306.70	X
			\$2,186.00	
			\$437.20	
			\$1,748.80	

Less 20%

S/Nett

1 *REAR BUMPER CLIPS - SET		MC	\$80.00	50 in
1 *REAR LH TAILLAMP CLIPS - SET		MC	\$30.00	—
			\$110.00	

TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS,
CHECK LIGHTING, AND REWIRE FOR PARKING SENSOR

\$80.00 201

TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS,
REPAIR PORTION, AND WHERE CONSISTENT TO THE
ACCIDENT

\$1,000.00 2001

TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE
ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT
AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS
AND DAMAGED CONSISTENT TO THE ACCIDENT

\$1,000.00 2201

\$2,080.00

Total

\$3,938.80

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: