



FALCON - AIR AUTO SERVICES PTE LTD

Co. Reg. No.: 199501140D
GST Reg. No.: 199501140D

FALCON - AIR

LONPAC INSURANCE BHD
300 BEACH ROAD #17-04/07
THE CONCOURSE 199555
ATTENTION: GERALD POH

Attention : Motor Claim Department

Contact : 62507388 Fax No. : 62962706

Supplementary Estimate : ES012129

Date : 17/02/2021

Vehicle Num. : SLW 2745H

Make/Model : HONDA JAZZ CVT-2017/2018

Chassis/Eng# : JHMGK5850JX203974

Accident Date : 16/12/2020

Claim No. :

Reference : O/D

Policy No. : Z20VP05025865

S/N	Quantity	Particular	Unit Price	Amount S\$
1.	1 PC	PARTS PURCHASED : FRONT GRILLE STAY		10.00
		Total Parts Purchased S\$:		10.00
		15.00% Of The Above Parts S\$:		1.50
		Based On Cost Plus S\$:		11.50

E. & O.E.

Total S\$:

11.50

for FALCON AIR AUTO SERVICES PTE LTD

The quotation was prepared from visual inspection. Further materials and labour charges may be required when repair commences. We will advise you accordingly.

FALCON AIR AUTO SERVICES PTE LTD
(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office : Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S(575721) Tel: 6452-0880 / 6458-0880 Fax: 6454-7862

Branches : Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No 8 Pandan Loop (Blk 1/Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110
Website: www.falconair.com.sg Email: email@falconair.com.sg



FALCON - AIR

FALCON - AIR AUTO SERVICES PTE LTD

Co. Reg. No.: 199501140D
GST Reg. No.: 199501140DLONPAC INSURANCE BHD
300 BEACH ROAD #17-04/07
THE CONCOURSE 199555
ATTENTION: GERALD POH

Attention: Motor Claim Department

Contact: 62507388 Fax No.: 62962706

Estimate: ES012095

Date: 17/12/2020

Vehicle Num.: SLW 2745H

Make/Model: HONDA JAZZ CVT-2017/2018

Chassis/Eng#: JHMGK5850JX203974

Accident Date: 16/12/2020

Claim No.:

Reference: O/D

Policy No.: Z20VP05025865

Not Notarized
Recovery B4prim
EX ?

S/N Quantity Particular *6 days* Unit Price Amount S\$

PARTS PURCHASED:		
1. /1 PC	BONNET	
2. /2 PCS	BONNET HINGE	
3. /1 PC	BONNET INSULATOR	
4. /2 PCS	BONNET RUBBER (OUTER)	
5. /2 PCS	BONNET RUBBER (INNER)	
6. /1 PC	BONNET LOCK	
7. /1 PC	RH FRONT FENDER	
8. /1 PC	RH FRONT FENDER SHIELD	
9. /2 PCS	HEADLAMP	
10. /2 PCS	HEADLAMP RETAINER	
11. /1 PC	RADIATOR GRILLE BASE	
12. /1 PC	RADIATOR GRILLE LOGO	
13. /1 PC	RADIATOR GRILLE LOGO BASE	
14. /1 PC	RADIATOR GRILLE TOP COVER	
15. /2 PCS	RADIATOR GRILLE CHROME MOULDING	
16. /1 PC	FRONT BUMPER	
17. /2 PCS	FRONT BUMPER SIDE RETAINER	
18. /1 PC	FRONT NUMBER PLATE GARNISH	
19. /1 PC	RADIATOR GRILLE CHROME GARNISH	
20. /1 PC	FRONT BUMPER TOW COVER	
21. /1 PC	FRONT BUMPER LOWER GRILLE	
22. /1 PC	FRONT BUMPER LOWER SPOILER	

<i>BH/ID</i>	22.00	<i>Rehm</i>	44.00	<i>303.00</i>	<i>280.00</i>	
<i>DI/ID</i>	15.00		30.00			
<i>"</i>	15.00		30.00			
		<i>Bu</i>	65.00			
		<i>Bu</i>	130.00			
<i>CM</i>	1,000.00		2,000.00			
	32.00	<i>DI</i>	64.00			
		<i>CM</i>	185.00			
		<i>MC</i>	16.00			
		<i>CM</i>	18.00			
		<i>DI</i>	15.00			
	15.00	<i>CM</i>	30.00			
		<i>DI</i>	340.00			
<i>DI</i>	6.00		12.00			
		<i>DI</i>	35.00			
		<i>DI</i>	100.00			
<i>DI/ID</i>		<i>DI</i>	11.00			
		<i>CM</i>	150.00			
		<i>DI</i>	240.00			

1pc - front grille stay — 10.00

CONTINUE / ...

8820 - 8920

Parts - 6293.95
Supply - 11.50
S/N - 155.00
Labour - 1820.00
Total - 9820.45
P/P

FALCON - AIR AUTO SERVICES PTE LTD
(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S(575721) Tel: 6452-0880 / 6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No 8 Pandan Loop (Blk 1/Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110



FALCON - AIR AUTO SERVICES PTE LTD

Co. Reg. No.: 199501140D
GST Reg. No.: 199501140D

FALCON INSURANCE LTD

300 BEACH ROAD #17-04/07

THE CONCOURSE 199555

ATTENTION: GERALD POH

Attention: Motor Claim Department

Contact: 62507388 Fax No.: 62962706

Estimate: ES012095

Date: 17/12/2020

Vehicle Num.: SLW 2745H

Make/Model: HONDA JAZZ CVT-2017/2018

Chassis/Eng#: JHMGK5850JX203974

Accident Date: 16/12/2020

Claim No.:

Reference: O/D

Policy No.: Z20VP05025865

S/N	Quantity	Particular	Unit Price	Amount S\$
23.	1 PC	FRONT BUMPER REINFORCEMENT		190.00
24.	1 PC	FRONT SUPPORT PANEL		260.00
25.	2 PCS	AIR GUIDE	12.00	24.00
26.	1 PC	AIR CON CONDENSER		280.00
27.	1 PC	AIR CON LIQUID PIPE		95.00
28.	1 PC	AIR CON DISCHARGE HOSE		110.00
29.	1 PC	AIR CON SUCTION HOSE		110.00
30.	1 PC	AIR CON FAN COWLING		65.00
31.	1 PC	AIR CON FAN BLADE		35.00
32.	1 PC	AIR CON FAN MOTOR		180.00
33.	1 PC	RADIATOR		780.00
34.	1 PC	RADIATOR FAN COWLING		50.00
35.	1 PC	RADIATOR FAN BLADE		35.00
36.	1 PC	RADIATOR FAN MOTOR		160.00
37.	1 PC	COOLANT SPARE TANK		20.00
38.	1 PC	AIR DUCT		35.00
39.	1 PC	WIPER WASHER TANK		20.00
40.	1 PC	WIPER WASHER TANK NECK		12.00
41.	1 PC	FRONT BUMPER CENTER GARNISH		25.00
42.	2 PCS	FRONT FOG LAMP GARNISH		24.00
43.	2 PCS	FRONT FOG LAMP GARNISH CHROME		100.00
Total Parts Purchased S\$:			5473	6,720.00
15.00% Of The Above Parts S\$:			820.95	1,008.00
Based On Cost Plus S\$:			6293.95	7,728.00

CONTINUE / ...



FALCON - AIR

LONPAC INSURANCE BHD
300 BEACH ROAD #17-04/07
THE CONCOURSE 199555
ATTENTION: GERALD POH

Attention: Motor Claim Department
Contact: 62507388 Fax No.: 62962706

Estimate : ES012095

Date: 17/12/2020
Vehicle Num.: SLW 2745H
Make/Model: HONDA JAZZ CVT-2017/2018
Chassis/Eng#: JHMGK5850JX203974
Accident Date: 16/12/2020
Claim No.:
Reference: O/D
Policy No.: Z20VP05025865

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1.	10 PCS	SPECIAL NETT ITEMS :		
2.	8 PCS	BONNET INSULATOR CLIP	4.00	40.00 ✓
3.	10 PCS	RH FRONT FENDER SHIELD CLIP	5.00	50.00 ✓
4.	1 PC	FRONT BUMPER CLIP	4.00	40.00 ✓
5.	1 BOTTLE	FRONT NUMBER PLATE		45.00 ✓
		COOLANT		40.00 ✓

Special Nett Total S\$:

205.00

LABOUR :

TO FOCUS HEADLAMP

50.00 200

TO REMOVE/REFIX AIR CON CONDENSER, PIPE

VACUUM AND TOP UP AIR CON GAS

120.00 100

TO STRAIGHTEN LH/RH FRONT CHASSIS, LH FRONT FENDER, RH

FRONT DOOR, CUT/REWELD FRONT SUPPORT PANEL AND

REPLACEMENT OF PARTS

1,000.00 700

TO SPRAY PAINT ON BONNET, FRONT BUMPER, FRONT BUMPER

REINFORCEMENT, FRONT SUPPORT PANEL, LH/RH FRONT

CHASSIS, LH/RH FRONT FENDER, RH FRONT DOOR

1,680.00 1000

Labour Total S\$:

2,850.00

E. & O.E.

Total S\$: 10,783.00

for FALCON AIR AUTO SERVICES PTE LTD

The quotation was prepared from visual inspection. Further materials and labour charges may be required when repair commences. We will advise you accordingly.