



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

| | | |
|-------------------------------------|-----------|------------------------|
| CHINA TAIPING INSURANCE (S) PTE LTD | INV No. | AC2102943 |
| 3 ANSON ROAD #16-00 | INV Date | 27/04/2021 |
| SPRINGLEAF TOWER | Reference | CC6/CTI20014082/Ura3q2 |
| SINGAPORE 079909 | Code | CTI |

PROFESSIONAL SERVICE FEE

| | |
|-----------------|--------------------|
| Vehicle No. | GBG 7719D |
| Insured Veh. | SLT 4522L |
| Claim No. | SNM20D204855/C02 |
| Policy No. | DMHCSNA00001902000 |
| Accident Date | 01/12/2020 |
| Inspection Date | 18/12/2020 |

| Description | Total |
|--------------------------------|---------------|
| Third Party Express Settlement | 400.00 |
| Subtotal | 400.00 |
| GST (7%) | 28.00 |
| Grand Total | 428.00 |

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | |
|--|--|--|------------|
| CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909 | | Ref: CC6/CTI20014082/Ura3q2 Date: 27/04/2021 Code: CTI | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | |
| Insured Veh. | SLT 4522L | Veh. Inspected | GBG 7719D |
| Policy No. | DMHCSNA00001902000 | Coverage (\$) | 0.00 |
| Claim No. | SNM20D204855/C02 | Excess (\$) | 0.00 |
| Assign From | | Assign Date | 18/12/2020 |
| 2. Vehicle Particulars & Condition | | | |
| Make & Model | FIAT DOBLO CARGO MAXI | c.c | 1598 |
| Engine No. | HIDDEN | Year of Reg. | 2017 |
| Chassis No. | ZFA26300006H34426 | Colour | WHITE |
| Odometer | 54969 KM | Steering | IN ORDER |
| Brakes | IN ORDER | Modification | NIL |
| General | GOOD | | |
| 3. Conditions of Tyres | | | |
| | Size | Make | Balance |
| R/H Front Tyre | 195/60 R16 | PIRELLI | 6 mm |
| L/H Front Tyre | 195/60 R16 | PIRELLI | 6 mm |
| R/H Rear Tyre | 195/60 R16 | PIRELLI | 6 mm |
| L/H Rear Tyre | 195/60 R16 | PIRELLI | 6 mm |
| 4. Description of Damages | | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS. | | | |
| 5. General Information | | | |
| Accident Date | 01/12/2020 | Inspection Date | 18/12/2020 |
| Survey held at | LIU'S BROTHER AUTO ENGINEERING WORKSHOP 1 KAKI BUKIT AVENUE 6 #01-01 AUTOBAY @ KAKI BUKIT SINGAPORE 417883 | | |
| 5a. Remarks | | | |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | |
| 5b. Estimate Days of Repair | | | |
| ESTIMATED NORMAL PERIOD FOR REPAIR: | | 2 Working Days | |



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBG 7719D

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|---|---|---------------|---------------------------|-------------------|
| REPLACEMENT OF PARTS | | | | |
| 1 | FRONT LH SLIDING DOOR OUTER PROTECTOR | SCRATCHED | 207.80 | 207.80 |
| 1 | FRONT LH SLIDING DOOR HANDLE | NOT NECESSARY | 276.00 | - |
| 1 | FRONT LH DOOR OUTER PROTECTOR | SCRATCHED | 320.00 | 320.00 |
| 1 | FRONT LH DOOR OUTER HANDLE | NOT NECESSARY | 276.00 | - |
| | LESS 10% DISCOUNT | | - | -52.78 |
| | | | 1,079.80 | 475.02 |
| SPECIAL NETT ITEMS | | | | |
| 1 | SET FRONT LH DOOR PROTECTOR CLIPS (SN) | NOT NECESSARY | 48.00 | - |
| 1 | FRONT LH 'CORPORATE' ADVERTISEMENT & ARTWORK (SN) | NOT NECESSARY | 200.00 | - |
| | | | 248.00 | - |
| LABOUR | | | | |
| | TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION . | | 80.00 | 20.00 |
| | LABOR FOR PANEL BEATING ,CUT ,WELD ,STRAIGHTEN & REPLACING PARTS ETCS. | | 200.00 | 120.00 |
| | TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED . | | 500.00 | 400.00 |
| | TO REMOVE ,REPLACE AND TRANSFER DOOR PANEL ,FITTING AND MECHANISM . | NOT NECESSARY | 80.00 | - |
| | TO APPLY RUST PROOFING, RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA. | NOT NECESSARY | 60.00 | - |
| | | | 920.00 | 540.00 |
| GRAND TOTAL | | | 2,247.80 | 1,015.02 |
| RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) | | | | 800.00 |

Report Ref No. CC6/CTI20014082/Ura3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBG 7719D

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R








LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBG 7719D

RE-INSPECTION

