BIKE PRODUCTION PTE LTD

610, Serangoon Road S(218216) Tel: 63922555, 62995177 Fax: 62975400

ROC/ GST Reg No.: 200007407G

Date: 13 Dec 2020

ASSESSMENT FOR REPAIR: HONDA CB150R MANUAL - FBN2485Z

Chassis No.: Engine No.:

<u>Qty</u>	<u>Description</u>	<u>Estimate</u>
1 pc	Front fender	\$185.00
1 pc	Front wheel shaft	\$75.00
1 pc	Front disk brake	\$195.00
1 pc	Front brake caliper	\$215.00
1 pc	Front left fork assy	\$795.00
1 pc	Front righ fork assy	\$795.00
1 pc	Steering stem	\$295.00
1 pc	Steering bridge	\$220.00
2 pcs	Steering bearings	\$90.00
1 set	Steering bridge holder	\$150.00
1 pc	Front right signal	\$125.00
1 pc	Front left signal	\$125.00
1 pc	Left view mirror	\$95.00
1 pc	Right view mirror	\$75.00
1 pc	Meter assy	\$395.00
1 pc	Meter cover	\$115.00
1 pc	Handle bar	\$175.00
1 pc	Clutch lever	\$65.00
1 pc	Clutch lever holder	\$85.00
1 pc	Clutch cable rubber	\$25.00
1 pc	Left balancer	\$48.00
1 pc	Front headlamp	\$380.00
1 pc	Frant headlamp cover	\$105.00
1 pc	Fuel tank left cover	\$295.00
1 pc	Amblem	\$25.00
1 pc	Left side cover	\$145.00
1 pc	Left side inner cover	\$105.00
1 pc	Radiator	\$385.00
1 pc	Radiator fan assembly	\$195.00
1 pc	Exhaust assy	\$750.00
1 pc	Exhaust cover	\$145.00
1 pc	Brake pedal	\$78.00
1 pc	Left tail cover	\$145.00
1 pc	Left side cover	\$125.00
1 pc	Rear mudguard	\$175.00
		\$7,396.00
	Less discount 10%	<u>\$739.60</u>
	Consist watt items	\$6,656.40
1 nc	Special nett items	¢500 00
1 pc	Sport rim front	\$580.00
1 pc	Coolant	\$50.00
1 pc	Front no plate	\$25.00
1)	Towing charges	\$100.00

	Replace, realign and adjust above	
	damaged parts, check wiring and	
2)	lighting system To knock, straighten chassis & body	\$750.00
3)	balancing	\$380.00
	To remove/refit, replace (if damage) check and	
4)	straighten front fork tubes.	\$180.00
	To remove/refit, replace (if damage) check and	
4)	straighten front sport rims.	\$150.00
6)	Spray painting	\$350.00
	Total Estimate	\$9,221.40

Note: The above estimate is subjected to the prevailing GST of 7%