BIKE PRODUCTION PTE LTD

610, Serangoon Road S(218216) Tel: 63922555, 62995177 Fax: 62975400

ROC/ GST Reg No.: 200007407G

Date: 13 Dec 2020

ASSESSMENT FOR REPAIR: HONDA CB150R MANUAL - FBN2485Z

Chassis No.: Engine No.:

	<u>Description</u>	<u>Estimate</u>
Qty	Description	\$185.00 CRK
	Front fondor	\$75.00 ?
1 pc	Front fender Front wheel shaft	\$75.00 ? \$195.00 ?
1 pc		
1 pc	Front disk brake	\$215.00 NO DEF \$795.00 DEF
1 pc	Front brake caliper	\$795.00 7 DEF
1 pc	Front left fork assy	\$795.00
1 pc	Front righ fork assy	\$295.00 [?]
1 pc	Steering stem	\$220.00 ?
1 pc	Steering bridge	\$90.00 ?
2 pcs	Steering bearings	¢150.00
1 set	Steering bridge holder	\$125.00 × 5 × 5
1 pc	Front right signal	\$125.00 / MI
1 pc	Front left signal	\$95.00 / CRK
1 pc	Left view mirror	\$75.00 / S44
1 pc	Right view mirror	\$395.00 / CK
1 pc	Meter assy	\$115.00 ?
1 pc	Meter cover	\$175.00 [?]
1 pc	Handle bar	\$65.00 / 13KK
1 pc	Clutch lever	\$85.00 / Red SCR
1 pc	Clutch lever holder	\$25.00 / 12
1 pc	Clutch cable rubber	\$48.00 / MIS
1 pc	Left balancer	\$380.00 / SCR
1 pc	Front headlamp	\$105.00/CRK
1 pc	Frant headlamp cover	\$295.00 / DEF
1 pc	Fuel tank left cover	\$25.00 / NEL
1 pc	Amblem	\$145.00 /MIS
1 pc	Left side cover	\$105.00 / CK
1 pc	Left side inner cover	\$385.00
1 pc	Radiator	\$195.00 × \$ V \(\)
1 pc	Radiator fan assembly	\$750.00 7
1 pc	Exhaust assy	\$145.00 / 5 CR
1 pc	Exhaust cover	\$145.00
1 pc	Brake pedal	\$78.00 / 3 (2)
1 pc	Left tail cover	\$145.00 / 5 @
1 pc	Left side cover	\$125.00 ?
1 pc	Rear mudguard	\$175.00 / 8 /
		\$7,396.00
	Less discount 10%	<u>\$739.60</u>
		\$6,656.40
	Special nett items	1500 00 X (VI
1 pc	Sport rim front	\$580.00 × 50 (
1 pc	Coolant	\$50.00 / ~ \$ (
1 pc	Front no plate	20 \$25.00/MIS
1)	Towing charges	\$100.00 ×

	Replace, realign and adjust above	
2)	damaged parts, check wiring and lighting system	\$ 750.00 \$00
3)	To knock, straighten chassis & body balancing	\$380.00 20 XVV
4)	To remove/refit, replace (if damage) check and straighten front fork tubes.	\$1 80.00 150
,	To remove/refit, replace (if damage) check and	\$150.00 > ~
4)	straighten front sport rims.	
6)	Spray painting Total Estimate	\$9,221.40

Note: The above estimate is subjected to the prevailing GST of 7%

NAZ UCK
21/2/2020 1330
LIS
4 DAYS)
ELFECT ITEM PHOTOS
ATTER PERMIT PHOTOS