

BIKE PRODUCTION PTE LTD
 610, Serangoon Road S(218216)
 Tel: 63922555, 62995177 Fax: 62975400
 ROC/ GST Reg No.: 200007407G

Date: 13 Dec 2020

ASSESSMENT FOR REPAIR: HONDA CB150R MANUAL - FBN2485Z

Chassis No.:

Engine No.:

<u>Qty</u>	<u>Description</u>	<u>Estimate</u>
1 pc	Front fender	\$185.00 / CRK
1 pc	Front wheel shaft	\$75.00 ? / BT
1 pc	Front disk brake	\$195.00 ? / BT
1 pc	Front brake caliper	\$215.00 X SVL SCR
1 pc	Front brake caliper	\$795.00 / DEF
1 pc	Front left fork assy	\$795.00 / DEF
1 pc	Front right fork assy	\$295.00 ? / BT
1 pc	Steering stem	\$220.00 ? / SCR
1 pc	Steering bridge	\$90.00 ? / NEL
2 pcs	Steering bearings	\$150.00 ? X SVL
1 set	Steering bridge holder	\$125.00 X SVL
1 pc	Front right signal	\$125.00 / MIS
1 pc	Front left signal	\$95.00 / CRK
1 pc	Left view mirror	\$75.00 / SCR
1 pc	Right view mirror	\$395.00 / CRK
1 pc	Meter assy	\$115.00 ? / CRK
1 pc	Meter cover	\$175.00 ? / BT
1 pc	Handle bar	\$65.00 / CRK
1 pc	Clutch lever	\$85.00 / SCR
1 pc	Clutch lever holder	\$25.00 / TN
1 pc	Clutch cable rubber	\$48.00 / MIS
1 pc	Left balancer	\$380.00 / SCR
1 pc	Front headlamp	\$105.00 / CRK
1 pc	Front headlamp cover	\$295.00 / DEF
1 pc	Fuel tank left cover	\$25.00 / NEL
1 pc	Amblem	\$145.00 / MIS
1 pc	Left side cover	\$105.00 / CRK
1 pc	Left side inner cover	\$385.00 / DT
1 pc	Radiator	\$195.00 X SVL not working
1 pc	Radiator fan assembly	\$750.00 ? / DEF
1 pc	Exhaust assy	\$145.00 / SCR
1 pc	Exhaust cover	\$78.00 / SCR
1 pc	Brake pedal	\$145.00 / SCR
1 pc	Left tail cover	\$125.00 ? SVL
1 pc	Left side cover	\$175.00 / BT
1 pc	Rear mudguard	
	Less discount 10%	\$7,396.00
		\$739.60
		\$6,656.40
	Special nett items	
1 pc	Sport rim front	\$500.00 X SVL
1 pc	Coolant	\$50.00 / NEL
1 pc	Front no plate	20 \$25.00 / MIS
1)	Towing charges	\$100.00 X

7146
 X 0.9
 6431.4
 20
 \$100.00 X
 000007407G

- 2) Replace, realign and adjust above damaged parts, check wiring and lighting system
 - 3) To knock, straighten chassis & body balancing
 - 4) To remove/refit, replace (if damage) check and straighten front fork tubes.
 - 4) To remove/refit, replace (if damage) check and straighten front sport rims.
 - 6) Spray painting
- Total Estimate**

~~\$750.00~~ 400
~~\$380.00~~ 200
~~\$180.00~~ 150
~~\$150.00~~ NW
~~\$350.00~~ 200
\$9,221.40

Note: The above estimate is subjected to the prevailing GST of 7%

NAZ UKK

2.11/2020 1330

LIS

4 DAYS

CHECK ITEM PHOTOS

AFTER REPAIR PHOTOS



7251.40
 X 0.8
 5801.12