

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933  
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way #07-16  
Singapore 079120

**Our File No:** CS/AIG20014093/ETD3E2  
**Date:** 13/01/2021

### REFERENCE

Insured/Claimant: QUEK BEE GUAT Policy No: 2100493001  
Date of Loss: 17/12/2020 Nature of Claim: OD Claim No: 9831953113SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **EZ9333J**  
Make & Model: KIA FORTE K3, 1.6 (A) Engine No: G4FGGH638471  
Reg. Date: 08/12/2016 (Man. Year: 2016) Chassis No: KNAFZ411MH5649394  
Colour: White Odometer: 78899 km  
Engine Capacity: 1591 cc  
Market Value/New Car Price: S\$56,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

### CONDITION OF TYRES

Front Tyre Size: 215/45 R17 Rear Tyre Size: 215/45 R17  
Front Left Side: Yokohama 5 mm Rear Left Side: Yokohama 5 mm  
Front Right Side: Yokohama 5 mm Rear Right Side: Yokohama 5 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,160.00	2,276.00	884.00	27.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,700.00	1,710.00	990.00	36.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>5,860.00</b>	<b>3,986.00</b>	<b>1,874.00</b>	<b>31.98</b>
<b>- Excess (S\$)</b>	<b>600.00</b>	<b>600.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>5,260.00</b>	<b>3,386.00</b>	<b>1,874.00</b>	<b>35.63</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>368.20</b>	<b>237.02</b>	<b>131.18</b>	<b>35.63</b>
<b>Nett Amount (S\$)</b>	<b>5,628.20</b>	<b>3,623.02</b>	<b>2,005.18</b>	<b>35.63</b>

### INSPECTION

Date of Assignment: 18/12/2020  
Date Inspected: 18/12/2020 Inspected At: Cycle & Carriage KIA Pte Ltd (Pandan Gardens)  
209 Pandan Gardens  
Singapore 609339  
Estimated Period of Repair: 4.0 days

**Adjuster:** CHEN TSUE YEE

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	20.00 FS	*20.00 FS
2	1		*LAMP ASSY-HEAD, RH	Broken	1,707.00 FL	*1,707.00 FL
3	1		*PANEL-FENDER, RH	Dented	435.00 FL	*435.00 FL
4	1		*GUARD ASSY-FRONT WHEEL, RH	Not Necessary	95.00 FL	*- FL
5	1		*WHEEL ASSY-ALUMINIUM RHF	Not Necessary	981.00 FL	*- FL
6	1		*ORNAMENT-KIA NO.115	Necessary	32.00 FL	*32.00 FL
7	1		*COVER-FR BUMPER	Broken	633.00 FL	*633.00 FL
8	1		*BRACKET-FR BUMPER SIDE MTG, RH	Broken	13.00 FL	*13.00 FL
9	1		*STRIP ASSY-FR BUMPER UPR	Not Necessary	29.00 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>3,945.00</b>	<b>2,840.00</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	785.00	564.00
<b>Total Parts (\$\$)</b>	<b>3,160.00</b>	<b>2,276.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	RENEW FRT BUMPER & RHF FENDER	New	1,600.00	800.00
2	RESPRAY FRT BUMPER & RHF FENDER	New	700.00	700.00
3	CHECK WIRING ELECTRICAL SYSTEM & ADJUST HEADLAMP AIM	New	30.00	0.00
4	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
5	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	120.00	0.00
6	APPLY ANTI CORROSION ON AFFECTED AREAS	New	40.00	0.00
7	REMOVE & REFIT FRT PARKING ASSIST SENSOR	New	60.00	60.00
8	RENEW RHF SPORT RIM, TRANSFER TYRE AND TYRE BALANCING	New	30.00	30.00
			<b>Gross Labour Cost (\$\$)</b>	<b>2,700.00</b>
				<b>1,710.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >