

勝峰記公司

LKK Auto Consultants hence notify
the Repairer of the following

• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis * 車輛修理，焊接與噴漆等 *
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

SENG HONG KEE CO.
BLOCK 4, 393-F WOODLANDS ROAD (YEW TEE INDUSTRIAL ESTATE)
SINGAPORE 677976 TEL: 6760 5120 FAX: 6760 2129

REG No: 270675/00X

Motor Vehicles Repairing, Welding and Spray Painting

Our Ref: 3299/20/SHK

Date: 18 Dec 2020

Acknowledged by Repairer

Signature: LOE SU SENG

Date: Blk 815A #03-13 Choa Chu Kang Ave 7
Singapore 681815

Estimated cost of repair to vehicle Registration No: SJF 3387 P

Qty	List Items	Price (\$)	Price (\$)
1 pc.	Tailgate / pn	1,382.50	
1 pc.	Tailgate lock / Jam	109.40	
1 pc.	Tailgate frame weatherstrip / CRU.	191.20	
1 pc.	Tailgate centre garnish / CRU	451.30	
1 pc.	Tailgate top spoiler / CRU.	750.00	
2 pcs.	Tailgate lamps @\$245.30 X SVC	490.60	
2 pcs.	Rear number plate lamps @\$32.80 X SVC	65.60	
1 pc.	Rear bumper / CRU	1,078.50	
1 pc.	Rear bumper beam X SVC	90.00	
2 pcs.	Rear bumper side retainers @\$25.00 X NN	50.00	4,460.20
1 pc.	Rear end panel / DD	508.70	- 20%
1 pc.	Rear end panel garnish / CRU	138.60	
		5,306.40	3,568.16
	Less 20% dis.	1,061.28	4,245.12

Special nett items

1 set.	Reverse camera / CRU	235.00	150
1 set.	Rear number plate / DD	45.00	
1 tube.	Tailgate glass sealant / NRC	30.00	
1 set.	Tailgate glass moulding / NRC	80.00	390.00
		305	

Labour Charge

01.	To remove and refix tailgate glass	150.00	100
02.	To remove all listed parts, straighten, reshape and re-position spare tyre panel and rear end floor. Cut and weld rear end panel. Refix and re-align same.	1,000.00	
03.	To spray paint on affected areas	1,000.00	800
04.	To anti-rust affected areas	80.00	40
05.	To renew tailgate, refix tailgate lock, lock mechanism and tailgate attachments	100.00	60
		2,330.00	
	Total	2,000	6,965.12

Repair day - 6 days

LS

After paint photo.

SunPin (Hk)

18/12/2020

8661 2627

Sunpin@lkkayto.com

3,568.16
305
2,000
5,873.16
- 20%
4,698.53

2/5
\$4,700
6 days