

Trident Auto Service Centre Pte Ltd

8 Kaki Bukit Ave 4, #02-44
Premier @ Kaki Bukit (Gate 1)
Singapore 415875
Tel: 63441918

First Capital Insurance Ltd
6 Raffles Quay
Singapore 048580

Justin

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Date : 17/12/2020
Vehicle : SIC280Z
Make/Model : Toyota C-HR Hybrid 1.8
ORD : 2017
Chassis : ZYX102013996
ODO : 199324
ACC Date : 14/12/2020

Estimate

S/N	Qty	Description & Specification	Amount S\$
		List Items	
1	1	Front fender LH <i>Dented</i>	\$921.60 ✓
2	1	Front fender 'HYBRID' emblem LH <i>new</i>	\$105.90 ✓
3	1	Front fender quarter garnish LH <i>new</i>	\$132.70 +
4	1	Front door LH <i>Dented</i>	\$1,453.30 ✓ <i>1295</i>
5	1	Front door outer handle LH <i>cut</i>	\$253.80 ✓
6	1	Front door outer handle cover LH <i>repair</i>	\$111.40 +
7	1	Front door outer handle gasket LH <i>new</i>	\$58.90 ✓
8	1	Front door outer handle cover gasket LH <i>new</i>	\$47.90 + <i>97</i>
9	1	Front door top hinge LH <i>Bent</i>	\$167.90 ✓
10	1	Front door bottom hinge LH <i>new</i>	\$167.50 +
11	1	Front door lock LH <i>new</i>	\$458.20 +
12	1	Front door w/strip LH <i>new</i>	\$229.70 +
13	1	Front door glass regulator LH <i>new damaged</i>	\$456.90 + <i>255</i>
14	1	Front door glass regulator motor LH <i>new</i>	\$627.90 + <i>485</i>
15	1	Front door glass outer moulding LH <i>new</i>	\$313.80 ✓
16	1	Front door glass channel LH <i>new</i>	\$204.90 +
17	1	Front door glass run LH <i>new</i>	\$199.80 +
18	1	Front door outer garnish LH <i>new</i>	\$289.60 ✓
19	1	Front door quarter glass LH <i>new</i>	\$454.90 +
20	1	Front door quarter glass moulding LH <i>new</i>	\$122.30 +
21	1	Front door inner trim board LH <i>new</i>	\$998.40 + <i>685</i>
22	1	Wing mirror LH <i>Dented</i>	\$984.80 ✓
23	1	Wing mirror cover LH <i>new</i>	\$101.20 ✓
24	1	Wing mirror chrome garnish LH <i>cut</i>	\$95.20 ✓
25	1	Rear door LH <i>Dented</i>	\$1,384.50 ✓ <i>1279</i>
26	1	Rear door w/strip LH <i>new</i>	\$201.80 +
27	1	Rear door outer garnish LH <i>new</i>	\$251.80 ✓
28	1	Rear door quarter glass LH <i>new</i>	\$374.20 +
29	1	Rear door quarter glass moulding LH <i>new</i>	\$99.90 +
		<i>Front Fender Inner Garnish, new 128 ✓</i>	
			Less 25% \$2,817.58
			List Total \$8,452.73

S/Nett Items	Qty	Description	Amount S\$
1	1set	Front fender arch garnish clips LH <i>new</i>	\$50.00- 20
2	1set	Front fender inner shield clips LH <i>new</i>	\$50.00- 20
3	1set	Front door inner trim board clips LH <i>new</i>	\$100.00- 30
4	1set	Front door protector clips LH <i>new</i>	\$50.00- 30
5	1set	Rear door inner trim board clips LH <i>new</i>	\$100.00- 30
6	1set	Rear door protector clips LH <i>new</i>	\$50.00- 20
7	1set	Rear fender arch garnish clips LH <i>new</i>	\$50.00- 20
8	1set	Rear fender inner shield clips LH <i>new</i>	\$50.00- 20
9	1set	Rear bumper clips <i>new</i>	\$100.00- 30
			S/Nett Total \$600.00

Labour	Description	Amount S\$
1	To repair 'A' pillar LH, repair rear fender LH, replace front fender LH and both LH doors plus re-align on all accident affected areas	\$1,000.00- 800
2	To putty and respray on LH accident portion	\$1,500.00- 1100
3	To check LH lighting and wiring	\$100.00- 80
4	To apply anti-rust corrosion on affected areas	\$200.00- 80
5	To transfer front door LH mechanism to new door	\$300.00- 80
6	To transfer rear door LH mechanism to new door	\$300.00- 80
7	To remove and refit upholstery, lining, garnish etc to assist repair	\$300.00- 80
		Labour Total \$3,700.00

Grand Total \$12,752.73

total: 7695.65
h/s: 6/50
Adrian Lj
h/s 18/12/20
07 Dan