

JWG INTERNATIONAL PTE. LTD.

10, ANG MO KIO IND PARK 2A, #03-08 AMK AUTOPOINT, SINGAPORE 568047

H/P: 8299 6103 | FAX: 6909 9592

E-Mail: jwg.claims@yahoo.com

To: AIG ASIA PACIFIC INSURANCE PTE LTD

Att: Motor Claims Dept

ACCIDENT INVOLVING SKL848C [YOUR INSURED] & SMS3233X [OUR CLIENT]
ON 16/12/2020.

ESTIMATED REPAIR COSTS FOR SMS3233X

<u>QTY</u>	<u>PARTS</u>	<u>AMOUNT</u>	
1PC	FRONT DOOR LH <i>Dent</i>	1266.00	\$ 2,310.00 ✓
1PC	FRONT DOOR WINDOW MOULDING LH <i>HH</i>		\$ 210.00 ✗
1PC	FRONT DOOR CHROME MOULDING LH <i>HH</i>		\$ 241.00 ✗
1PC	FRONT DOOR BLACK STICKER LH <i>HH</i>		\$ 49.00 ✓
1PC	FRONT DOOR INNER TRIM BOARD LH <i>HH</i>		\$ 881.00 ✗
1PC	FRONT DOOR LOWER GARNISH LH <i>HH</i>	342.60	\$ 496.00 ✓
1PC	FRONT DOOR WINDOW MOTOR LH <i>HH</i>		\$ 791.00 ✗
1PC	FRONT DOOR WINDOW REGULATOR LH <i>HH</i>		\$ 599.00 ✗
1PC	FRONT DOOR LOCK LH <i>HH</i>		\$ 391.00 ✗
1PC	SIDE MIRROR ASSY LH <i>HH</i>		\$ 1,878.00 ✗
1PC	ROCKER PANEL LH <i>HH</i>		\$ 1,923.00 ✗
1PC	REAR DOOR LH <i>3A</i>	1152.60	\$ 2,481.00 ✓
1PC	REAR DOOR WINDOW MOULDING LH <i>HH</i>		\$ 221.00 ✗
1PC	REAR DOOR CHROME MOULDING LH <i>HH</i>		\$ 274.00 ✗
1PC	REAR DOOR BLACK STICKER LH <i>HH</i>		\$ 49.00 ✓
1PC	REAR DOOR INNER TRIM BOARD LH <i>HH</i>		\$ 932.00 ✗
1PC	REAR DOOR LOWER GARNISH LH <i>cut (distorted)</i>	280.40	\$ 499.00 ✓
1PC	REAR DOOR WINDOW MOTOR LH <i>HH</i>		\$ 779.00 ✗
1PC	REAR DOOR WINDOW REGULATOR LH <i>HH</i>		\$ 601.00 ✗
1PC	REAR DOOR LOCK LH <i>HH</i>		\$ 401.00 ✗
1PC	REAR FENDER ARC GARNISH <i>cut / manually broken</i>		\$ 497.00 ✓

3636.60

3272.94

PARTS SUM: \$ 16,006.00

PARTS LESS 10%: \$ 1,600.60

PARTS TOTAL: \$ 14,405.40

LABOUR & SPECIAL NETT ITEMS

*	TO SUPPLY FRONT DOOR INNER TRIM CLIPS	44	\$	50.00	X
*	TO SUPPLY REAR DOOR INNER TRIM CLIPS	44	\$	50.00	X
*	TO SUPPLY FRONT DOOR LOWER GARNISH CLIPS	44	\$	50.00	20/-
*	TO SUPPLY REAR DOOR LOWER GARNISH CLIPS	44	\$	50.00	20/-
*	TO SUPPLY ROCKER PANEL SEALANT	44	\$	50.00	X
		40.00			
*	TO REMOVE ALL INTERIOR UPHOLSTERLY ITEMS TO FACILITATE REPAIRS		\$	400.00	44
*	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS		\$	1,400.00	500/-
*	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS		\$	1,400.00	500/-
*	TO TUFF COAT DAMAGED AREAS	1200/-	\$	300.00	40/-
*	TO RNR FRONT DOOR MECHANISM TO FACILITATE REPAIRS		\$	250.00	80/-
*	TO RNR REAR DOOR MECHANISM TO FACILITATE REPAIRS		\$	250.00	80/-
*	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS		\$	200.00	44


LABOUR & S/N TOTAL: \$ 4,450.00

GRAND TOTAL ESTIMATED REPAIR COSTS (NON-INCLUSIVE OF 7% GST): \$ 18,855.40

18/12/2020 @ 1700hrs
H/A Andrew
2/sun 4 days.

Ryan

LKK Auto



Check part prices

4512.94
L/S 3600/-

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: