



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2104206

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV Date 14/06/2021
Reference CC4/FCI20014104/Ues3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SMM 5904L
Insured Veh. SHC 1130R
Claim No. D20005174MFSH
Policy No. D-20094922MFSH
Accident Date 17/12/2020
Inspection Date 21/12/2020

Description	Total
Third Party Express Settlement	500.00
Subtotal	500.00
GST (7%)	35.00
Grand Total	535.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC4/FCI20014104/Ues3q2	
			Date: 14/06/2021	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHC 1130R	Veh. Inspected	SMM 5904L
	Policy No.	D-20094922MFSH	Coverage (\$)	0.00
	Claim No.	D20005174MFSH	Excess (\$)	0.00
	Assign From	VIC	Assign Date	18/12/2020
2. Vehicle Particulars & Condition				
	Make & Model	mitsubishi attrage (A)	c.c	1193
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	MMBSTA13AKH001818	Colour	WHITE
	Odometer	38505 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	185/55 R15	YOKOHAMA	7 mm
	L/H Front Tyre	185/55 R15	YOKOHAMA	7 mm
	R/H Rear Tyre	185/55 R15	YOKOHAMA	7 mm
	L/H Rear Tyre	185/55 R15	YOKOHAMA	7 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	17/12/2020	Inspection Date	21/12/2020
	Survey held at	CYCLE & CARRIAGE.FULCO MOTOR DEALER PL NO.330 UBI ROAD 3 SINGAPORE 408650		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMM 5904L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FACE ,RR BUMPER (SN)	TO REPAIR SEE LABOUR	748.00	-
10	CLIP,BUMPER (SN)	NECESSARY	40.00	40.00
1	LH BRACKET ,RR BUMPE (SN)	NOT NECESSARY	28.00	-
1	RH BRACKET ,RR BUMPE (SN)	NOT NECESSARY	28.00	-
1	ATTRAGE BODY KIT (SN)	CRACKED	1,643.00	1,643.00
1	LH RR ,MUD GUARD (SN)	NOT NECESSARY	36.00	-
1	RH RR ,MUD GUARD (SN)	NOT NECESSARY	36.00	-
1	COVER ,RR VENTILATOR (SN)	NOT NECESSARY	40.00	-
1	DUCT ,RR VENTILATOR (SN)	NOT NECESSARY	30.00	-
1	BUZZER ,KEYLESS OPER (SN)	NOT NECESSARY	91.00	-
1	ANTENNA ,KEYLESS OPE (SN)	NOT NECESSARY	96.00	-
1	TRIM ,RR END (SN)	NOT NECESSARY	66.00	-
1	PANEL ,RR END (SN)	TO REPAIR SEE LABOUR	425.00	-
			3,307.00	1,683.00
	<u>LABOUR</u>			
	DIAGNOSTIC /SCANNING .		250.00	250.00
	TO CHECK ALL LIGHTING /WIRING SYSTEM ON REAR ACCIDENT AFFECTED AREAS.		100.00	80.00
	TO REMOVE & REINSTALL ALL CARPETS /TRIMMING TO FACILITATE REPAIR ON REAR ACCIDENT AFFECTED AREAS.	NOT NECESSARY	640.00	-
	TO APPLY SEALANT KIT ON NEW & REPAIR PANELS .	NOT NECESSARY	200.00	-
	TO REPLACE REAR BUMPER ,BRACKETS ,CLIPS ,VENTILATOR ,ETC TO CUT & WELD REAR END PANEL STRAIGHTEN ,REFORM ,ALIGN ON REAR ACCIDENT AFFECTED AREAS.INCLUSIVE OF THE REPAIR OF FACE ,RR BUMPER AND PANEL ,RR END.		3,200.00	640.00
	SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS.		1,650.00	550.00
	TO REPLACE & RESPRAY NEW BODY KIT.		600.00	600.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO APPLY ZERTONA PAINT PROTECTION .		234.39	234.39
			6,874.39	2,354.39
GRAND TOTAL			10,181.39	4,037.39
RECOMMENDED COST OF REPAIRS				4,037.39

Report Ref No. CC4/FCI20014104/Ues3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMM 5904L

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMM 5904L

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMM 5904L

RE-INSPECTION

