

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SMM5904L

at Workshop m/s

C & C Ubi 10am

of

Insured:

SAC1130R

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

\$54k.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.: Yes or No

Lum Sum:

1.31

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

1071
Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SMM5904L

Yr Regn:

5/7/19

Type: ~~M. Car~~ / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

(A)

Make:

Mit Attrage

c.c

1193

Colour

white

A/C:

Insured / Std / NI / NA

Sp. Reading

38505

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

MMBSTA13AKH 001818

Gen. Cond:

Good / Fair / Poor / Burnt

Steering:

In order / Jammed / Leaked / Burnt or

Brake:

In order / Jammed / Leaked / Burnt or

Modi:

Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/55 R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

17.2/20

mm

L/Bal.

21.7/20

mm

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

L1A 26819
video of Rolde

12/1/21

conf. met final by 4037-39 with Ren

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) ___ S + RS ___ SI

) Photos

) Others

)

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

)



CYCLE & CARRIAGE

CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD

EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857


MITSUBISHI
MOTORS

ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info	
MS First Capital Insurance Limited 36 Robinson Road #16-01 City House Singapore 068877 Contact No	Cust No/Name	KCV11657/Ms Sharon Soh Mei Wan
	Reg No/Reg Date	SMM5904L / 05/07/2019
	Date In/Mileage	17/12/2020/ 38129
	Chassis No	MMBSTA13AKH001818
	Engine No	3A92UHS9392
	Make/Model	MIT/19MY ATTRAGE 1.2 CVT
	Colour/Trim	W05 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
F0000034	Credit	17/12/2020/ 11:31	DS	303 / Renemer	58306
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
S MIPNT88088	DIAGNOSTIC/SCANNING				250.00
S MIPNT88088	TO CHECK ALL LIGHTING/WIRING SYSTEM ON REAR ACCIDENT AFFECTED AREAS				100.00
S MIPNT88088	TO REMOVE & RE-INSTALL ALL CARPETS/TRIMMING TO FACILITATE REPAIR ON REAR ACCIDENT AFFECTED AREAS				640.00
S MIPNT88088	TO APPLY SEALANT KIT ON NEW & REPAIR PANELS				200.00
S MIPNT88088	TO REPLACE REAR BUMPER,BRACKETS,CLIPS,VENTILATOR,ETC				3200.00
S MIPNT88088	TO CUT & WELD REAR END PANEL				1650.00
S MIPNT88088	STRAIGHTEN,REFORM,ALIGN ON REAR-ACCIDENT AFFECTED AREAS				600.00
S MIPNT88088	TO REPLACE & RESPRAY NEW BODY KIT (INCLUDED SEALANT KIT)				234.39
S MIPNT88088	TO APPLY ZERTONA PAINT PROTECTION (DISCOUNTED RATE 40% OFF)				
M JJ6410C750	FACE, RR BUMPER	1.00	748.00	0.00	748.00
M JJMR200300	CLIP, BUMPER	10.00	4.00	0.00	40.00
M JJ6410C433	LH BRACKET, RR BUMPER	1.00	28.00	0.00	28.00
M JJ6410C434	RH BRACKET, RR BUMPER	1.00	28.00	0.00	28.00
M JJMZ330600-W54	ATTRAGE BODY KIT	1.00	1643.00	0.00	1643.00
M JJ5370B565	LH RR,MUD GUARD	1.00	36.00	0.00	36.00
M JJ5370B566	RH RR,MUD GUARD	1.00	36.00	0.00	36.00
M JJ7835A023	DUCT,RR VENTILATOR	1.00	30.00	0.00	30.00
M JJ7835A032	COVER, RR VENTILATOR	1.00	40.00	0.00	40.00
M JJ8637A176	BUZZER, KEYLESS OPER	1.00	91.00	0.00	91.00
M JJ8637B115	ANTENNA, KEYLESS OPE	1.00	96.00	0.00	96.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE FULCO MOTOR DEALER PTE LTD

EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info	
MS First Capital Insurance Limited 36 Robinson Road #16-01 City House Singapore 068877 Contact No	Cust No/Name	KCV11657/Ms Sharon Soh Mei Wan
	Reg No/Reg Date	SMM5904L / 05/07/2019
	Date In/Mileage	17/12/2020/ 38129
	Chassis No	MMBSTA13AKH001818
	Engine No	3A92UHS9392
	Make/Model	MIT/19MY ATTRAGE 1.2 CVT
	Colour/Trim	W05 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
F0000034	Credit	17/12/2020/ 11:31	DS	303 / Renemer	58306

Description of Goods / Services		Qty	Unit Price	Disc%	Amount	
M	JJ7240A172XA	TRIM, RR END	1.00	66.00	0.00	66.00
M	JJ5281A631	PANEL,RR END	1.00	425.00	0.00	425.00
Z	NOTES					
ACCIDENT ON 17/12/2020 ALONG JUNC OF KAKI BUKIT RD 3 & KAKI BUKT AVE 2						
OWNER CLAIMING THIRD PARTY						
REQUIRED REPLACEMENT CAR						
TP#: SHC1130R		TP INS: MS FIRST CAPITAL				

Estimate

LKK Auto Consultants hence notify the Repairer of the following:

• To resurvey before/after spray painting

• To display damaged part(s) during resurvey

• Parts prices are subject to confirmation

• Third party survey is on a "Without Prejudice" basis

• No illegal modification(s) is allowed

• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Confirm & accepted by	Parts	3,307.00
	Labour	0.00
Authorized signatory and company stamp	Standard Menu	0.00
	Specialist Job	6,874.39
	Others (Lub, etc)	0.00
	Sundry	0.00
	Total (w/o GST)	10,181.39

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.