

SK Automobile Pte. Ltd.
(Co Reg. No. 201500047H)
48 Toh Guan Road Esat #01-121
Enterprise Hub S(608586)
Tel : 6266 0555 Fax : 6266 3155

TO ATTENTION ESTIMATE REPORT <u>OWNER PARTICULAR</u> NAME ADDRESS TEL. NO. OWNER INSUANCE POLICY NO. PERSON INCHARGE	: CHINA TAIPING : MOTOR CLAIMS DEPARTMENT : MSIG : B300312434QMY : DATE : 17-Dec-20 : JOB TYPE : T/P CLAIMS <u>VEHICLE DETAILS</u> VEHICLE NO. MODEL / MAKE CHASSIS NO. <u>ACCIDENT DETAIL</u> DATE TIME
---	---

QUOTATION SUMMARY PAGE 01

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR TAILGATE GOLF EMBLEM	1	\$ 96.00	\$ new 96.00
2	REAR TAILGATE TSI EMBLEM	1	\$ 64.00	\$ new 64.00
3	REAR TAILGATE BLUE MOTION TECHNOLOGY EMBLEM	1	\$ 80.00	\$ new 80.00
4	REAR TAILGATE REFLECTOR LAMP RH	1	\$ 231.00	\$ new 231.00
5	REAR TAILLAMP RH	1	\$ 253.00	\$ new 253.00
6	REAR TAILLAMP INNER PANEL RH	1	\$ 308.00	\$ Rx 308.00
7	REAR TAILLAMP LOWER BRACKET RH	1	\$ 48.00	\$ new 48.00
8	REAR FENDER RH	1	\$ 1,370.00	\$ bt 1,370.00
9	REAR FENDER INNER SHIELD RH	1	\$ 205.00	\$ th 205.00
10	REAR FENDER INNER AIR VENT RH	1	\$ 50.00	\$ X 50.00
11	REAR FENDER PETROL LID MECHANISM LOCK RH	1	\$ 88.00	\$ X 88.00
12	REAR WHEEL HOUSE PANEL RH	1	\$ 950.00	\$ Rx 950.00
13	REAR BUMPER	1	\$ 1,003.00	\$ de 1,003.00
14	REAR BUMPER REFLECTOR RH	1	\$ 62.00	\$ X 62.00
15	REAR BUMPER SIDE RETAINER RH	1	\$ 48.00	\$ de 48.00
16	REAR BUMPER TOP RETAINER	1	\$ 80.00	\$ X 80.00
17	REAR DOOR RH	1	\$ 1,727.00	\$ Rx 1,727.00
18	REAR DOOR OUTER LOCK HANDLE RH	1	\$ 137.00	\$ Rx 137.00
19	REAR DOOR OUTER LOCK HANDLE COVER RH	1	\$ 25.00	\$ X 25.00
20	REAR DOOR OUTER LOCK INNER BRACKET RH	1	\$ 80.00	\$ X 80.00

1169.11

850

QUOTATION SUMMARY

PAGE 02

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
21	REAR 16" SPORT RIM RH	1	\$ 1,034.00	\$ cut 1,034.00
22	REAR UPPER ARM RH	1	\$ 256.00	\$ nn x 256.00
23	REAR LOWER ARM RH	1	\$ 256.00	\$ nn x 256.00
24	REAR KNUCKLE ARM RH	1	\$ 658.00	\$ ht x 658.00
25	REAR KNUCKLE ARM BEARING RH	1	\$ 446.00	\$ ht x 446.00
26	REAR TRAILING ARM RH	1	\$ 257.00	\$ nn x 257.00

750

282-50

4734.61
4261.14

TOTAL PRICE \$ 9,812.00
LESS -10% \$ (981.20)
SUB TOTAL PRICE \$ 8,830.80

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR TAILLAMP CLIPS SET RH	1	\$ 40.00	\$ 10 net 40.00
2	REAR TAILLAMP INNER PANEL SEALANT RH	1	\$ 50.00	\$ x nn 50.00
3	REAR TAILLAMP LOWER BRACKET RIVET SET RH	1	\$ 40.00	\$ x nn 40.00
4	REAR FENDER SEALANT RH	1	\$ 120.00	\$ 50 net 120.00
5	REAR FENDER INNER SHIELD CLIPS SET RH	1	\$ 60.00	\$ 10 net 60.00
6	REAR WHEEL HOUSE PANEL SEALANT RH	1	\$ 50.00	\$ x nn 50.00
7	REAR BUMPER CLIPS SET	1	\$ 80.00	\$ 30 net 80.00
8	REAR BUMPER RIVET SET	1	\$ 60.00	\$ 20 net 60.00
9	REAR BUMPER SIDE RETAINER RIVET SET RH	1	\$ 40.00	\$ 10 net 40.00
10	REAR BUMPER TOP RETAINER RIVET SET	1	\$ 50.00	\$ x nn 50.00
11	REAR 16" TYRE RH	1	\$ 200 350.00	\$ x 350.00

cut

TOTAL

70% → 140
\$ 940.00

270

QUOTATION SUMMARY

PAGE 03

CLAIMS DETAIL : LABOUR CHARGES AND SPRAY PAINTING

TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION	\$ 1,500.00	900	
TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA	\$ 1,250.00	900	
TO APPLY ANTI-RUST & TUFF KOTE	\$ 105.00	30	
TO PERFORM LIGHTING & WIRING CHECK	\$ 80.00	30	
TO PERFORM DISMANTLE & REINSTALL ROOF TOP INNER LINING	\$ 280.00	60	
TO DISMANTLE & REINSTALL REAR DOOR INNER COMPONENT MECHANISM RH TO FACILITATE REPAIR WITH CHECKING	\$ 280.00	x n7	
TO PERFORM DIAGNOSTIC CHECK & RESET MEMORY FAULT CODE TO IDENTIFICATION STANDARD	\$ 350.00	150	
TO DISMANTLE & REINSTALL REAR PETROL TANK FOR FACILITATE REPAIR	\$ 250.00	100 x n7 plus photo.	
TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR WITH DISTANCE SETTING	\$ 120.00	30	
TO DISMANTLE & REPLACED REAR UNDER CARRIAGE COMPONENT RH TO PERFORM FACILITATE REPAIRS	\$ 280.00	100? plus photo.	
TO SEND VEHICLE FOR 3D COMPUTERISED TO PERFORM CHECK & ADJUSTED ALL WHEEL ALIGNMENT	\$ 100.00	80	
TO DISMANTLE & REINSTALL INTERIOR CARPET WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR	\$ 280.00	60	
TO PERFORM CONDUCT WATER LEAKAGE TEST OF ACCIDENT PORTION	\$ 80.00	x n7.	

TOTAL

\$ 4,955.00

2340

QUOTATION SUMMARY

PAGE 04

ESTIMATE REPORT

TOTAL PARTS COST	:	\$	9,770.80
TOTAL LABOUR COST	:	\$	4,955.00
TOTAL REPAIR COST	:	\$	14,725.80

4261.14

270

2340

6871.14

APPROVED DETAILS

NO. OF REPAIR DAYS

:

DAYS

45 \$5500

7 days #

REPAIR UNDER

:

PART BY PART OR LUMP SUM

DATE / TIME OF SURVEY

:

18/12/20 @ 530p-

SURVEYED BY / FROM

:

Tanfir LKK

7 days

CONTACT NUMBER

:

97495749 / 67418434

FAX NUMBER

:

Tanfir LKK

EMAIL ADDRESS

:

DATE / TIME OF RE-SURVEY

:

Resurvey after repair.

EXCESS

:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: