

SLC 4593X

TPMS19.

Honda Vezel

Dense

RU11108577

- Front Bumper ^{Behind} 762.20 ✓
- Front Bumper Clips. ⁱⁿ 30 (SN) ✓
- Front Bumper Side Holder RH ^{new} 27.10 ✓
- Front Bumper Lower Spoiler ^{cut} 351 ✓
- Headlamp RH. ^{Not new} 1827.80 X.
- Front RH Fender ^{Dented} 585.40 ✓
- Front RH Fender Inner Shield. ^{MEM} 166.50 X
- Front RH Fender Inner Shield clips. ^{new} 30 (SN) X.
- Front RH Fender Arch Garnish ^{cut} 153 ✓
- Front RH Fender Arch Garnish Clips. ^{new} 20 (SN) ✓
- Front RH Wheel Rim. ^{cut} ~~800(SN)~~ 400(SN)
- Front RH Tyre. ^{Not new} 300(SN) X.

SLC4593X.

Front RH Lower Arm.	Best	392.30	✓
Front RH Shock Absorber	NEW	389.60	+
Front RH Knuckle Arm.	NEW	390.70	+
Front RH Wheel Hub c/w Bearings.	Dgd	193.50	✓
Front RH Door	Dented	958.90	✓
Front RH Door Lock.	} NEW NEW	278.20	+
Front RH Door Weatherstripe.		195.80	+
Front RH Door Black Tape.	NEW	50(SN)	✓
Rear RH Door	Dented	966.50	✓
Rear RH Door Lock	} NEW NEW	270.20	+
Rear RH Door Weatherstripe		187.60	+
Rear RH Door Black Tape.	NEW	50(SN)	✓
Rear RH Fender Arch Garnish.	at	195	✓
Rear RH Fender Arch Garnish Clips.	NEW	20(SN)	✓
Rear RH Wheel Rim.	NEW	800(SN)	+
Rocker Panel Outer Skirting.	at	466.80	✓
Rocker Panel Outer Skirting Clips	NEW	30(SN)	✓

SLC4593X

Panel Beating,	1000 700.
Spray Painting.	1000 800.
Wiring.	50 30
To underseal	150 40
To transfer front and rear door fittings.	300 160
To perform wheel alignment	150 80
To dismantle front undercarriage.	350 150

hist: 505170

Amto%: 404136

S.N: 600

Labour: 1960

total: 660136

4/s: 5.2K: ✓

06 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: