

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SMW7843M/2012122

21st December 2020

The Manager
Motor Claim Department
AIG Asia Pacific Insurance Pte Ltd
CHARTIS Building
78 Shenton Way #07-16
Singapore 079120

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

not followed
rule
3/1/20
Take photo before pa.ing
2 days.

Date of Accident : 17th December 2020

Location : Tampines Street 11

Third Party Claim Vehicle No : SLZ 8405 J

Repair Cost For Vehicle No : SMW 7843 M Mercedes GLC 300

Estimate Supply of Parts & Labours

No.	Particulars	Qty	Price	Amounts
1	Rear bumper fascia	1	805.00	\$ 805.00 ✓
2	Rear bumper pad (centre)	1	710.00	\$ 710.00 ✓
3	Rear bumper pad (side)	1	59.00	\$ 59.00 X
4	Rear bumper diffuser	1	200.00	\$ 200.00 X
5	Rear bumper chrome L&RH	2	170.00	\$ 340.00 X
6	Rear bumper chrome (centre)	1	149.00	\$ 149.00 ?
7	Rear bumper sensor	2	136.00	\$ 272.00 ?
8	Rear bumper beam	1	160.00	\$ 160.00 ?
9	Rear fender arch garnish L&RH	2	230.00	\$ 460.00 X
				\$ 3,155.00

Labour Charges :-

	Amounts
Renew parts, knocking & welding rear end panel, remove & install all damage parts & re-align body	\$ 780.00 300
Remove & refix rear bumper sensor	\$ 100.00 50
Spray painting on damage parts	\$ 680.00 300
Diagnostic & reset	\$ 300.00 80
Check all lighting after repairs	\$ 60.00 X
Labour Charge	\$ 1,920.00
Total Amount	\$ 5,075.00

GST will be reflected in the final bills.