

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SMW7843M/2012122

21st December 2020

The Manager
Motor Claim Department
AIG Asia Pacific Insurance Pte Ltd
CHARTIS Building
78 Shenton Way #07-16
Singapore 079120

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

not Authorised

date

31/12/20

take place before party

2 days

A/P \$2519.76

Date of Accident : 17th December 2020

Location : Tampines Street 11

Third Party Claim Vehicle No : SLZ 8405 J

Repair Cost For Vehicle No : SMW 7843 M Mercedes GLC 300

Estimate Supply of Parts & Labours

No.	Particulars	Qty	Price	Amounts
1	Rear bumper fascia <i>20/22</i>	1	1,352.12	\$ 1,352.12 <i>=</i>
2	Rear bumper pad (centre) <i>30/22</i>	1	566.50	\$ 566.50 <i>=</i>
3	Rear bumper pad (side) <i>11</i>	1	59.00	\$ 59.00 <i>X</i>
4	Rear bumper diffuser <i>11</i>	1	200.00	\$ 200.00 <i>X</i>
5	Rear bumper chrome L&RH <i>11</i>	2	170.00	\$ 340.00 <i>X</i>
6	Rear bumper chrome (centre) <i>11</i>	1	149.00	\$ 149.00 <i>X</i>
7	Rear bumper sensor <i>11</i>	2	136.00	\$ 272.00 <i>X</i>
8	Rear bumper beam <i>11</i>	1	160.00	\$ 160.00 <i>X</i>
9	Rear fender arch garnish L&RH <i>11</i>	2	230.00	\$ 460.00 <i>X</i>
10	Rear bumper rivet <i>11</i>	1set	90.00	\$ 90.00 <i>70</i>
				\$ 3,648.62

Labour Charges :-

	Amounts
Renew parts, knocking & welding rear end panel, remove & install all damage parts & re-align body	\$ 780.00 <i>300</i>
Remove & refix rear bumper sensor	\$ 100.00 <i>50</i>
Spray painting on damage parts	\$ 680.00 <i>300</i>
Diagnostic & reset	\$ 300.00 <i>80</i>
Check all lighting after repairs	<i>11</i> \$ 60.00 <i>X</i>

Labour Charge

\$ 1,920.00

Total Amount

\$ 5,568.62

GST will be reflected in the final bills.

P-1988.62

102

1789.75

2619.71