



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722

Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031

Email: yeeautopteltd@gmail.com

Registration No.: 201719251W GST No: 201719251W

M/S: India International Insurance Pte Ltd

64 Cecil Street

#05-01 IOB Building

Singapore 049711

Estimate No: ES2000115

Date: 18 Dec 2020

Policy No:

Veh Reg No: SMU8067R

Make/Model: B.M.W. 218I LED HL

Chassis No: WBA12AK0607F88981

Engine No: 33545990B38A15A

Reg. Date: 28/08/2020

ATTN: Motor Claim Department

Your Ref No: -

Claim Type: Third Party

Accident Date: 16/12/2020

TP Veh Reg No: GBF2318R

Not Authorised
Permy B4paing
4 days

Estimate Repair Cost to Vehicle No :SMU8067R

Description	U/Price	Quantity	List Price SS	Amount SS
Net Price				
1 REVERSE SENSOR CENTRE - LH	395.20	1 PC	395.20	X
2 REVERSE SENSOR CENTRE - RH	395.20	1 PC	395.20	X
			790.40	790.40
Spare Parts				
3 BUZZER SENSOR	380.15	1 PC	380.15	X
4 HANDBRAKE ECU	450.15	1 PC	450.15	X
5 REAR BOOT LID	2,206.10	1 PC	2,206.10	X
6 REAR BOOT LID '218I' EMBLEM	105.10	1 PC	105.10	X
7 REAR BOOT LID LOCK	455.90	1 PC	455.90	X
8 REAR BOOT LID LOGO EMBLEM	189.75	1 PC	189.75	X
9 REAR BOOT LID REFLECTOR	789.15	1 PC	789.15	X
10 REAR BOOT LID WEATHERSTRIP	235.90	1 PC	235.90	X
11 REAR BUMPER	1,810.20	1 PC	1,810.20	X
12 REAR BUMPER BRACKET - LH	132.20	1 PC	132.20	X
13 REAR BUMPER BRACKET - RH	132.20	1 PC	132.20	X
14 REAR BUMPER INNER IMPACT GARNISH	198.20	1 PC	198.20	X
15 REAR BUMPER LOWER SPOILER	385.15	1 PC	385.15	X
16 REAR BUMPER REFLECTOR - LH	128.50	1 PC	128.50	X
17 REAR BUMPER REFLECTOR - RH	128.50	1 PC	128.50	X
18 REAR BUMPER REINFORCEMENT	740.10	1 PC	740.10	X
19 REAR BUMPER SIDE BRACKET - LH	320.00	1 PC	320.00	X
20 REAR BUMPER SIDE BRACKET - RH	320.00	1 PC	320.00	X
21 REAR BUMPER SPONGE	281.10	1 PC	281.10	X
22 REAR BUMPER TOWING COVER	85.50	1 PC	85.50	X
23 REAR END PANEL	420.15	1 PC	420.15	X
24 REAR END PANEL TOP GARNISH	380.15	1 PC	380.15	X
			10,274.15	10,274.15
Labour				
25 TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY.	1,200.00	1 JOB	1,200.00	400
26 TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.	1,200.00	1 JOB	1,200.00	600
27 TO APPLY RUST- PROOFING ON REPAIRED, REPLACED PANEL.	120.00	1 JOB	120.00	X
28 TO REMOVE/RENEW EXHAUST MUFFLER.	250.00	1 JOB	250.00	X
29 TO CHECK WIRING FUNCTIONS.	80.00	1 JOB	80.00	200
30 TO REMOVE/TRANSFER TAILGATE COMPONENTS.	80.00	1 JOB	80.00	X



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722
Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031
Email: yeeautopteltd@gmail.com
Registration No.: 201719251W GST No: 201719251W

M/S : India International Insurance Pte Ltd
64 Cecil Street
#05-01 IOB Building
Singapore 049711

ATTN: Motor Claim Department
Your Ref No: -
Claim Type: Third Party
Accident Date: 16/12/2020
TP Veh Reg No: GBF2318R

Estimate No: ES2000115
Date: 18 Dec 2020
Policy No:
Veh Reg No: SMU8067R
Make/Model: B.M.W. 218I LED HL
Chassis No: WBA12AK0607F88981
Engine No: 33545990B38A15A
Reg. Date: 28/08/2020

Estimate Repair Cost to Vehicle No :SMU8067R

Estimate Repair Cost to Vehicle No :SMU88667/K				
Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
31 COMPUTER DIAGNOSTIC RESET.	280.00	1 JOB	280.00	?
			3,210.00	3,210.00
			Total	S\$ 14,274.55
			Add GST @ 7%	999.22
			Total Amount Payable	S\$ 15,273.77

TOTAL: SINGAPORE DOLLAR FIFTEEN THOUSAND TWO HUNDRED SEVENTY THREE AND CENTS SEVENTY SEVEN ONLY

For Yee Auto Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following: AUTHORIZED SIGNATURE

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: