

ASS. REC. BY:

REF:

TH / 200741151K6

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

04

days

Res.: _____

Yes or No

Lum Sum: _____

1.8.1 %

3 Val.: _____

Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: _____

SMU 8087R

Yr Regn: _____

08, 20

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: _____

BMW 218i

c.c

1499

Colour

M. Blue

A/C: _____

Insured / Std / NI / NA

Sp. Reading

2013

T/Radio: _____

Insured / Std / NI / NA

Eng/No: _____

C/No: _____

WBA12AK0607F 88981

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size: _____

F: _____

225/45R17

R: _____

BS / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal. _____

9

mm

Rear

R/Bal. _____

9

mm

L/Bal. _____

9

mm

L/Bal. _____

9

mm

D.O.A. _____

16/12/20

D.O.I. _____

18/12/2020

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

24/12 11.15 825501- Continuum

Date/Time, File Pass to?

☐

: Prell. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair: _____

Resurvey No. of Trlp: _____

Survey Fee: _____

Transportation: _____

S + RS. \$

Fees

Others

TOTAL

Add Fee: _____

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722

Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031

Email: yeeautopte ltd@gmail.com

Registration No.: 201719251W GST No: 201719251W

M/S : India International Insurance Pte Ltd

64 Cecil Street

#05-01 IOB Building

Singapore 049711

ATTN: Motor Claim Department

Your Ref No: -

Claim Type: Third Party

Accident Date: 16/12/2020

TP Veh Reg No: GBF2318R

Estimate No: ES2000115

Date: 18 Dec 2020

Policy No:

Veh Reg No: SMU8067R

Make/Model: B.M.W. 218I LED HL

Chassis No: WBA12AK0607F88981

Engine No: 33545990B38A15A

Reg. Date: 28/08/2020

Not Assthan
Resumy B4 painting
4 days
1/12 @ 2550h

Estimate Repair Cost to Vehicle No :SMU8067R

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
Net Price				
1 REVERSE SENSOR CENTRE - LH	395.20	1 PC	<i>h</i> 395.20	X
2 REVERSE SENSOR CENTRE - RH	395.20	1 PC	<i>h</i> 395.20	X
			790.40	790.40
Spare Parts				
3 BUZZER SENSOR	380.15	1 PC	<i>h</i> 380.15	X
4 HANDBRAKE ECU	450.15	1 PC	<i>h</i> 450.15	X
5 REAR BOOT LID	2,206.10	1 PC	<i>h</i> 2,206.10	X
6 REAR BOOT LID '218I' EMBLEM	105.10	1 PC	<i>h</i> 105.10	X
7 REAR BOOT LID LOCK	455.90	1 PC	<i>h</i> 455.90	X
8 REAR BOOT LID LOGO EMBLEM	189.75	1 PC	<i>h</i> 189.75	✓
9 REAR BOOT LID REFLECTOR	789.15	1 PC	<i>h</i> 789.15	X
10 REAR BOOT LID WEATHERSTRIP	235.90	1 PC	<i>h</i> 235.90	X
11 REAR BUMPER	1,810.20	1 PC	<i>h</i> 1,810.20	✓
12 REAR BUMPER BRACKET - LH	132.20	1 PC	<i>h</i> 132.20	X
13 REAR BUMPER BRACKET - RH	132.20	1 PC	<i>h</i> 132.20	X
14 REAR BUMPER INNER IMPACT GARNISH	198.20	1 PC	<i>h</i> 198.20	✓
15 REAR BUMPER LOWER SPOILER	385.15	1 PC	<i>h</i> 385.15	✓
16 REAR BUMPER REFLECTOR - LH	128.50	1 PC	<i>h</i> 128.50	X
17 REAR BUMPER REFLECTOR - RH	128.50	1 PC	<i>h</i> 128.50	X
18 REAR BUMPER REINFORCEMENT	740.10	1 PC	<i>h</i> 740.10	X
19 REAR BUMPER SIDE BRACKET - LH	320.00	1 PC	<i>h</i> 320.00	X
20 REAR BUMPER SIDE BRACKET - RH	320.00	1 PC	<i>h</i> 320.00	X
21 REAR BUMPER SPONGE	281.10	1 PC	<i>h</i> 281.10	X
22 REAR BUMPER TOWING COVER	85.50	1 PC	<i>h</i> 85.50	X
23 REAR END PANEL	420.15	1 PC	<i>h</i> 420.15	X
24 REAR END PANEL TOP GARNISH	380.15	1 PC	<i>h</i> 380.15	X
			10,274.15	10,274.15
Labour				
25 TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY.	1,200.00	1 JOB	1,200.00	400h
26 TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.	1,200.00	1 JOB	1,200.00	600h
27 TO APPLY RUST- PROOFING ON REPAIRED, REPLACED PANEL.	120.00	1 JOB	<i>h</i> 120.00	X
28 TO REMOVE/RENEW EXHAUST MUFFLER.	250.00	1 JOB	<i>h</i> 250.00	X
29 TO CHECK WIRING FUNCTIONS.	80.00	1 JOB	<i>h</i> 80.00	20h
30 TO REMOVE/TRANSFER TAILGATE COMPONENTS.	80.00	1 JOB	<i>h</i> 80.00	X



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722

Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031

Email: yeeautopteltd@gmail.com

Registration No.: 201719251W GST No: 201719251W

M/S : India International Insurance Pte Ltd

64 Cecil Street

#05-01 IOB Building

Singapore 049711

ATTN: Motor Claim Department

Your Ref No: -

Claim Type: Third Party

Accident Date: 16/12/2020

TP Veh Reg No: GBF2318R

Estimate No: ES2000115

Date: 18 Dec 2020

Policy No:

Veh Reg No: SMU8067R

Make/Model: B.M.W. 218i LED HL

Chassis No: WBA12AK0607F88981

Engine No: 33545990B38A15A

Reg. Date: 28/08/2020

Estimate Repair Cost to Vehicle No :SMU8067R

Description	U/Price	Quantity	List Price	Amount
31 COMPUTER DIAGNOSTIC RESET.	280.00	1 JOB	SS 280.00	SS
			3,210.00	3,210.00
Total				SS 14,274.55
Add GST @ 7%				999.22
Total Amount Payable				SS 15,273.77

TOTAL: SINGAPORE DOLLAR FIFTEEN THOUSAND TWO HUNDRED SEVENTY THREE AND CENTS SEVENTY SEVEN ONLY

For Yee Auto Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

AUTHORISED SIGNATURE