



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2104749

INV Date 06/07/2021

Reference CC4/LPC20014145/R1ea3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SMD 7699M
Insured Veh. GBF 3944B
Claim No. 20/20/20/VC00/0243995
Policy No. Z/20/VC00/108648
Accident Date 09/12/2020
Inspection Date 23/12/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CC4/LPC20014145/R1ea3q2 Date: 06/07/2021 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBF 3944B	Veh. Inspected	SMD 7699M	
Policy No.	Z/20/VC00/108648	Coverage (\$)	0.00	
Claim No.	20/20/20/VC00/0243995	Excess (\$)	0.00	
Assign From	GERALD POH	Assign Date	17/12/2020	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI ELANTRA AD 1.6 GLS	c.c	1591	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	KMHD841CMJU730388	Colour	GREY	
Odometer	28379 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	NEXEN	6 mm	
L/H Front Tyre	195/65 R15	NEXEN	6 mm	
R/H Rear Tyre	195/65 R15	NEXEN	6 mm	
L/H Rear Tyre	195/65 R15	NEXEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	09/12/2020	Inspection Date	23/12/2020	
Survey held at	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD BLK 3, PIONEER ROAD NORTH, #01-18 SINGAPORE 628457.			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMD 7699M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRT BUMPER	TO REPAIR SEE LABOUR	474.00	-
6	FRT BUMPER CLIPS @\$4.80	NOT NECESSARY	28.80	-
1	FRT BUMPER RETAINER (RH)	NOT NECESSARY	20.80	-
1	FRT BUMPER SIDE RETAINER (RH)	NOT NECESSARY	31.00	-
1	FRT FOGLAMP COVER (RH)	NOT NECESSARY	115.00	-
	LESS 20% DISCOUNT		-133.92	-
			535.68	-
	<u>LABOUR</u>			
	TO KNOCK ,WELD ,REMOVE & FIX ABOVE PARTS .INCLUSIVE OF THE REPAIR OF FRT BUMPER .		240.00	200.00
	TO PUTTY & RESPRAY PAINTING ON AFFECTED AREA.		200.00	200.00
			440.00	400.00
GRAND TOTAL			975.68	400.00
RECOMMENDED COST OF REPAIRS				400.00

Report Ref No. CC4/LPC20014145/R1ea3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMD 7699M

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMD 7699M

RE-INSPECTION

