

Not Authorized
 Remy Bepain
 AAD2011-148

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9942G

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :
 Date of Registration:

30 NOV 2020

SHD9942G

JTDKB3FUX03092621

TOYOTA

PRIUS GEN 4

27/11/2020

AIG

06/11/2020

PART		LIST	
1	COVER, REAR BUMPER	\$ R 485.60	X
1	REINFORCEMENT SUB-ASSY, REAR BUMPER	\$ 332.70	?
1	GUARD, REAR BUMPER, CENTER	\$ ndl 374.50	✓
1	RETAINER, REAR BUMPER SIDE, LH	\$ 132.60	X
1	RETAINER, REAR BUMPER SIDE, RH	\$ 132.60	✓
1	PANEL SUB-ASSY, BACK DOOR	\$ R 1,147.80	} X
1	HINGE ASSY, BACK DOOR, LH	\$ R 61.00	
1	HINGE ASSY, BACK DOOR, RH	\$ R 61.00	
1	STAY ASSY, BACK DOOR, LH	\$ 242.50	
1	STAY ASSY, BACK DOOR, RH	\$ 242.50	
1	GLASS, BACK WINDOW FIX	\$ 761.40	
1	GARNISH SUB-ASSY, BACK DOOR, OUTSIDE	\$ 913.60	
1	ORNAMENT SUB-ASSY, BACK DOOR	\$ 47.90	
1	PLATE, LUGGAGE COMPARTMENT DOOR NAME, NO.2	\$ 54.60	
1	PLATE, BACK DOOR NAME, NO.1	\$ 54.60	
1	LENS & BODY, REAR COMBINATION LAMP, NO.2 RH	\$ 261.00	
1	LENS & BODY, REAR COMBINATION LAMP, RH	\$ 339.60	
1	LENS & BODY, REAR COMBINATION LAMP, NO.2 LH	\$ 261.00	
1	LENS & BODY, REAR COMBINATION LAMP, LH	\$ 339.60	
1	COVER, FLOOR UNDER, NO.1 (LH)	\$ 175.10	
1	COVER, FLOOR UNDER, NO.2 (RH)	\$ 241.90	
1	COVER, REAR FLOOR (CTR)	\$ 229.90	
TOTAL		\$ 6,246.10	
25%		\$ 1,561.53	
		\$ 4,684.58	

AAD2011-148

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9942G

Special Nett

1SET PARKING AID	\$	Sn	700.00	}	X
1SET REAR BUMPER CLIP	\$	Nn	85.00		
1 WHEELHOUSE LINER CLIP	\$	Nn	70.00		
1 BUMPER CENTRE GUARD CLIP	\$	Nn	80.00		
1 REAR TAILGATE STICKER 'TRANS-CAB'	\$	Nn	80.00		
1 REAR TAILGATE STICKER '6555-3333'	\$	Nn	80.00		
1 REAR BUMPER PROTECTOR	\$	Sn	180.00		
1 REAR BUMPER RETAINER CLIP	\$	Nn	75.00		
1SET TAILLAMP CLIP	\$	Nn	50.00		
2 WINDSCREEN SEALANT	\$	Nn	150.00		
1 WINDSCREEN MOULDING	\$	Nn	200.00		
1 WINDSCREEN INNER SPONGE SEAL	\$	Nn	130.00		
TOTAL	\$		1,400.00		

TOTAL PARTS	\$	6,084.58
--------------------	-----------	-----------------

LABOUR

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	240.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	1,600.00	20%
To transfer of rear end panel fittings, attachment to facilitate bodywork repair.	\$	380.00	X
Putty And Spray Painting Of The Affected Portion.	\$	1,600.00	220%

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9942G**AAD2011-148**To Remove And Refit Rear Big & Small W/Screen Glass To
Facilitate Bodywork Repair.\$ *nn* 300.00 X

To reinstall rear bumper parking sensor.

\$ *nn* 170.00 X

To Check Electrical Lighting Concerned.

\$ *nn* 170.00 X**TOTAL \$ 4,840.00****Over All Total \$ 10,924.58****(PART-BY-PART) Repair Days***10 Days**1 day***For Official Use**Prepared By : _____
(Accident Dept)Verify By : _____
(Accident Workshop)Checked By : _____
(Finance Dept)LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: