

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III20014150/GBA3Q2
Date: 15/09/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant Vehicle No :	FBR6251J	Insured Vehicle No :	SH6285M
Date of Loss:	06/12/2020	Nature of Claim:	TP
		Claim No:	MCT20120112

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBR6251J	Engine No:	XS1P58QMK18010986
Make & Model:	SYM JET 14 200I, 169cc ABS	Chassis No:	LXMCA501KXA20725
Reg. Date:	03/09/2020 (Man. Year: 2019)	Odometer:	0 km
Colour:	White		
Engine Capacity:	169 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	100/90-14	Rear Tyre Size:	110/80-14
Front Left Side:	CST 8 mm	Rear Left Side:	CST 8 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,247.20	1,994.48	252.72	11.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	250.00	200.00	50.00	20.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,497.20	2,194.48	302.72	12.12
+ GST 7.00/7.00% (S\$)	174.80	153.61	21.19	12.12

Nett Amount (S\$)	2,672.00	2,348.09	323.91	12.12
+ Loss of Use (2.0 x S\$30.00/day) (S\$)		60.00		
Nett Liability (S\$)		2,408.09		
Global Sum Settlement (S\$)		2,400.00		

INSPECTION

Date of Assignment: 14/12/2020

Date Inspected: 16/12/2020

Estimated Period of Repair: 2.0 days

Inspected At:

Pan Euro Bikes Pte Ltd (HQ)
 21 Moonstone Lane #01-01 Poh Leng Building
 Singapore 328462

Adjuster: XING GUO QIANG**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 06 Jul 2021)	
Parts:	N/A	SYM JET 14 200l 169cc ABS (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBR6251J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RH MIRROR	Cut	29.00 F	*29.00 FL
2	1		*RH BAR END MATT BLACK	Cut	22.00 F	*22.00 FL
3	1		*RH BRAKE LEVER	Cut	15.00 F	*15.00 FL
4	1		*METER DASH MATT	Cut	42.00 F	*42.00 FL
5	1		*REAR SHIELD MATT	Cracked	95.00 F	*95.00 FL
6	1		*FRONT COWLING ,RH WHITE	Distorted	238.00 F	*238.00 FL
7	1		*RH FRONT SIGNAL	Cracked	35.00 F	*35.00 FL
8	1		*HEADLAMP ASSY	Scratched	260.00 F	*260.00 FL
9	1		*FRONT LOWER PANEL ,MATT BLACK	Distorted	46.00 F	*46.00 FL
10	1		*FRONT MUDGUARD ,BLACK	Cracked	68.00 F	*68.00 FL
11	1		*RH FRONT FORK ASSY	Cut	180.00 F	*180.00 FL
12	1		*RUBBER BUNG ,FRONT WHEEL AXLE ,RH	Cut	1.20 F	*1.20 FL
13	1		*RH FLOORBOARD LOWER PANEL TEXTURED	Missing	18.00 F	*18.00 FL
14	1		*RB FLOORBOARD LOWER PANEL MATT GREY	Missing	36.00 F	*36.00 FL
15	1		*FLOORBOARD BRACKET ,RH	Bent	9.00 F	*9.00 FL
16	1		*BOTTOM BELLYPAN MATT	Cut	38.00 F	*38.00 FL
17	1		*FLOORBOARD MATT	Cracked	79.00 F	*79.00 FL
18	1		*EXHAUST GUARD MATT PLASTIC	Cut	49.00 F	*49.00 FL
19	1		*EXHAUST MUFFLER	Bent	667.00 F	*667.00 FL
20	1		*SET DECAL 200 FRONT COWLING	Necessary	15.00 FS	*15.00 FS
21	1		*SET EMBLEM JET 14 RH REAR FAIRING	Missing	25.00 FS	*25.00 FS
22	1		*SET REAR TOP BOX ,GIVI	Cut	280.00 FS	*220.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	2,247.20	2,187.20
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	192.72
Total Parts (\$\$)	2,247.20	1,994.48

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR CHARGE	New	250.00	200.00
Gross Labour Cost (S\$)			250.00	200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >