



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2101502

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 10/03/2021
Reference CC6/CTI20014153/Ara3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SGY 2939P
Insured Veh. GBF 7516C
Claim No. SNM20D204835
Policy No. DMCVSNA00029102000
Accident Date 05/12/2020
Inspection Date 17/12/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Ref: CC6/CTI20014153/Ara3q2 Date: 10/03/2021 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBF 7516C	Veh. Inspected	SGY 2939P
Policy No.	DMCVSNA00029102000	Coverage (\$)	0.00
Claim No.	SNM20D204835	Excess (\$)	0.00
Assign From		Assign Date	17/12/2020
2. Vehicle Particulars & Condition			
Make & Model	SUBARU XV	c.c	1600
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JF1GT3KC5JG020440	Colour	GREY
Odometer	110874 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/60 R17	YOKOHAMA	6 mm
L/H Front Tyre	225/60 R17	YOKOHAMA	6 mm
R/H Rear Tyre	225/60 R17	YOKOHAMA	6 mm
L/H Rear Tyre	225/60 R17	YOKOHAMA	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	05/12/2020	Inspection Date	17/12/2020
Survey held at	POLYMATH GARAGE PTE LTD 1 KAKI BUKIT AVENUE 6 #02-02 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGY 2939P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	TORN	446.40	446.40
1	FRONT BUMPER SIDE HOLDER RH	DAMAGED	36.00	36.00
1	FRONT RH FENDER	DENTED	325.40	325.40
1	FRONT RH FENDER PROTECTOR	DEFORMED	125.10	125.10
1	FRONT RH FENDER INNER SHIELD	TORN	108.40	108.40
1	HEADLAMP RH	CRACKED	2,520.00	2,520.00
1	HEADLAMP LOWER BRACKET RH	NOT NECESSARY	48.50	-
1	BONNET	TO REPAIR SEE LABOUR	1,072.80	-
1	FRONT RH LOWER ARM	NOT NECESSARY	385.10	-
1	FRONT RH SHOCK ABSORBER	NOT NECESSARY	521.50	-
1	FRONT RH KNUCKLE ARM	NOT NECESSARY	652.40	-
1	FRONT RH WHEEL HUB C/W BEARING	NOT NECESSARY	184.90	-
	LESS 20% DISCOUNT		-1,285.30	-712.26
			5,141.20	2,849.04
<u>SPECIAL NETT ITEMS</u>				
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	30.00	30.00
1	SET FRONT RH FENDER PROTECTOR CLIPS (SN)	NECESSARY	20.00	20.00
1	SET FRONT RH FENDER INNER SHIELD CLIPS (SN)	NECESSARY	30.00	30.00
1	FRONT RH WHEEL RIM (SN)	CUT	850.00	500.00
			930.00	580.00
<u>LABOUR</u>				
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF BONNET		800.00	500.00
	SPRAY PAINTING .		900.00	400.00
	WIRING .		50.00	30.00
	TO PERFORM WHEEL ALIGNMENT.		150.00	80.00
	TO REMOVE FRONT UNDERCARRIAGE.	NOT NECESSARY	350.00	-
			2,250.00	1,010.00
GRAND TOTAL			8,321.20	4,439.04



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,500.00
---	--	--	-----------------

Report Ref No. CC6/CTI20014153/Ara3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SGY 2939P

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SGY 2939P

RE-INSPECTION






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

