

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20014163/GQD3E2

Date: 28/12/2020

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993937		
Claimant Vehicle No :	SGH5155D	Insured Vehicle No :	GBE7554Y		
Date of Loss:	17/12/2020	Nature of Claim:	TP	Claim No:	2150251320SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGH5155D	Engine No:	HIDDEN
Make & Model:	MERCEDES-BENZ GLA200, 1.6 (A)	Chassis No:	WDC1569432J043152
Reg. Date:	06/02/2015 (Man. Year: 2015)	Odometer:	100406 km
Colour:	Grey		
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R19	Rear Tyre Size:	225/45 R19
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	18/12/2020	Benefit Auto Care Pte Ltd (HQ)
Date Inspected:	21/12/2020 Inspected At:	11 KAKI BUKIT ROAD 1 #01-02 EUNOS
		TECHNOLINK
		Singapore 415939
Estimated Period of Repair:	2.0 days	

Adjuster: XING GUO QIANG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE	Cracked	0.00 F	*- F
2	1		*FRT BUMPER	Repair	0.00 F	*- F
3	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
4	1		*FRT BUMPER EMBLEM	Necessary	0.00 F	*- F
5	1		*FRT GRILLE	Cracked	0.00 F	*- F
6	1		*FRT GRILLE EMBLEM	Broken	0.00 F	*- F
7	1		*FRT GRILLE CHROME MOULDING	Necessary	0.00 F	*- F
Total Parts (S\$)					0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >