

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AUTO & GENERAL INSURANCE (S) PTE LTD
190 CLEMENCEAU AVE #03-01
SINGAPORE SHOPPING CENTRE
SINGAPORE 239924

TEL: 6221 2199 FAX: 6725 0853
ATTN: Motor Claim Department

Estimate No: **EST2000299**
Date: 18 Dec 2020

Veh Reg No: **SMV7170B**
Make/Model: VOLKSWAGEN GOLF
1.4TSI AT 5G13HZ HID
SR
Chasis No: WVVZZZAUZGW164420
Reg. Date: 23/06/2016
Your Ref No: SLH6587A

Claim Type: Third Party
Accident Date: 17/12/2020
TP Veh Reg No: SLH6587A

Estimate Repair Cost to Vehicle No :SMV7170B

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
	List Price		
1	1 PC FRT DOOR LH	1,999.60	
2	1 PC FRT DOOR OUTER MOULDING LH	200.97	
3	1 PC FRT DOOR GLASS CHANNEL LH	233.60	
		2,434.17	
	Less 10%	243.42	2,190.75
	Labour		
4	1 TO REMOVE AND REFIT DOOR TRIM	80.00	
5	1 TO SPRAY UNDERSEAL	80.00	
6	1 TO REMOVE AND REFIT DOOR GLASS	100.00	
7	1 TO SPRAY PAINTING	600.00	
8	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	500.00	
		1,360.00	1,360.00
	Total		S\$ 3,550.75
	Add GST @ 7%		248.55
	Total Amount Payable		<u>S\$ 3,799.30</u>

TOTAL: SINGAPORE DOLLAR THREE THOUSAND SEVEN HUNDRED NINETY NINE AND CENTS THIRTY ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd

AUTHORISED SIGNATURE