

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16

AIG BUILDING, SINGAPORE 079120

TEL: 64193000 FAX: 68357416

ATTN: Motor Claim Department

Claim Type: Third Party

Accident Date: 16/12/2020

TP Veh Reg No: GBJ2403G

Estimate No: EST2000295

Date: 17 Dec 2020

Veh Reg No: SKD2586L

Make/Model: TOYOTA VIOS E M

Chasis No: MR053HY9305281250

Reg. Date: 14/11/2011

Your Ref No: GBJ2403G

Estimate Repair Cost to Vehicle No :SKD2586L

Quantity	Description	List Price	Amount
		SS	SS
	List Price		
1	1 PC BOOT LID <i>Disbld</i>	784.30	✓
2	1 PC BOOT LID LOGO <i>new</i>	50.20	✓
3	1 PC BOOT LID "VIOS" EMBLEM <i>new</i>	43.60	✓
4	1 PC BOOT LID "E" EMBLEM <i>new</i>	38.60	✓
5	2 PCS BOOTLID HINGE <i>new</i>	197.60	✗
6	1 PC BOOT LID GARNISH <i>cut</i>	168.90	✓
7	2 PCS REAR NUMBER PLATE LAMP <i>new</i>	137.20	+
8	1 PC BOOTLID KEY LOCK <i>new</i>	128.90	+
9	1 PC BOOT LID INNER LOCK <i>new</i>	298.80	✓
10	1 PC BOOT LID INNER LOCK STRIKER <i>new</i>	28.60	+
11	1 PC BOOTLID RUBBER <i>cut</i>	166.40	✓
12	1 PC REAR FENDER TRIM RH <i>new</i>	355.90	+
13	1 PC REAR FENDER MUDFLAP RH <i>new</i>	69.30	+
14	1 PC REAR FENDER TRIM LH <i>new</i>	355.90	+
15	1 PC TAIL LAMP - RH <i>cut</i>	357.90	✓
16	1 PC TAIL LAMP PANEL RH <i>Disbld</i>	162.40	✓
17	1 PC TAIL LAMP LH <i>cut</i>	357.90	✓
18	1 PC TAIL LAMP PANEL LH <i>new</i>	162.40	+
19	1 PC REAR PANEL <i>Disbld</i>	680.10	✓
20	1 PC REAR PANEL TRIM <i>cut</i>	242.10	✓
21	1 PC SPARE TYRE COVER <i>cut</i>	206.90	✓
22	1 PC REAR SPARE TYRE PANEL RH SPONGE <i>Disbld</i>	245.20	✓
23	1 PC SPARE TYRE PANEL LH SPONGE <i>Disbld</i>	245.20	✓
24	1 PC SPARE TYRE PANEL INNER SPONGE <i>new</i>	246.30	✗
25	1 PC REAR BUMPER <i>Disbld</i>	482.30	✓
26	2 PCS REAR BUMPER BRACKET <i>RH Best</i>	152.00	76
27	2 PCS REAR BUMPER SIDE RETAINER <i>new</i> Nec	193.40	✓
28	2 PCS REAR BUMPER RETAINER (SMALL) <i>new</i>	147.20	+
29	1 PC REAR BUMPER REFLECTOR - RH <i>cut</i>	99.80	✓
30	1 PC EXHAUST PIPE <i>new</i>	683.40	+

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 16/12/2020
TP Veh Reg No: GBJ2403G

Estimate No: EST2000295
Date: 17 Dec 2020
Veh Reg No: SKD2586L
Make/Model: TOYOTA VIOS E M
Chasis No: MR053HY9305281250
Reg. Date: 14/11/2011
Your Ref No: GBJ2403G

Estimate Repair Cost to Vehicle No :SKD2586L

Quantity	Description	List Price	Amount
		SS	SS
31	2 PCS EXHAUST PIPE MOUNTING <i>4800</i>	38.40	X
	<i>3675</i>	7,527.10	
	Less 25%	1,881.78	5,645.39
	Special Net		
32	1 PC BOOT LID NUMBER '285' STICKER <i>4800</i>	35.00	✓
33	1 PC REAR NUMBER PLATE <i>Best</i>	50.00	30
34	1 SET REAR FENDER TRIM CLIPS RH <i>4800</i>	60.00	+
35	1 SET REAR FENDER MUDFLAP CLIPS RH <i>4800</i>	30.00	+
36	1 PC REAR FENDER STICKER RH <i>4800</i>	290.00	✓
37	1 SET REAR FENDER TRIM CLIPS LH <i>4800</i>	60.00	+
38	1 SET REAR PANEL TRIM CLIPS <i>4800</i>	40.00	20
39	2 PCS "L" PLATE BRACKET <i>Best 4800</i>	70.00	50
40	1 PC "L" PLATE <i>Best</i>	80.00	50
41	1 SET REAR BUMPER STICKER <i>4800</i>	280.00	✓
42	1 SET REAR BUMPER CLIPS <i>4800</i>	50.00	30
		1,045.00	1,045.00
	Labour		
43	1 TO CHECK WIRING	50.00	30
44	1 TO REMOVE AND REFIX REAR EXHAUST PIPE	150.00	X
45	1 TO REPLACE STICKERS	80.00	X
46	1 TO REMOVE AND REFIT REAR INNER TRIM	100.00	60
47	1 TO SPRAY UNDERSEAL	100.00	60
48	1 (REAR) TO SPRAY PAINTING	1,500.00	800
49	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,500.00	1000
		3,480.00	3,480.00

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 16/12/2020
TP Veh Reg No: GBJ2403G

Estimate No: EST2000295
Date: 17 Dec 2020
Veh Reg No: SKD2586L
Make/Model: TOYOTA VIOS E M
Chasis No: MR053HY9305281250
Reg. Date: 14/11/2011
Your Ref No: GBJ2403G

Estimate Repair Cost to Vehicle No :SKD2586L

Quantity	Description	List Price	Amount
		S\$	S\$
	Total		S\$ 10,170.39
	Add GST @ 7%		711.93
	Total Amount Payable		S\$ 10,882.32

TOTAL: SINGAPORE DOLLAR TEN THOUSAND EIGHT HUNDRED EIGHTY TWO AND CENTS THIRTY TWO ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd



AUTHORISED SIGNATURE

Adrian Lj
L/s 18/12/20
0724p

total: 6410

L/s : SK (Nett Value)

SK

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: