

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGX 8886Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DEFORMED	1,255.60	1,155.36
1	REAR BUMPER SIDE BRACKET RH	DAMAGED	76.00	48.15
1	REAR BUMPER REFLECTOR RH	SERVICEABLE	85.00	-
1	TAIL LAMP RH	SERVICEABLE	385.50	-
1	REAR FENDER RH	TO REPAIR SEE LABOUR	918.00	-
2	REAR BUMPER REVERSE SENSOR @\$215.00	SERVICEABLE	430.00	-
1	REAR SHOCK ABSORBER RH	SERVICEABLE	312.50	-
1	REAR WHEEL BEARING RH	SERVICEABLE	210.30	-
	LESS 10% DISCOUNT		-367.29	-120.35
			3,305.61	1,083.16
	SPECIAL NETT ITEMS			
1	REAR TYRE RIM RH (SN)	TO REPAIR SEE LABOUR	525.50	-
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	50.00	30.00
			575.50	30.00
	<u>LABOUR</u>			
	TO DISMANTLE, REPLACE, CUT, WELD, KNOCK OUT DENTS TO STRAIGHTEN ACCIDENT PARTS AS-MENTIONED ON THE 'PARTS REPAIR' COLUMN INCLUSIVE OF REPLACEMENT PARTS. INCLUSIVE OF THE REPAIR OF REAR FENDER RH AND REAR TYRE RIM RH.		720.00	400.00
	PUTTY & SPRAY PAINTING TO ADJACENT PANELS. JOB ALLOWANCE. PAINT / MATERIAL.		500.00	500.00
	APPLY RUST PROOFING ON THE ADJACENT PANELS.	NOT NECESSARY	30.00	-
	REMOVE AND REFIX REAR BUMPER REVERSE SENSOR & CONDUCT DISTANCE SAFETY SETTING.		76.50	40.00
	WIRING / BULB CHECKING (INCLUSIVE OF RE-FOCUS / RE-ADJUST ON ANGLE OF LIGHT INTENSITY).		22.50	22.50
	REMOVE AND REFIX REAR UNDERCARRIAGE WORKS RH.	NOT NECESSARY	90.00	-
			1,439.00	962.50
	GRAND TOTAL		5,320.11	2,075.66

Report Ref No. CS3/ASM20008152/Gqf3e2-1



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS	1,650.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CS3/ASM20008152/Gqf3e2-1



M.MATAI, AMSAE-A
Automotive Assessor

X.S.

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.