Note: This document has not been finalised. LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25

Paya Ubi Industrial Park Singapore 408933

Attn: Pauline Tham 02 Mar 2021 Date:

Preliminary Advice

Insured Vehicle No : YN9355Y

TP Vehicle No : SJP2385Z Accident Date : 18/12/2020 Make : TOYOTA CAMRY Assignment Date : 21/12/2020

Date of Inspection : 21/12/2020 Est. Duration of Repair : 18

: JWG INTERNATIONAL PTE LTD (HQ) Inspection At

BLK 10, ANG MO KIO IND PARK 2A,, #03-08 AMK AUTOPOINT

SINGAPORE 568047

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	39,945.80
Revised Amount	:S\$	24,050.76
Check Items (Estimated)	:S\$	0.00
Total	:S\$	24,050.76
Lump Sum Repair	:S\$	19.200.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
)	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
)	Other comments :