

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST: 201001158E RCB NO: 201001158E

Estimate No: ES2091030/AMK
Date: 21 Dec 2020
Policy No: 5085048929-04 DC
Veh Reg No: SKW4853C
Make/Model: MAZDA 3
Chassis No: JM6BM42A8G0322466
Engine No: P520326974
Reg. Date: 30/10/2015

Estimate Repair Cost to Vehicle No :SKW4853C				
Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
1 FRONT LH DOOR				
2 FRONT LH DOOR FRAME STICKER	1,060.00	1 PC	1,060.00	
3 LH ROCKER PANEL	73.00	1 SET	73.00	
	960.00	1 PC	960.00	
			1133	2,092.00
		Less 20%	418.60	1,673.40
			226-60	
Labour				
4 REMOVE & REFIX FRT LH DOOR & ATTACHMENTS; TO CUT, WELD & RENEW LH ROCKER PANEL; KNOCKING & REPAIR LH CENTRE PILLAR & REALIGN THE SAME	600	1 LA	600.00	400
5 PUTTY & RESPRAY FRT LH DOOR, FRT LH FENDER, LH ROCKER PANEL, LH CENTRE PILLAR & ALL AFFECTED AREAS	800.00	1 LA	800.00	600
6 REMOVE & REFIX FRT LH DOOR WINDOW GLASS & RESET CENTRAL LOCKING	60.00	1 LA	60.00	✓
7 REMOVE & REFIX FRT SEAT, CARPET & GARNISH TO FACILITATE REPAIR	100.00	1 LA	100.00	80
8 RUSTPROOFING	60.00	1 LA	60.00	30
			1,620.00	1,620.00
			Total	S\$ 3,294.40
			Add GST @ 7%	230.61
			Total Amount Payable	S\$ 3,525.01

PLS CHECK & CONFIRM

AUTHORIZED SIGNATURE

Date: _____
Signature: _____

Acknowledged by Repairer _____

• Items prices are subject to confirmation during resurvey
• Third party survey is on a "Without Prejudice" basis
• No illegal modifications allowed
• Supplementary item(s) must be resurveyed and approved
• Payment for final approval from Insurance Company

Please notify us at 05916501